

REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(EP 1130-2-520)

PAGE 1 OF 1

DATE
 18 August 2008

TO:
 Navigation Interests

FROM:
 U.S. Army Engineer District, Baltimore
 P.O. Box 1715 Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE
 Warwick River Dorchester County, Maryland

MINIMUM DEPTHS IN
 CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Warwick River Station 0+000 to 8+200	1/Sep/2005	100	2	10	4	4	4

REMARKS *(Continue on reverse)*

All depths refer to MLLW for the 1960-1978 tidal epoch. This information represents the results of surveys made on the dates indicated and can only be as indicating the general results at that time. Length of channel is reported to the nearest foot. The actual length of channel 1.55 miles. Depths are reported to nearest foot.

LQ=E1611470.74, N345643.27 (3.6')

MH=E1611450.56, N345619.07 (4.4')

RQ=E1611132.09, N345562.58 (4.4')