

REPORT OF CHANNEL CONDITIONS
(FOR CHANNELS 400 FEET WIDE OR GREATER)
 (EP 1130-2-520)

PAGE 1 OF PAGES 1

DATE
6 August 2008

TO: Navigation Interests

FROM: U.S. Army Engineer District, Baltimore
 P.O. Box 1715
 Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE

Baltimore Harbor Baltimore, Maryland

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
Anchorage #3	19 Jun 2008	4500		35	30	41	41	41

REMARKS (Continue on reverse)

All depths refer to MLLW for the 1983-2001 tidal epoch. This information represents the results of surveys made on the dates indicated and can only be as indicating the general conditions at that time.

LQ=E1438690.10, N576717.87 (30.3') LIQ=E1439640.29, N575953.32 (40.5') RIQ=E1440901.81, N574664.12 (40.6') RQ=E1441441.98, N574323.17 (40.8')