

REPORT OF CHANNEL CONDITIONS
(FOR CHANNELS 400 FEET WIDE OR GREATER)
 (EP 1130-2-520)

PAGE 1 OF PAGES 1

DATE
25 July 2008

TO: Navigation Interests

FROM: U.S. Army Engineer District, Baltimore
 P.O. Box 1715
 Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE

Baltimore Harbor Baltimore, Maryland

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
East Channel Station 111+100 to 118+150	24 Jan 2008	600	1	49	40	45	44	42

REMARKS (Continue on reverse)

All depths refer to MLLW for the 1983-2001 tidal epoch. This information represents the results of surveys made on the dates indicated and can only be as representing the conditions at that time. Actual depth is 1.33 miles.
 LQ=E1433623.32, N579433.29 (40.3') LIQ=E1432726.85, N580861.01 (44.7') RIQ=E1434209375, N579404.33 (44.2')
 RQ=E1434333.78, N579505.78 (42.1')