

**REPORT OF CHANNEL CONDITIONS**  
**(FOR CHANNELS 400 FEET WIDE OR GREATER)**  
 (EP 1130-2-520)

PAGE 1 OF PAGES 1

DATE  
24 July 2008

TO: Navigation Interests

FROM: U.S. Army Engineer Distric, Baltimre  
 P.O. Box 1715  
 Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE

Baltimore Harbor Baltimore, Maryland

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF  
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
Feryy Bar Channel Station 0+000 to 7+900	15 Feb 2008	600	2	42	35	34	36	35

REMARKS (Continue on reverse)

All depths refer to MLLW for the 1983-2001 tidal epoch. This information represents the results of surveys made on the dates indicated and can only be as indicating the general conditions at that time. Actual channel length is 1.5 miles.  
 LQ=E1429554.96, N578621.92 (34.5') LIQ=E1428595.12, N578802.06 (33.6') RIQ=E1426595.12, N578982.06 (36.0')  
 RQ=E1431155.19, N579221.77 (35.3')