

REPORT OF CHANNEL CONDITIONS
(FOR CHANNELS 400 FEET WIDE OR GREATER)
 (EP 1130-2-520)

DATE
 22 Sep 2015

TO: Navigation Interests

FROM: U.S. Army Engineer District, Baltimore
 P.O. Box 1715
 Baltimore, Maryland 21201-1715

RIVER/HARBOR NAME AND STATE

Baltimore Harbor Baltimore, Maryland

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
Anchorage #3 Additional survey dates: 25 August 2015	26 Aug 2015	4500		35	30	31	28	28

REMARKS (Continue on reverse)

This information represents the results of surveys made on the dates indicated and can only be as representing the general conditions at that time. Depths are reported to the nearest foot. LOQ=E1437727.48,N576141.37 (30.6') LIQ=E1437797.38,N576211.35 (30.7') RIQ=E1438287.46,N576631.36 (27.7') ROQ=E1438567.41,N576841.38 (27.7')