

**REPORT OF CHANNEL CONDITIONS**  
**(FOR CHANNELS 400 FEET WIDE OR GREATER)**  
 (EP 1130-2-520)

PAGE 1 OF 1 PAGES

DATE  
 15 Apr 2016

TO: Navigation Interests

FROM: U.S. Army Engineer District, Baltimore  
 P.O. Box 1715  
 Baltimore, Maryland 21201-1715

RIVER/HARBOR NAME AND STATE

Baltimore Harbor Baltimore, Maryland

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF  
 CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
Anchorage #4 Additional survey dates: 4 & 6 April 2016	7 Apr 2016	1700		35	36	35	32	30

REMARKS (Continue on reverse)

This information represents the results of surveys made on the dates indicated and can only be as representing the general conditions at that time. Depths are reported to the nearest foot. LOQ=E1441801.92,N571334.50 (35.6') LIQ=E1441847.98,N571633.89 (34.6') RIQ=E1442094.45,N572364.24 (32.4') ROQ=E1442437.95,N572695.35 (30.3')