

**REPORT OF CHANNEL CONDITIONS**  
**(FOR CHANNELS 400 FEET WIDE OR GREATER)**

(EP 1130-2-520)

PAGE 1 OF 1 PAGES

DATE  
23 Sep 2014

TO: Navigation Interest

FROM: U.S. Army Engineer District, Baltimore  
P.O. Box 1715  
Baltimore, Maryland 21201-1715

RIVER/HARBOR NAME AND STATE

Baltimore Harbor Baltimore, Maryland

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF  
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
Seagirt Marine Terminal Connecting Channel Station 0+000 to 2+789 Additional survey dates of: 6 August and 2 & 17 September 2014	18 Sep 2014	400	1	42	46	47	49	49

REMARKS (Continue on reverse)

This information represents the results of surveys made on the dates indicated and can only be as representing the general conditions at that time. All depths refer to MLLW for the '83-'01 tidal epoch. Length of channel reported to the nearest mile (actual length is 0.53 miles). All depths reported to the nearest foot. LOQ=E1441506.82,N576723.36 (45.6') LIQ=E1441536.82,N576868.36 (47.3') RIQ=E1441746.82,N576713.36 (49.0') ROQ=E1441731.82,N577053.36 (48.5')