

REPORT OF CHANNEL CONDITIONS
(FOR CHANNELS 400 FEET WIDE OR GREATER)
 (EP 1130-2-520)

PAGE 1 OF 1 PAGES

DATE
 17 Aug 2015

TO: Navigation Interest

FROM: U.S. Army Engineer District, Baltimore
 P.O. Box 1715
 Baltimore, Maryland 21201-1715

RIVER/HARBOR NAME AND STATE

Baltimore Harbor Baltimore, Maryland

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF
 CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
Seagirt Marine Terminal West Channel Station 0+000 to 6+937 Additional Survey dates of: 4 Aug 2015	4 Aug 2015	400	1	42	40	42	45	42

REMARKS (Continue on reverse)

This information represents the results of surveys made on the dates indicated and can only be as representing the general conditions at that time. All depths refer to MLLW for the '83-'01 tidal epoch. Length of channel reported to the nearest mile (actual length is 1.31 miles). All depths reported to the nearest foot. LOQ=E1437836.17,N579434.37 (40.3') LIQ=E1436216.12,577859.44 (41.6') RIQ=E1436846.11,N578069.37 (44.6') ROQ=E1436756.12,N577054.37 (41.8')