

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE**
(EP 1130-2-520)

PAGE 1 OF 1

DATE
1 Apr 2013

TO:
Navigation Interests

FROM:
U.S. Army Engineer District, Baltimore
P.O. Box 1715 Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE

Tilghman Island Talbot County, Maryland

MINIMUM DEPTHS IN
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Tilghman Island Harbor Station 0+000 to 2+476.80	24 Jul 2012	60 200	1	6		5	

REMARKS (Continue on reverse)

All depths refer to MLLW for the '83-'01 tidal epoch. This information represents the results of surveys made on the dates indicated and can only be as indicating the general conditions at that time. Length of channel reported to nearest mile (actual length of channel is 0.47 statute miles). Depths reported to nearest foot. Middle Half equals 80% of channel width.
MH= E1502366.24,N381037.46 (4.9')