

REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(EP 1130-2-520)

PAGE 1 OF 1

DATE
 8 Jul 2010

TO:
 Navigation Interests

FROM:
 U.S. Army Engineer District, Baltimore
 P.O. Box 1715 Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE
 Cambridge Harbor Dorchester County, Maryland

MINIMUM DEPTHS IN
 CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Cambridge Harbor Station 0+000 to 3+600 Turning Basin width - 750'	24 Jun 2010	150	1	25	4	3	18

REMARKS *(Continue on reverse)*
 All depths refer to MLLW for the '83-'01 tidal epoch. This information represents the results of surveys made on the dates indicated and can only be as indicating the general conditions at that time. Length of channel reported to nearest mile (actual length of channel is 0.68 statute miles). Depths reported to nearest foot. LQ=E1578237.10,331301.12 (4.2') MH=E1578224.56,N331306.82 (2.5') RQ=E1577973.90,N332081.24 (18.3')