

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE**
(EP 1130-2-520)

PAGE 1 OF 1

DATE
23 Jan 2014

TO:
Navigation Interests

FROM:
U.S. Army Engineer District, Baltimore
P.O. Box 1715 Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE

Lower Thorofare Somerset County, MD

MINIMUM DEPTHS IN
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Lower Thorofare Station 0+000 to 4+800	15 Jan 2014	60	1	7		3	

REMARKS (Continue on reverse)

All depths refer to MLLW for the '83-'01 tidal epoch. This information represents the results of surveys made on the dates indicated and can only be as indicating the general conditions at that time. Length of channel reported to nearest mile (actual length of channel is 0.91 miles). Depths reported to nearest foot. Middle Half equals 80% of channel width.
MH= E1615267.14,N169321.40 (3.2')