

REPORT OF CHANNEL CONDITIONS
 100 TO 400 FEET WIDE
 (EP 1130-2-520)

PAGE 1 OF 1

DATE
 13 September 2007

TO:
 Navigation Interests

FROM:
 U.S. Army Engineer District, Baltimore
 P.O. Box 1715 Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE

MINIMUM DEPTHS IN
 CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Coan River	1/Jul/2007	60	0	10		10	

REMARKS (Continue on reverse)

All depths refer to mean lower low water (MLLW) for the 1983 to 2001 tidal epoch.
 This information represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions at that time.
 The length of the channel is reported to the nearest mile (it is actually 0.17 miles). The depth is reported to the nearest foot.
 Middle Half equals minimum depth in full channel: E12068896 22 N6684432.69 10.3