

**REPORT OF CHANNEL CONDITIONS**  
**(FOR CHANNELS 400 FEET WIDE OR GREATER)**  
 (EP 1130-2-520)

PAGE 1 OF 1 PAGES

DATE  
7 Jan 2013

TO: Navigation Interests

FROM: U.S. Army Engineer District, Baltimore  
 P.O. Box 1715  
 Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE  
 Baltimore Harbor Baltimore, Maryland

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
Brewerton Angle	19 Nov 2012	600	1	50	51	51	51	51

REMARKS (Continue on reverse)  
 All depths refer to MLLW for the '83-'01 tidal epoch. This information represents data from the survey dates shown and can only be as representing the general conditions at that time. Length of channel reported to nearest mile (actual length = 1.10 statute miles). All depths reported to nearest foot. LOQ= E1449683.77,N559983.76(51.1) LIQ=E1450039.88,N560454.41 (50.9) RIQ=E1450860.83,N560229.23(50.9) ROQ=E1451867.55,N559750.65 (50.7)