

REPORT OF CHANNEL CONDITIONS
(FOR CHANNELS 400 FEET WIDE OR GREATER)
 (EP 1130-2-520)

PAGE 1 OF 1 PAGES

DATE
 27 Jun 2012

TO: Navigation Interests

FROM: U.S. Army Engineer District, Baltimore
 P.O. Box 1715
 Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE

Baltimore Harbor Baltimore, Maryland

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
Craighill Upper Range Station 52+900 to 59+200 Additional survey dates: 11, 18, & 25 June 2012	25 Jun 2012	700	1	50	49	51	52	49

REMARKS (Continue on reverse)

This information represents the results of surveys made on the dates indicated and can only be as indicating the general conditions at that time. All depths refer to MLLW for the '83-'01 tidal epoch. Length of channel reported to nearest mile (actual length of channel is 1.19 miles). All depths reported to nearest foot. LOQ=E1475876.23,N545139.78 (48.6') LIQ=E1475713.86,N545746.42 (51.4') RIQ=E1476262.60,N545489.40 (51.6') ROQ=E1474611.68,N548583.99 (49.1')