

## **4825 Glenbrook Road Weekly Update for May 1, 2015**

This week crews started scrapping and digging the soils and concrete in the former back porch area, as they progress down to grade. They have not encountered debris or visual signs of contamination.

Crews are placing all of the soil and concrete from this area into drums because of the mustard and lewisite contaminated soil that was found by the back porch during the previous investigation. They will continue to excavate this area for the next few weeks.

Safety continues to be our number one priority at the site. Throughout every phase of the project, all necessary precautions are taken to ensure the safety of the site workers, the residents of the community, and those driving by.