

**REPORT OF CHANNEL CONDITIONS**  
**100 TO 400 FEET WIDE**  
*(EP 1130-2-520)*

PAGE 1 OF 1

DATE  
 7 September 2007

TO:  
 Navigation Interests

FROM:  
 U.S. Army Engineer District, Baltimore  
 P.O. Box 1715 Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE  
 Knapps Narrows Talbot County, Maryland

MINIMUM DEPTHS IN  
 CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Knapps Narrows	1/Jan/2007	75	2	9		5	

**REMARKS** *(Continue on reverse)*

All depths refer to mean lower low water (MLLW) for the 1983 to 2001 epoch.  
 This information represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions at that time.  
 The length of the channel is reported to the nearest mile (it is actually 1.95 miles). Since the channel width is 75 feet the middle half refers to the full channel width and only one depth will be reported. The depth reported is to the nearest foot.  
 Middle Half equals minimum depth in full channel: E1503144.97 N383819.61 4.8