

REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(EP 1130-2-520)

PAGE 1 OF 1

DATE
 12 September 2007

TO:
 Navigation Interests

FROM:
 U.S. Army Engineer District, Baltimore
 P.O. Box 1715 Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE
 Ocean City Inlet and Harbor Worcester County, Maryland

MINIMUM DEPTHS IN
 CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Ocean City Inlet and Harbor	1/Apr/2007	200	2	10	6	3	2

REMARKS *(Continue on reverse)*

All depths refer to mean lower low water (MLLW) for the 1983 to 2001 tidal epoch. This information represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions at that time. The length of the channel is reported to the nearest mile (it is actually 2.27 miles long). The depths are reported to the nearest foot.

L.O.Q.: E1856934.71 N246158.75 6.2 M.H.: E1856444.63 N246267.43 2.6 R.O.Q.: E1856459.72 N246280.80 1.6

Survey started at 7+000 and ended at 12+004.50.