

**REPORT OF CHANNEL CONDITIONS**  
**(FOR CHANNELS 400 FEET WIDE OR GREATER)**  
 (EP 1130-2-520)

PAGE 1 OF 1 PAGES

DATE  
 26 Jun 2012

TO: Navigation Interests

FROM: U.S. Army Engineer District, Baltimore  
 P.O. Box 1715  
 Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE  
 Baltimoe Harbor Baltimore, Maryland

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
Inner Harbor Additional survey dates: 8 & 10 May 2012	12 Jun 2012	400		25	18	22	21	18

REMARKS (Continue on reverse)  
 All depths refer to MLLW for the '83-'01 tidal epoch. This information represents the results of surveys made on the dates shown and can only be as representing the general conditions at that time. All depths reported to the nearest foot.  
 LOQ=E1424789.32,N587470.29 (17.4') LIQ=E1425384.40,N586930.29 (21.1') RIQ=E1425724.36,N586750.29 (22.0')  
 ROQ=E1424709.35,E588100.32 (17.8')