

REPORT OF CHANNEL CONDITIONS
(FOR CHANNELS 400 FEET WIDE OR GREATER)

(EP 1130-2-520)

PAGE 1 OF 1 PAGES

DATE
23 Dec 2011

TO: Navigation Interests

FROM: U.S. Army Engineer District, Baltimore
P.O. Box 1715
Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE
Baltimore Harbor Baltimore, MD

MINIMUM DEPTHS IN EACH 1/4 WIDTH OF
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
West Channel Additional survey dates of 30 November 2011.	1 Dec 2011	600	1	40	38	39	36	36

REMARKS (Continue on reverse)

All depths refer to MLLW for the 1983-2001 tidal epoch. This information represents the results of surveys made on the dates indicated and can only be as indicating the general results at that time. Length of channel reported to the nearest mile. Actual length is 1.38 statute miles. All depths are reported to nearest foot. LOQ=E1429825.74,N585689.85 (37.8') LIQ=E1430168.49,N585623.89 (39.0') RIQ=E1427451.06,587482.46 (36.3') ROQ=E1430285.61,N586040.66 (35.5')