

REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(EP 1130-2-520)

PAGE 1 OF 1

DATE
 21 August 2008

TO:
 Navigation Interests

FROM:
 U.S. Army Engineer District, Baltimore
 P.O. Box 1715 Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE
 Rock Hall Harbor Kent County, Maryland

MINIMUM DEPTHS IN
 CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Rock Hall Harbor Station Station 0+000 to 4+962.03	3/Jun/2008	100 200	1	10	4	5	6

REMARKS *(Continue on reverse)*

All depths refer to MLLW for the 1983-2001 tidal epoch. This information represents the results of surveys made on the dates indicated and can only be as indicating the general conditions at that time. The length of channel is reported to the nearest mile. The actual length of channel is 0.94 miles. Depths are reported to the nearest foot.

LQ=E1525336.93, N533758.37 (4.0')

MH=E1525355.43, N533736.48 (4.8')

RQ=E1526682.75, N534752.09 (6.4')