

REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(EP 1130-2-520)

PAGE 1 OF 1

DATE
 14 August 2008

TO:
 Navigation Interests

FROM:
 U.S. Army Engineer District, Baltimore
 P.O. Box 1715 Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE
 Smith Island Somerset County, Maryland

MINIMUM DEPTHS IN
 CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Ewell Basin Station 0+000 to 0+631	17/Apr/200	100	1	7	5	7	7

REMARKS *(Continue on reverse)*

All depths refer to MLLW for the 1983-2001 tidal epoch. This information represents the results of surveys made on the dates indicated (17 April 2008) and can only be as indicating the general conditions at that time.Length of channel reported to nearest mile (actual length is 0.12 miles).

LQ=E1590530.14, N121624.51 (5.3')

MH=E1590622.67, N121574.23 (6.5')

RQ=E1590576.15, N121694.19 (6.6')