

**REPORT OF CHANNEL CONDITIONS  
100 TO 400 FEET WIDE**  
(EP 1130-2-520)

PAGE 1 OF 1

DATE  
5 Aug 2015

TO:  
Navigation Interests

FROM:  
U.S. Army Engineer District, Baltimore  
P.O. Box 1715 Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE  
Smith Island Somerset County, MD

MINIMUM DEPTHS IN  
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Big Thorofare Station 7+677 to 15+100  Additional survey date: 29 July 2015	30 Jul 2015	60	3	7		4	

REMARKS (Continue on reverse)  
All depths refer to MLLW for the '83-'01 tidal epoch. This information represents the results of surveys made on the dates indicated and can only be as indicating the general conditions at that time. Length of channel reported to nearest mile (actual length of channel is 2.86 statute miles). Depths reported to nearest foot. Middle Half equals 80% channel width.  
MH=E1597625.94,N119249.10 (3.9')