

MW-24
 70
 57.6

MW-25
 60
 53.6

PZ4

PZ5

MW-26
 1.6
 2.28


Lot 18 Debris Area

SW-1
 6.5
 7.24

PZ3

MW-27
 2.6
 2.9
 3.23
 3.04
 3.36

Munitions Recovery Pits



Perchlorate Detections (ug/l)
 GPL Results in Blue
 Data Chem Results in Red
 Note: Results for wells with no perchlorate detection are not shown

Legend

- USACE Monitoring Well
- Proposed USACE Monitoring Well
- Surface Water Sample Location
- Piezometer
- Pit
- Trench
- Fault (Fleming, et al. 1994)
- State Boundary
- Spring Valley Boundary
- Building
- Road
- Water
- Topography (USGS)
 - 50-Foot Contour
 - 10-Foot Contour
- Topography (USACE)
 - 50-Foot Contour
 - 10-Foot Contour
 - 2-Foot Contour



File: MW_02_09_2005.mxd

Date: 2/10/06
 Author: JMN
 Checked: DF
 Senior: BE

200 Orchard Ridge Drive
 Gaithersburg, MD 20878
 301-258-9780

Figure 4
 Lot 18 Area
 Perchlorate Detections
 Spring Valley FUDS
 Washington, DC

Note: December Perchlorate Data are not Validated