

## **STURGIS Project Update, April 30, 2015**

The STURGIS safely arrived at the Port of Galveston today. The trip from Virginia went very well, but it went faster than we originally expected. Photos of her arrival can be found on the right-side of the page in the photo rotator and at:

<https://drive.google.com/open?id=0B9rzkLhUIJv1fmI4VzdKcFJ5amdMTWpmaXQxQjRQeWZ5SjV5dEd2a0hEYXBnRUITbEJseDQ&authuser=0>

CB&I (our prime contractor) has been at the Malin International Shipyard since April 20, and they have prepared the dock for the arrival of the STURGIS. As we explained in our email April 16, this preparation included installing the project security fencing, setting up office trailers, environmental monitoring equipment, and staff training.

The team is continuing to prepare the site for the decommissioning work and plans to start the radiological work at the beginning of July.