SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 03 January 2017
Site Location: 4825 Glenbrook Road

Weather:
Rain and cold Low 41° High 48°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	
Matter, Phil	Prate, Warren	
Nelms, Bobby	Vail, Todd	
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Hatcher, Charles

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel worked to get the site up and operational after the holiday break. They inspected and tested equipment and resupplied expendables.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors
DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	


PG
82 1-3-17
0630 SAFETY BRIEF.
0980 RADIO CHECKS.
1760 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 04 January 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cold Low 41° High 48°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Askew, Tom
Matter, Phil	Prate, Warren	Lewis, Leon
Nelms, Bobby	Vail, Todd	Shipp, Jason
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Boncal, Janelle		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Hatcher, Charles

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel began the day pumping rainwater from the driveway, 11 drums of water were collected. Then the team loaded roll off boxes with previously excavated soil from area B. Two boxes were filled and stored at the federal property site.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report	
Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**1/4/2017**
Weather:	**Mostly Cloudy 38-54 °F, wind – 0 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Started loading staged soil in driveway area into roll-offs. Two roll-offs filled.**
Summary:	**2 disposal characterization samples collected and subitted for headspace analysis: RA-4825GR-Area B-010417-01 and RA-4825GR-Area B-010417-02.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs
	Daily QC Logs
	UXO Safety Log (Weekly)
	COC
Signed by:	
Name (print):	**Janelle Boncal**
Date:	**1/4/2017**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Margaret Rockwell**

Sensitive



Pg

83 1-4-17

0630 SAFETY BRIEF

0700 RADIO CHECKS

0800 TRAFFIC SIGNS IN PLACE.
EYE WASH STATION HAS BEEN
FILLED. Janelle Bonial on Site.

0830 PUMPING WATER FROM DRIVEWAY.

0907 MINICAMS UP.

0919 DAAMS PUMPS RUNNING.

1030 WATER BARRELS H2O 522 THRU 533
FILLED AND READY FOR TRANSPORT.

1050 EPDS ~~SETUP~~ COMPLETE. EXCLUSION
ZONE ESTABLISHED.

1131 VOC COLLECTED, FILLING ROLLOFF
274169.

1220 COMPOSITE COLLECTED, ROLLOFF 274169 FULL.

1240 STARTING MID DAY CHALLENGE.

1335 MID DAY COMPLETE

1400 VOC COLLECTED, ROLLOFF R25926RT IN PLACE.

1425 ROLLOFF R25926RT IS FULL AND COMPOSITE COLLECTED

1509 STARTING END OF DAY CHECKS.

1750 SECURED

[signature]

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 05 January 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cold Low 30° High 36°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	Askew, Tom
Matter, Phil	Prate, Warren	Lewis, Leon
Nelms, Bobby	Vail, Todd	Shipp, Jason
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Boncal, Janelle		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Hatcher, Charles

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

The team continued loading roll off boxes with previously excavated soil from area B. Three boxes were filled and stored at the federal property site.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**1/5/2017**
Weather:	**Mostly Cloudy 33-38 °F, wind – 0 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Continued loading staged soil in driveway area into roll-offs. Three roll-offs filled.**
Summary:	**3 disposal characterization samples collected and subitted for headspace analysis: RA-4825GR-Area B-010517-01, RA-4825GR-Area B-010517-02 and RA-4825GR-Area B-010517-03.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Janelle Boncal**
Date:	**1/5/2017**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Margaret Rockwell**



Pg

84 1-5-12

0636 SAFETY BRIEF.

0750 RADIO CHECKS, MINICANS UP.

0815 TRAFFIC SIGNS IN PLACE.

0815 DAAMS PUMPS RUNNING.

0842 VOC COLLECTED, ROLLOFF R02112 RT IS BEING FILLED.

0925 ROLLOFF R02112RT IS FULL & COMPOSITE COLLECTED.

1015 VOC COLLECTED FILLING ROLLOFF R25924RT.

1050 ROLLOFF R25924RT IS FULL & COMPOSITE COLLECTED.

1146 STARTING MID DAY CHALLENGE

1159 MID DAY CHALLENGE COMPLETE.

1246 ROLLOFF R25359 RT ON SITE

1254 VOC COLLECTED

1450 ROLLOFF R25359RT IS FULL AND COMPOSITE COLLECTED.

1455 STARTING END OF DAY CHECKS.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 06 January 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cold Low 33° High 38°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	Askew, Tom
Matter, Phil	Prate, Warren	Lewis, Leon
Nelms, Bobby		Shipp, Jason
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Hatcher, Charles

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel worked to relocate the set of yellow stairs that go down the hill onto the site. The stairs were relocated and a new gravel walkway was constructed.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors
DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

85 6-6-17

0630 SAFETY BRIEF.

0750 RADIO CHECKS

0800 TRAFFIC SIGNS IN PLACE. THE TEAMS IS WORKING TO INSTALL TEMPORARY STAIRS.

1150 SECURED



SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 09 January 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and very cold Low 18° High 31°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	Askew, Tom
	Prate, Warren	Lewis, Leon
Nelms, Bobby	Vail, Todd	Shipp, Jason
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Hatcher, Charles

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel began the day dumping cleared soil roll off boxes at the federal property site. At 1000 Long fence arrived on site, they made repairs to the fence at the federal property site and installed three posts at the 4825 site. The posts will be used to install the new gate on Tuesday.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**1/9/2017**
Weather:	**Mostly Cloudy 20-26 °F, wind – 0 to 6 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Sent samples to ECBC for low level analysis. Crews dumped 3 roll-offs at Fed Property. Long Fence on-site--repaired barbed wire fence at Federal Property. Installed 3ft fence posts for new gate at 4825 site.**
Summary:	**Sent 5 samples to ECBC for low level analysis (See COC for IDs). Crews dumped 3 roll-offs at Fed Property. Long Fence on-site--repaired barbed wire fence at Federal Property. Installed 3ft fence posts for new gate at 4825 site.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**1/9/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



PG

86 1-9-17

0630 SAFETY BRIEF.

0700 RADIO CHECKS.

0744 MINI RAMS UP.

0800 DAAMS PUMPS RUNNING.

0830 THE TEAM IS WORKING AT FFD PROPERTY DUMPING ROLL OFF'S

1000 LONG FENCE ON SITE AND BRIEFED

1137 STARTING MID DAY CHALLENGE

1204 MID DAY CHALLENGE COMPLETE.

1468 STARTING END OF DAY CHECKS W/ MONITORING.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 10 January 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and very cold Low 28° High 35°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	Askew, Tom
	Prate, Warren	Lewis, Leon
Nelms, Bobby	Vail, Todd	Shipp, Jason
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel worked on leveling the new truck entrance along the front yard fence. Long Fence company installed the new truck gate. Site personnel installed temporary privacy screening.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**1/10/2017**
Weather:	**Cloudy 23-35 °F, wind – 0 to 12 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Sent samples to APPL for waste characterization. Crews dumped 3 roll-offs at Fed Property. Long Fence on-site--moved the fence line and installed swing gate. Parsons then installed temporary privacy screening on the gate. Crew put gravel and E&S controls in place.**
Summary:	**Sent samples 2 composite samples and 5 VOC samples to APPL for waste characterization. (See COC for IDs). Long Fence on-site--moved the fence line and installed swing gate. Parsons then installed temporary privacy screening on the gate. Crew put gravel and E&S controls in place.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**1/10/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



RG

87 1-10-17

0630 SAFETY BRIEF.

0700 RADIO CHECKS.

0800 TRAFFIC SIGN IN PLACE.

0825 SECURED POWER PANEL. "LOCKED" PADLOCK

0842 COMPLETED POWER PANEL MOVE. THE BREAKER PANEL IS UNLOCKED AND POWER BACK ON.

1020 LONG FENCE ON SITE, INSTALLING ROLL OFF GATE FOR AREA "B".

1310 LONG FENCE IS OFF SITE.

1700 SECURED.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 11 January 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cold Low 41° High 45°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	Askew, Tom
Matter, Phil		Lewis, Leon
Nelms, Bobby	Vail, Todd	Shipp, Jason
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Naum, Marin
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel worked to prepare a new area to load roll off boxes. The construction matting was rearranged and the area was graded and leveled. New walkway lighting was installed on the stairway.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**1/11/2017**
Weather:	**Mostly Cloudy 46-56 °F, wind – 0 to 8 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Moved construction mats , levelling and grading the new roll-off area.**
Summary:	**Moved construction mats , levelling and grading the new roll-off area.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**1/11/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Sensitive


Pg
88
1-11-17
0630 SAFETY BRIEF.
0730 RADIO CHECKS.
0800 TRAFFIC SIGNS IN PLACE.
0820 THE TEAMS ARE WORKING LEVELING
DRIVE.
1750 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 12 January 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cold Low 45° High 60°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	Askew, Tom
Matter, Phil	Prate, Warren	Lewis, Leon
Nelms, Bobby	Vail, Todd	Shipp, Jason
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT	CENAB
Naum, Marin	Martin, JR
Vargas, Brandon	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

The team worked to reestablish the walkway to the personnel gate that was disturbed by the installation of the new truck gate. After this the site worked on non- intrusive activities.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**1/12/2017**
Weather:	**Cloudy 51-71°F, wind – 0 to 8 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Moved construction mats , levelling and grading the new roll-off area. Crews performed work and maintenance activities at Fed Property.**
Summary:	**Moved construction mats , levelling and grading the new roll-off area. Crews performed work and maintenance activities at Fed Property.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**1/12/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



PG

89

1-12-17

0630 SAFETY BRIEF

0740 RADIO CHECKS

0820 TRAFFIC SIGNS IN PLACE

0825 TAT TEAMS ARE LEVELING DRIVEWAY

1100 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 17 January 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cold Low 43° High 57°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	
	Prate, Warren	
Nelms, Bobby	Vail, Todd	
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons and Zimmer personnel Cleaned the construction matting at the 4825 site. They also packaged filters for transport and dumped roll off boxes. ACI personnel began disconnecting the AC units at 4835.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY (0)
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**1/17/2017**
Weather:	**Rainy 46-56 °F, wind – 0 to 8 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**ACI on-site for air conditioning removal. Crews performed work at Fed Property in support of the air conditioning unit relocation.**
Summary:	**ACI on-site for air conditioning removal. Crews performed work at Fed Property in support of the air conditioning unit relocation.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**1/17/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**


1-17-17
SAFETY BRIEF
RADIO CHECKS.
TRAFFIC SIGNS IN PLACE.
ACI ON SITE AND BRIEFED.
WORKING ON PRESIDENT AC UNITS.
ACI OFF SITE
STICKERS

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 18 January 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cold Low 42° High 56°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	
	Prate, Warren	
Nelms, Bobby	Vail, Todd	
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

ACI continued disconnecting the AC units at 4835. Parsons and Zimmer personnel continued packaging filters. They also attended hazardous waste training at the federal property site and then transported the AC units from 4835 to the federal property for storage.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**1/18/2017**
Weather:	**Rainy 39-53 °F, wind – 0 to 12 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**ACI on-site for air conditioning removal. Crews performed work at Fed Property in support of the air conditioning unit relocation and relocated air conditioning units to Fed Property.**
Summary:	**ACI on-site for air conditioning removal. Crews performed work at Fed Property in support of the air conditioning unit relocation and relocated air conditioning units to Fed Property.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**1/18/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



Pg

91 1-18-17

0630 SAFETY BRIEF

0645 RADIO CHECKS.

0800 ACI ON SITE WORKING ON AC UNITS

1200 HAZ WASTE HANDLING TRAINING @ FEB

PROPERTY. SEAN BUCKLEY PROVIDED TRAINING.

1400 ACI OFF SITE. AC UNITS @ FEB

PROPERTY. TWO WEEK LOOK AHEADS.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 19 January 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cold Low 38° High 55°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	
	Prate, Warren	
Nelms, Bobby	Vail, Todd	
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel continued packaging filters and dumping roll off boxes. ACI completed capping the AC lines at 4835.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**1/19/2017**
Weather:	**Cloudy 39-52 °F, wind – 0 to 12 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews performed work at Fed Property.**
Summary:	**Crews performed work at Fed Property.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**1/19/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**


Pg
92 1-19-17
0630 SAFETY BRIEF
0800 RADIO CHECKS.
0830 ACI ON SITE. WORKING @ 4835 FB AC SYSTEM.
1200 ACI OFF SITE.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 23 January 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cold Low 42° High 52°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	Heard, Irvin
Matter, Phil	Prate, Warren	Shipp, Jason
Nelms, Bobby	Vail, Todd	Wright, Chris
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Intrusive operations were canceled due to heavy rain and high winds. Long Fence on-site to install privacy screen on fence. Parsons crews dumped roll-offs. 2 truckloads of Subtitle D Landfill soil went out. Improved E&S controls against the excessive rainfall from the storm.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**1/23/2017**
Weather:	**Wind and Rain 40-44 °F, wind – 0 to 25 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Long Fence on-site to install privacy screen on fence. Parsons crews dumped roll-offs. 2 truckloads of Subtitle D Landfill soil went out. Improved E&S controls against the excessive rainfall from the storm.**
Summary:	**Long Fence on-site to install privacy screen on fence. Parsons crews dumped roll-offs. 2 truckloads of Subtitle D Landfill soil went out. Improved E&S controls against the excessive rainfall from the storm.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**1/23/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



93 1-23-17
0630 SAFETY BRIEF.
0815 RADIO CHECKS
0925 LONG FENCE ON SITE TO INSTALL GATE SCREEN.
1040 LONG FENCE OFF SITE.
1700 SECURED.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 24 January 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cold Low 40° High 48°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	Heard, Irvin
Matter, Phil	Prate, Warren	Shipp, Jason
Nelms, Bobby	Vail, Todd	Wright, Chris
	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Pumped rainwater from area B and transferred 6 water drums to Fed Property. Removing fence panels at property line with AU President's House. Loaded 2 dump trucks of soil at the federal property site and sent to Subtitle D Landfill. Cut shrubbery on the AU President's property to gain access to the dig zone. Installed temporary fence panels in section were fence panels were removed.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY (0)
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**1/24/2017**
Weather:	**Mostly Cloudy 38-48 °F, wind – 0 to 15 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Transferred 6 water drums to Fed Property. Removing fence panels at property line with AU President's House. Loaded 2 dump trucks of soil to Subtitle D Landfill. Cut shrubbery on the AU President's property to gain access to the dig zone. Installed temporary fence panels in section were fence panels were removed.**
Summary:	**Transferred 6 water drums to Fed Property (See COC for IDs). Removing fence panels at property line with AU President's House. Loaded 2 dump trucks of soil to Subtitle D Landfill. Cut shrubbery on the AU President's property to gain access to the dig zone. Installed temporary fence panels in section were fence panels were removed.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**1/24/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



2

24	1-24-17
0630	SAFETY BRIEF.
0637	LIGHTNING HOLD. RADIO CHECKS.
0707	OFF LIGHTNING HOLD.
0755	TRAFFIC SIGNS IN PLACE. MINI CAMS UP.
0850	SWING GATES ARE OPEN. THE TEAMS ARE PUMPING WATER. AND REMOVING FENCE PANELS ON THE 4835 PROPERTY LINE.
1145	STARTING MID DAY CHALLENGE.
1205	MID DAY COMPLETE
1417	STARTING END OF DAY CHECKS WITH MONITORING
1750	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 25 January 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and mild Low 47° High 58°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	Heard, Irvin
Matter, Phil	Prate, Warren	Shipp, Jason
Nelms, Bobby	Vail, Todd	Wright, Chris
Oien, Joshua		
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel set up to begin intrusive operations along the 4825 and 4835 property line. AU personnel came and removed a flood light from the 4825 side of the property. After beginning intrusive operations, it was determined that the temporary fence would have to be placed in a way that may cause concerns for the event at the president's residence. Due to concerns from AU about the temporary fence and the event, intrusive was suspended and the temporary fence moved back to its original position. Intrusive operations will resume after the AU event.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY (0)
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**1/25/2017**
Weather:	**Sunny 44-60 °F, wind – 0 to 5 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Removing fence panels at property line with AU President's House. Cut shrubbery on the AU President's property to gain access to the dig zone.**
Summary:	**Removing fence panels at property line with AU President's House. Cut shrubbery on the AU President's property to gain access to the dig zone.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**1/25/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



95
1-25-17
0630 SAFETY BRIEF.
0738 RADIO CHECKS.
0753 TRAFFIC SIGNS IN PLACE.
0757 MINI CAMS UP @ 0752
0830 DAAMS PUMPS RUNNING
1150 STARTING END OF DAY CHECKS.
INTRUSIVE OPERATIONS SUSPENDED DUE
TO AN EVENT @ 483SGB.
1700 SECURED.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 26 January 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and mild Low 47° High 57°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	Heard, Irvin
Matter, Phil	Prate, Warren	Shipp, Jason
Nelms, Bobby	Vail, Todd	Wright, Chris
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel removed the brick facade from the retaining wall on the 4825 side of the property (NO JACKHAMMERING). The brick façade was transported to the federal property site. Personnel received training on the demolition saw then began scoring some sections of the wall on the 4825 side. After scoring the wall it was pulled down with the excavator.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**1/26/2017**
Weather:	**Partly Cloudy 35-57 °F, wind – 0 to 25 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Dumped 3 roll-offs. Crews removed red brick façade. Then loaded and transported façade to Fed site. Performed training with the demo saw. Used the demo saw to score/cut the cinder block wall. Proceeded to tear down approximately 5 ft high and 30 ft long section of cinder block wall. Performed end of week clean up and maintenance.**
Summary:	**Dumped 3 roll-offs. Crews removed red brick façade. Then loaded and transported façade to Fed site. Performed training with the demo saw. Used the demo saw to score/cut the cinder block wall. Proceeded to tear down approximately 5 ft high and 30 ft long section of cinder block wall. Performed end of week clean up and maintenance.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**1/26/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



96 1-26-17
0630 SAFETY BRIEF
0745 RADIO CHECKS. MINICAMS UP. SAW TRAINING
0800 TRAFFIC SIGNS IN PLACE.
0830 DAAMS PUMPS RUNNING. THE TEAM IS REMOVING THE BRICK FROM THE RETAINING WALL.
1150 CONFERENCE CALL
1139 STARTING MID DAY CHALLENGE.
1247 MID DAY CHALLENGE COMPLETE
1250 BREAKING AND REMOVING CINDER BLOCK WALL.
1450 STARTING END OF DAY/WEEK CHECKS.
1530 2WEEK LOOK AHEAD W/SEAN BUCKLEY.
1700 SECURE

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 30 January 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cold Low 31° High 34°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	Heard, Irvin
Matter, Phil	Prate, Warren	Owens Julius
Nelms, Bobby	Vail, Todd	Wright, Chris
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel began excavating area B along the 4825-4835 property line. Glass fragments were found and excavation halted. PDT agreed to continue intrusive operations. The waterline for the 4835 property line was uncovered and appears to have been damaged by an excavator sometime in the past. Parsons is making arrangements to have the waterline repaired.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**1/30/2017**
Weather:	**Cloudy 26-37 °F, wind – 0 to 15 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews excavated Area B near the 4835 property line. Crews sifted soil for AUES glass. A 2oz glass fragment was found and submitted for headspace.**
Summary:	**Crews excavated Area B near the 4835 property line. Crews sifted soil for AUES glass. A 2oz glass fragment was found and submitted for headspace (RA-4825GR-SCR-481).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**1/30/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



9Z L-30-17
0630 SAFETY BRIEF.
0750 RADIO CHECKS
0756 TRAFFIC SIGNS IN PLACE.
0808 MINICAMS AND DAMMS UP AND RONNING.
STARTING INTRUSIVE OPERATIONS.
0905 AUES GLASS FOUND. RA9825GR-SCE-481
WAS DOUBLE BAGGED, THE DIC SITE
COVERED AND NOTIFICATIONS MADE.
"LOW PROBABILITY CONTINGENCY PLAN INITIATED.
1050 PDT CALL TO DISCUSS POSSIBLE AUES GLASS.
1105 PDT DECISION WAS TO GO EACH TO
INTRUSIVE WORK.
1153 STARTING MID DAY CHALLENGE.
1257 MID DAY COMPLETE.
1430 THE TEAM FOUND THE WATER LINE FOR 4835 GD.
THE LINE IS KICKED, PICTURES AND
NOTIFICATIONS WERE MADE.
1540 STARTING END OF DAY CHECKS.
1700 SECURED.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 31 January 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cold Low 30° High 44°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	Heard, Irvin
Matter, Phil	Prate, Warren	Owens Julius
Nelms, Bobby	Vail, Todd	Wright, Chris
Oien, Joshua		
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel continued excavating area B along the 4825-4835 property line. Crews sifted soil for AUES glass. ACI made repairs to the waterline going to the 4835 property line. Glass fragments were found and submitted for headspace.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**1/31/2017**
Weather:	**Partly Cloudy 37-57 °F, wind – 0 to 8 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews excavated Area B near the 4835 property line. Crews sifted soil for AUES glass. Made repair to the waterline. Glass fragments were found and submitted for headspace.**
Summary:	**Crews excavated Area B near the 4835 property line. Crews sifted soil for AUES glass. Made repair to the waterline. Glass fragments were found and submitted for headspace (RA-4825GR-SCR-482).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**1/31/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



98 1-31-17
0630 SAFETY BRIEF.
0700 RADIO CHECKS.
0755 TRAFFIC SIGNS IN PLACE.
0800 ACI ON SITE. 3 RAMS PUMPS RUNNING.
0750 MINI CAMS UP.
0900 STARTING INTRUSIVE OPERATIONS, EPOS SETUP AND PERIMETER MONITORING IN PLACE.
1005 THE TEAM REPORTS FINDING CAR KEY GLASS. ALL INSTRUMENTS READ ZERO.
1129 STARTING MID DAY CHALLENGE
1150 MID DAY CHALLENGE COMPLETE.
1200 ACI ON SITE. MAKING REPAIRS TO 4" 35 GE WATER LINE.
1400 ACI COMPLETED REPAIRS.
1525 RA 4825 CB. SCR-482 DOUBLE BAGGED FOR HEAD SPACING. (GLASS & APPROX 24 OZ).
1540 STARTING END OF DAY CHECKS.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 01 February 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cold Low 36° High 45°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	Heard, Irvin
Matter, Phil	Prate, Warren	Owens Julius
Nelms, Bobby	Vail, Todd	Wright, Chris
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Hatcher, Charles

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel continued excavating area B along the 4825-4835 property line. One roll off box of area B soil was loaded and transported to the federal property site. Two truckloads of cleared soil were sent to the subtitle D landfill. Parsons received an inspection from the DC Inspections and Compliance Administration.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**2/1/2017**
Weather:	**Cloudy 36-49°F, wind – 0 to 4 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews excavated Area B near the 4835 property line. Crews filled one roll-off. Composite sample and VOC sample were collected and submitted for headspace. Shipped two trucks of soil to Subtitle D Landfill. Collected glass fragments and submitted for headspace. DC Department of Consumer and Regulatory Affairs Inspection and Compliance Administration on-site to conduct building permit inspection.**
Summary:	**Crews excavated Area B near the 4835 property line. Crews filled one roll-off. Composite sample and VOC sample were collected and submitted for headspace. Shipped two trucks of soil to Subtitle D Landfill. Collected glass fragments and submitted for headspace(RA-4825GR-SCR-483). DC Department of Consumer and Regulatory Affairs Inspection and Compliance Administration on-site to conduct building permit inspection.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**2/1/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg

99 2-1-17

0630 SAFETY BRIFF.

0730 CPJ ON SITE AND BRIEFED

0744 RADIO CHECKS. MINICAMS UP.

0800 DAAMS PUMPS RUNNING.

0837 CPJ OFF SITE.

0901 VOC COLLECTED. FILLING ROLLOFF 274806.

0946 ROLLOFF 274806 IS FULL & COMPOSITE COLLECTED

1100 ROLLOFF 274806 IS OFF SITE.

1127 STARTING MID DAY CHALLENGE.

1150 MID DAY COMPLETE.

1537 RA 4825 GE-SCR-483 DOUBLE BAGGED GLASS (7oz)

1539 STARTING END OF DAY CHECKS.

1710 SECURED. NOTE: THE CITY INSPECTOR WAS ON SITE @ APPROX 11:40 TO RENEW THE PUBLIC SPACE PERMIT. WE FAILED!

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 02 February 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cold Low 30° High 44°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	Heard, Irvin
Matter, Phil	Prate, Warren	Owens Julius
Nelms, Bobby	Vail, Todd	Wright, Chris
Oien, Joshua	Yorkshire, Bart	
	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Hatcher, Charles

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel continued excavating Area B along the 4825-4835 property line. Crews filled one roll-off. Pumped water from excavated area and transferred 2 drums to Fed Property. Collected glass fragments and submitted for headspace.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	W912DY-09-D-0062
Delivery Order Number:	0006
Project Name:	4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.
Project Number:	748272.03000
Site Location:	Spring Valley, Washington, DC.
Date:	2/2/2017
Weather:	Mostly Cloudy 26-44°F, wind – 0 to 10 mph.
Field Instrument:	Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs
Measurements:	All Non Detect.
Calibrations:	Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.
Activities Conducted:	Crews excavated Area B near the 4835 property line. Crews filled one roll-off. Composite sample and VOC sample were collected and submitted for headspace. Pumped water from excavated area and transfered 2 drums to Fed Property. Collected glass fragments and submitted for headspace.
Summary:	Crews excavated Area B near the 4835 property line. Crews filled one roll-off. Composite sample and VOC sample were collected and submitted for headspace. Pumped water from excavated area and transferred 2 drums (4825GR-RDW-AQ-540 and 4825GR-RDW-AQ-541) to Fed Property. Collected glass fragments and submitted for headspace (RA-4825GR-SCR-484).
Items Found:	None
Contingency Plan Initiated:	No
Air Monitoring:	MiniCAMMS , DAAMS
IDW Generated:	PPE and Decon Water
Waste Disposal:	None
Departures from approved SSWP:	None
Problems encountered/resolutions:	None
Instructions given by government personnel:	None
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) COC
Signed by:	
Name (print):	Margaret Rockwell
Date:	2/2/2017
Phone Number:	571-721-9804
Copies sent to:	Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal



100 2-2-17
0630 SAFETY BRIEF.
0745 RADIO CHECKS.
0750 MINICAMS UP
0800 DAMMS PUMPS RUNNING.
0821 ROLLOFF 279968 ON SITE.
0825 VOC COLLECTED.
0910 ROLLOFF 279968 IS FULL AND COMPOSITE SAMPLE COLLECTED.
0925 ROLLOFF 279968 OFF SITE.
1140 STARTING MID DAY CHALLENGE.
1157 MID DAY COMPLETE.
1258 RA-4825GR-AQ-540 & 541 HAVE BEEN FILLED. (HZ°)
141 JCA-4825CR-SCR-484 DOUBLE BAGGED "GLASS"
1438 STARTING END OF DAY/WEEK CHECKS.
1520 TWO WEEK LOOK AHEAD.
1718 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 06 February 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cold Low 38° High 54°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	Heard, Irvin
Matter, Phil	Prate, Warren	Owens Julius
Nelms, Bobby	Vail, Todd	Wright, Chris
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Hatcher, Charles

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

1000 hour maintenance was performed on the 88 excavator. Personnel dumped 4 roll off boxes of cleared soil at the federal property site. Crews excavated Area B near the 4835 property line and filled one roll-off.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**2/6/2017**
Weather:	**Sunny 46-61ºF, wind – 0 to 7 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Routine maintenance was performed on the 88 excavator. Crews excavated Area B near the 4835 property line. Crews filled one roll-off. Composite sample and VOC sample were collected and submitted for headspace.**
Summary:	**Routine maintenance was performed on the 88 excavator. Crews excavated Area B near the 4835 property line. Crews filled one roll-off. Composite sample (RA-4825GR-Area B-01-020617) and VOC(RA-4825GR-Area B-VOC-020617-01) sample were collected and submitted for headspace.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**2/6/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



Pg
1 2-6-17
0630 SAFETY BRIEF.
0715 RADIO CHECKS. RISH MAINTENANCE ON SITE.
0750 MINICAMS UP
0810 TRAFFIC SIGNS IN PLACE.
1052 RISH MAINTENANCE OFF SITE.
1130 STARTING MID DAY CHALLENGE.
1135 DAAMS PUMPS RUNNING
1138 MINICAMS BACKUP.
1250 VOC COLLECTED FOR ROLLOFF 274823.
1345 ROLLOFF 274823 IS FULL AND COMPOSITE COLLECTED.
1358 ROLLOFF 274823 IS OFF SITE.
1531 STARTING END OF DAY CHECKS.
1535 ROLL OFF 274314 ON SITE.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 07 February 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and mild Low 48° High 64°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	Heard, Irvin
Matter, Phil	Prate, Warren	Owens Julius
Nelms, Bobby	Vail, Todd	Copeland, Eric
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Hatcher, Charles

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Crews excavated Area B near the 4835 property line. Crews filled 3 roll-offs. 3 Composite samples and 3 VOC samples were collected and submitted for headspace.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY (0)
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**2/7/2017**
Weather:	**Mostly Cloudy 56-68°F, wind – 0 to 8 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**2 samples were sent to ECBC for low level analysis. Crews excavated Area B near the 4835 property line. Crews filled 3 roll-offs. 3 Composite samples and 3 VOC samples were collected and submitted for headspace.**
Summary:	**2 samples were sent to ECBC for low level analysis (See COC for IDs). Crews excavated Area B near the 4835 property line. Crews filled 3 roll-offs. Composite sample (RA-4825GR-Area B-01-020717, RA-4825GR-Area B-02-020717, RA-4825GR-Area B-03-020717) and VOC(RA-4825GR-Area B-VOC-020717-01, RA-4825GR-Area B-VOC-020717-02, RA-4825GR-Area B-VOC-020717-03) samples were collected and submitted for headspace.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**2/7/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg

2 2-7-17

0630 SAFETY BRIEF

0700 RADIO CHECKS

0745 MINICAMS UP.

0809 BAAMS PUMPS RUNNING.

0823 VOC COLLECTED FOR ROLLOFF 274823.

0910 ROLLOFF 274314 IS FULL AND COMPOSITE COLLECTED.

0930 ROLLOFF 274314 IS OFF SITE.

0953 ROLLOFF 280196 IS ON SITE.

1140 STARTING MIDDAY CHALLENGE

1200 MIDDAY CHALLENGE COMPLETE

1245 VOC COLLECTED FILLING ROLLOFF 280196.

1345 ROLLOFF FULL 280196 AND COMPOSITE COLLECTED

1350 ROLL OFF 280196 IS OFF SITE.

1405 ROLLOFF 279892 IS ON SITE

1503 VOC COLLECTED FILLING ROLLOFF 279892.

1536 ROL-OFF OFF 279892 IS FULL COMPOSITE COLLECTED.

1545 STARTING END OF DAY CHECKS.

1551 ROLLOFF 279892 OFF SITE.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 08 February 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and mild Low 55° High 60°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	Heard, Irvin
Matter, Phil	Prate, Warren	Owens Julius
Nelms, Bobby	Vail, Todd	Copeland, Eric
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Hatcher, Charles

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel continued excavating area B along the 4825-4835 property line and loading roll off boxes. One roll off box of concrete rubble was loaded and transported to the federal property site.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**2/8/2017**
Weather:	**Mostly Cloudy 35-68°F, wind – 0 to 9 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews continued to excavate Area B near the 4835 property line. Crews filled 2 roll-offs with soil and one with rubble. 2 composite and 2 VOC samples were collected.**
Summary:	**Crews continued to excavate Area B near the 4835 property line. Crews filled 2 roll-offs with soil and one with rubble. 2 composite (RA-4825GR-Area B-01-020817 and RA-4825GR-Area B-02-020817) and 2 VOC samples (RA-4825GR-Area B-VOC-020817-01 and RA-4825GR-Area B-VOC-020817-02) were collected and submitted for headspace.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**2/8/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg 3

2-8-17

0630 SAFETY BRIEF.
0744 RADIO CHECKS, MINICAMS UP.
0850 DAAMS PUMPS UP.
0912 ROLLOFF RB36777RT ON SITE. FILLING W/ DEBRIS
0959 ROLLOFF RB36777RT IS OFF SITE.
1149 ROLLOFF 279693 ON SITE
1153 STARTING MID DAY CHALLENGE.
1217 MIDDAY CHALLENGE COMPLETE.
1231 VOC COLLECTED FOR ROLLOFF 279693.
1335 ROLLOFF 279693 IS FULL AND COMPOSITE COLLECTED.
1348 ROLLOFF 279693 OFF SITE.
1401 ROLLOFF 27430815 ON SITE
1458 VOC COLLECTED
1527 ROLLOFF FULL 279693 AND COMPOSITE COLLECTED.
1536 STARTING END OF DAY CHECKS.
1540 ROLLOFF 279693 OFF SITE.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 09 February 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cold Low 25° High 45°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	Heard, Irvin
Matter, Phil	Prate, Warren	Owens Julius
Nelms, Bobby	Vail, Todd	Copeland, Eric
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel continued excavating area B in grids -10/-70, -10/-90, -30/-70 and -30/-90 .

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**2/9/2017**
Weather:	**Mostly Cloudy with some snow in the morning 22-36°F, wind – 0 to 20 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews continued to excavate Area B near the 4835 property line. Sent 4 samples to ECBC for low level analysis. 2 composite and 2 VOC samples were shipped to APPL for disposal characterization. 2 roll-offs were filled and 2 composite and 2 VOC samples were taken and submitted for headspace. Made improvements to the roll-off driveway.**
Summary:	**Crews continued to excavate Area B near the 4835 property line. Sent 4 samples to ECBC for low level analysis (See COC for IDs). 2 composite and 2 VOC samples were shipped to APPL for disposal characterization (See COC for IDs). 2 roll-offs were filled and 2 composite and 2 VOC samples were taken and submitted for headspace (RA-4825GR-Area B-01-020917, RA-4825GR-Area B-02-020917 and RA-4825GR-Area B-VOC-020917-01 and RA-4825GR-Area B-VOC-020917-02). Made improvements to the roll-off driveway.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**2/9/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

(4) 9 Feb 2017 Thursday

0630 Daily safety & operations briefings. Snow starting.
0735 Radio checks
0806 Mini CAMS/CAAMS up & running PID/HCL/HCN monitors up also.
0820 Begin intrusive operations in Area B. Bruce Courtney is out today after dental surgery.
0912 R/O # 279982 in.
0925 VOC sample collected Begin filling rolloff.
1010 Comp Sample taken
1022 Rolloff removed
1132 Midday/Lunch
1149 Min. CAMS up
1208 Resume ops. RO# RB37384RT in.
1212 VOC collected
1332 Composite Sample taken, rolloff full
1400 Rolloff out, bringing over rock to fix ruts @ gate.
1500 End of day Mini CAMS/Team securing items down range due to high winds
1545 Begin building & vehicle maintenance.
1700 End of day all secure.

Working follows

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 13 February 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cold Low 38° High 45°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth		Heard, Irvin
Matter, Phil	Prate, Warren	DeLaPaz, Hector
Nelms, Bobby	Vail, Todd	Copeland, Eric
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Crews continued to excavate Area B in grids -10/-70, -10/-90, -30/-70 and -30/-90. 2 roll-offs were filled and 2 composite and 2 VOC samples were collected. Parsons PM on-site for site walk. Personnel installed the vibration monitors on the 4835 property.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**2/13/2017**
Weather:	**Sunny with very high winds 30-44°F, wind – 25 to 35 mph with gusts up to 60 mph.**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews continued to excavate Area B near the 4835 property line. 2 composite and 4 VOC samples were shipped to APPL for disposal characterization. 2 roll-offs were filled and 2 composite and 2 VOC samples were collected. Parsons PM on-site for site walk.**
Summary:	**Crews continued to excavate Area B near the 4835 property line. 2 composite and 4 VOC samples were shipped to APPL for disposal characterization (See COC for IDs). 1 roll-off was filled and 1 composite and 1 VOC sample were collected. Parsons PM on-site for site walk.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**2/13/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg 5

2-13-17

0630 SAFETY BRIEF
0710 RADIO CHECKS.
0756 MINICAMS UP.
0800 SAAMS PUMPS RUNNING, THE EPO'S IS UP AND THE EXCLUSION ZONE ESTABLISHED. STARTING INTRUSIVE OPERATIONS.
1159 STARTING MID DAY CHALLENGE
1214 MINICAMS UP.
1303 ROLL OFF 279887 ON SITE.
1315 VOC COLLECTED, FILLING ROLLOFF 279887.
1412 ROLLOFF 279887 IS FULL AND COMPOSITE COLLECTED.
1420 ROLLOFF 279887 IS OFF SITE
1430 SEAN BUCKLEY ON SITE.
1444 ROLLOFF RE 21724RT ON SITE.
1540 SEAN BUCKLEY OFF SITE.
1555 STARTING END OF DAY CHECKS.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 14 February 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and mild Low 40° High 47°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth		Owevs, Julius
Matter, Phil	Prate, Warren	DeLaPaz, Hector
Nelms, Bobby	Vail, Todd	Copeland, Eric
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Hatcher, Charles

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Crews continued to excavate Area B near the 4835 property line. We filled 2 roll-offs with excavated soil. Due to the depth of the excavation we need to bench some ground on the 4835 side of the line and needed to push the temporary fence closer to the house. The team began cutting back brush and moving the fence.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**2/14/2017**
Weather:	**Cloudy 38-50°F, wind 0-3 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews continued to excavate Area B near the 4835 property line. Sent 4 samples to ECBC for low level analysis. Submitted sample from yesterday (RA-4825GR-Area B-01-021317) for headspace. Collected and submitted glassware for headspace (RA-4825GR-SCR-485). Filled 2 roll-offs and collected 2 composite (RA-4825GR-Area B-01-021417, RA-4825GR-Area B-02-021417) and 2 VOC (RA-4825GR-Area B-VOC-021417-01 and RA-4825GR-Area B-VOC-021417-02) samples and submitted for headspace. Crews moved fence closer to 4835 side.**
Summary:	**Crews continued to excavate Area B near the 4835 property line. Sent 4 samples to ECBC for low level analysis (See COC for IDs). Submitted sample from yesterday (RA-4825GR-Area B-01-021317) for headspace. Collected and submitted glassware for headspace (RA-4825GR-SCR-485). Filled 2 roll-offs and collected 2 composite (RA-4825GR-Area B-01-021417, RA-4825GR-Area B-02-021417) and 2 VOC (RA-4825GR-Area B-VOC-021417-01 and RA-4825GR-Area B-VOC-021417-02) samples and submitted for headspace. Crews moved fence closer to 4835 side.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**2/14/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg	
6	2-14-17
0630	SAFETY BRIEF.
0722	RADIO CHECKS.
0800	TRAFFIC SIGNS IN PLACE.
0824	MINICAMS UP.
0840	DAAMS PUMPS RUNNING.
0845	VOC COLLECTED ROLLOFF RB 21724RT BEING FILLED.
0924	ROLLOFF RB 21724RT IS FULL AND COMPOSITE COLLECTED.
0925	MINICAMS REPORTS AT ISSUE W/ THE FIRST GATE FOR MUSTARD. TAF TEAMS ARE OUT TO THE EXCLUSION ZONE.
1038	MINICAMS ARE BACK UP.
1100	ROLLOFF RB 21724RT OFF SITE. RA 4825GR SCR-485 DOUBLE BAGGED (GLASS) 116. TO FED PROPERTY FOR HEAD SPACING.
1115	ROLLOFF 279655 ON SITE
1129	VOC COLLECTED. FILLING ROLLOFF 279655.
1219	ROLLOFF 279655 IS FULL AND COMPOSITE COLLECTED. STARTING MID DAY CHALLENGE.
1244	MID DAY CHALLENGE COMPLETE.
1332	ROLLOFF 279655 OFF SITE.
1447	STARTING MINI CAMS END OF DAY CHECKS.
1700	SECURED



SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 15 February 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and mild Low 38° High 48°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth		Owevs, Julius
Matter, Phil	Prate, Warren	DeLaPaz, Hector
Nelms, Bobby	Vail, Todd	Copeland, Eric
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Hatcher, Charles

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel completed moving the temporary fence further onto the 4835 property. Team personnel continued to excavate Area B in grids -10/-70, -10/-90, -30/-70 and -30/-90.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**2/15/2017**
Weather:	**Partly Cloudy 29-51°F, wind 0-22 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews continued to excavate Area B near the 4835 property line andcompleted moving the fence at the 4835 property line. Filled one roll-off. Collected one composite and one VOC sample and submitted for headspace.**
Summary:	**Crews continued to excavate Area B near the 4835 property line and completed moving the fence at the 4835 property line. Filled one roll-off. Collected one composite and one VOC sample and submitted for headspace.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**2/15/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg	
7	2-15-17
0630	SAFETY BRIEF
0750	RADIO CHECKS.
0757	MINI CAMS UP @ 07:44 DAAMS @ 07:55
	FCBC MAINTENANCE ON SITE TO REPLACE
	THE MINI CAMS SHED HEATER.
0800	TRAFFIC SIGNS IN PLACE.
0845	ECBC MAINTENANCE OFF SITE.
1137	STARTING MID DAY CHALLENGE.
1154	MID DAY COMPLETE.
1335	ROLL OFF R2624RT ON SITE.
1352	VIC COLLECTED, FILLING ROLLOFF R2624RT.
1450	ROLLOFF R2624RT IS FULL AND COMPOSITE COLLECTED
1507	ROLLOFF R2624RT IS OFF SITE.
1540	STARTING END OF DAY CHECKS.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 16 February 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cool Low 3o° High 38°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth		Owevs, Julius
Matter, Phil	Prate, Warren	DeLaPaz, Hector
Nelms, Bobby	Vail, Todd	Copeland, Eric
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Hatcher, Charles

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Team personnel will continue to excavate Area B in grids -10/-70, -10/-90, -30/-70 and -30/-90 and load soil into roll off boxes.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**2/16/2017**
Weather:	**Partly Cloudy 26-38°F, wind 0-14 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews continued to excavate Area B near the 4835 property line. Submitted one sample to ECBC for low level analysis. Sent 2 composite samples and 4 VOC samples to APPL for disposal characterization. Filled one roll-off. Collected one composite and one VOC sample and submitted for headspace. Crews dumped roll-offs at the Fed Site and performed weekly vehicle and equipment maintenance. Crews prepped site for the weekend.**
Summary:	**Crews continued to excavate Area B near the 4835 property line. Submitted one sample to ECBC for low level analysis. Sent 2 composite samples and 4 VOC samples to APPL for disposal characterization (See COC for IDs). Filled one roll-off. Collected one composite and one VOC sample and submitted for headspace. Crews dumped roll-offs at the Fed Site and performed weekly vehicle and equipment maintenance. Crews prepped site for the weekend.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**2/15/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



PC
8

2-16-17

0630 SAFETY BRIEF.
0756 RADIO CHECKS.
0800 TRAFFIC SIGNS IN PLACE.
0804 MINICHAMS AND DRAMS UP.
0830 ROLL OFF 280192 ON SITE.
0840 VOC COLLECTED. FILLING ROLLOFF 280192
0924 ROLLOFF 280192 IS FULL AND COMPOSITE COLLECTED.
0935 ROLLOFF 280A2 OFF SITE
1055 STARTING END OF DAY CHECKS.
1100 WEEKLY CONFERENCE CALL.
1130 CONFERENCE CALL IS OVER.
1200 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 21 February 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and mild Low 51° High 60°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth		Alvano, Lou
Matter, Phil	Prate, Warren	DeLaPaz, Hector
Nelms, Bobby	Vail, Todd	Copeland, Eric
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Crews continued to excavate Area B near the 4835 property line. They are benching and sloping on the 4835 side of the line. The team also cut additional shrubbery.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report	
Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**2/21/2017**
Weather:	**Partly Cloudy 44-57°F, wind 0-6 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews continued to excavate Area B near the 4835 property line. Crews collected glass and submitted for headpsace. Submitted four samples to ECBC for low level analysis. Shipped composite and VOC samples to APPL for waste characterization.**
Summary:	**Crews continued to excavate Area B near the 4835 property line. Crews collected glass and submitted for headspace(RA-4825GR-SCR-486). Submitted four samples to ECBC for low level analysis. Shipped composite and VOC samples to APPL for waste characterization (See APPL COC for IDs).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs
	Daily QC Logs
	UXO Safety Log (Weekly)
	COC
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**2/21/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg 9

2-21-17

0630 SAFETY BRIEF.

0800 RADIO CHECKS. TRAFFIC SIGNS IN PLACE. EPDS AND EXCLUSION ZONE ESTABLISHED.

0820 STARTING INTRUSIVE OPERATIONS.

1020 EYE WASH STATION WAS CHANGED.

1158 STARTING MID DAY CHALLENGE.

1250 MID DAY COMPLETE @ 12:13.

1300 WILLIAMS SCOTTSMAN MAINTENANCE ON SITE TO REPAIR HEATER.

1320 WILLIAMS SCOTTSMAN MAINTENANCE OFF SITE. REPLACED ELECTRICAL BREAKER.

1520 CENAB ON SITE STARTING END OF DAY CHECKS.

1555 CENAB OFF SITE.

1701 SECURED.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 22 February 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and mild Low 53° High 66°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth		Alvano, Lou
Matter, Phil	Prate, Warren	DeLaPaz, Hector
Nelms, Bobby	Vail, Todd	Copeland, Eric
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel are removing a section of concrete wall and footer from grid -10/-90 and continuing to excavate area B.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**2/22/2017**
Weather:	**Mostly Cloudy 49-65°F, wind 0-5 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews continued to excavate Area B near the 4835 property line. Crews jackhammered a section of the retaining wall in grid (-10, -90). After the wall was removed, the crew broke it into pieces and staged it out of the way. Installed and observed vibration monitors. Fueled excavators. Glass was collected and submitted for headspace.**
Summary:	**Crews continued to excavate Area B near the 4835 property line. Crews jackhammered a section of the retaining wall in grid (-10, -90). After the wall was removed, the crew broke it into pieces and staged it out of the way. Installed and observed vibration monitors. Fueled excavators. Glass was collected and submitted for headspace (RA-4825GR-SCR-487).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**2/22/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

10	2-22-17
0630	SAFETY BRIEF.
0700	RADIO CHECKS.
0745	MINICAMS UP
0800	TRAFFIC SIGNS IN PLACE. DAAMS RUNNING.
0810	STARTING INTRUSIVE OPERATIONS. VIBRATION MONITORS ARE IN PLACE.
0942	STARTING HYDRAULIC HAMMER OPERATIONS.
1142	STARTING MID DAY CHALLENGE.
1228	MID DAY COMPLETE @ 12:03
1541	SA-4825GR-SCR-487 WAS DOUBLE RACKED (GLASS) 1.5 LBS FOR HEAD SPACING.
1557	STARTING END OF DAY CHECKS.
1615	THE TEAMS WERE OUT BRIEFED.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 23 February 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and mild Low 52° High 62°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth		Alvano, Lou
Matter, Phil	Prate, Warren	DeLaPaz, Hector
Nelms, Bobby	Vail, Todd	Copeland, Eric
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel continued to excavate area B and fill roll off boxes with soil. Black substance encountered in grid -10, -90. PDT notified. Samples collected.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**2/23/2017**
Weather:	**Mostly Sunny 53-75ºF, wind 0-12 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Ran 3 cycles of Minicams on the black substance. Conveyed a PDT call. Took Grab Sample 01 from Area B and submitted for headspace. Drummed the soil from the area surrounding the black substance. Put black substance in 8 oz jar and submitted for headspace. Filled roll-off R25738RT and collected composite and VOC sample and submitted for headspace. Sent 3 composite samples and 4 VOC to APPL for disposal characterization**
Summary:	**Ran 3 cycles of Minicams on the black substance. Conveyed a PDT call. Took Grab Sample 01 from Area B and submitted for headspace (RA-4825GR-Area B-Grab-01-022317). Drummed the soil from the area surrounding the black substance . Put black substance in 8 oz jar and submitted for headspace(RA-4825GR-AreaB-Grab-02-022317). Filled roll-off R25738RT and collected composite (RA-4825GR-Area B-01-022317) and VOC (RA-4825GR-Area B-VOC-022317-01) samples and submitted for headspace. Sent 3 composite samples and 4 VOC to APPL for disposal characterization (See APPL COC for IDs).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs
	Daily QC Logs
	UXO Safety Log (Weekly)
	COC
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**2/23/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg	
11	2-23-17
0630	SAFETY BRIEF.
0700	RADIO CHECKS.
0753	MINICAMS UP
0800	TRAFFIC SIGNS UP. DAAMS RUNNING EPDS UP AND EXCLUSION ZONE ESTABLISHED.
1100	CONFERENCE CALL.
1120	CONFERENCE CALL OVER.
1150	STARTING MID DAY CHALLENGE.
1215	MID DAY COMPLETE @ 12:03.
1315	PDT CALL.
1336	COLLECTING GRAB SAMPLE. "1 B"
1417	SOIL FROM EXCAVATION W/ BLACK SUBSTANCE DRUMED. RA4825GR-RDW-1031
1429	VOC COLLECTED. FILLING ROLLOFF R25738RT.
1515	ROLLOFF R25738RT IS FULL AND COMPOSITE COLLECTED.
1525	ROLLOFF R25738RT IS OFF SITE.
1528	STARTING END OF DAY/WEEK CHECKS.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 27 February 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cool Low 31° High 58°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Avila, Michelle
Matter, Phil	Prate, Warren	Askey, Tom
Nelms, Bobby	Vail, Todd	PalePale, Mo
Oien, Joshua		
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Crews continued to excavate Area B near the 4835 property line. They are benching and sloping on the 4835 side of the line. Four roll off boxes were filled and stored at the federal property site.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**2/27/2017**
Weather:	**Cloudy 44-53°F, wind 0-8 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews continued to excavate in Area B. Filled 4 roll-offs and collected 4 composite and 4 VOC samples and submitted for headspace.**
Summary:	**Crews continued to excavate in Area B. Filled 4 roll-offs and collected 4 composite and 4 VOC samples and submitted for headspace (See COC for IDs).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**2/27/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pa

12	2-27-17
0630	SAFETY BRIEF
0700	RADIO CHECKS.
0800	MINICAMS AND BARMS UP. TRAFFIC
	SIGNS IN PLACE. THE MONTHLY
	SAFETY MEETING WAS HELD @ THE
	SITE TRAILER.
0839	VOC COLLECTED. FILLING ROLLOFF RB36774RT.
0938	ROLLOFF RB36774RT IS FULL & COMPOSITE COLLECTED
0947	ROLLOFF RB36774RT IS OFF SITE.
1015	VOC COLLECTED. FILLING ROLLOFF 274582
1114	ROLLOFF 274582 IS FULL & COMPOSITE COLLECTED.
1126	ROLLOFF 274582 IS OFF SITE
1133	MINICAMS REPORTS 1.4 FOR MUSTARD.
	THE TEAMS WERE OUT OF THE EXCLUSION ZONE
	AND UP WIND.
1143	MINICAMS REPORTS ALL CLEAR.
1202	STARTING MID DAY CHALLENGE. THE GUARDS
	@ FEB PROPERTY REPORT A PAYNE TRUCK
	STRUCK THE FENCE. PICTURES OF THE DAMAGE
	WERE TAKEN AND SEAN BUCKLEY & DOUG ZIMMER
	NOTIFIED.
1254	MINICAMS BACK UP.
1302	VOC COLLECTED. FILLING ROLLOFF R25692RT.
1358	ROLLOFF R25692RT IS FULL & COMPOSITE COLLECTED.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 28 February 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cool Low 50° High 68°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Avila, Michelle
Matter, Phil	Prate, Warren	Askey, Tom
Nelms, Bobby	Vail, Todd	PalePale, Mo
Oien, Joshua		
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued excavating grids -10/-70, -10/-90, -30/-70 and -30/-90 in preparation of the geologist inspection tomorrow. Two roll off boxes were filled and stored at the federal property site.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**2/28/2017**
Weather:	**Cloudy 58-66°F, wind 0-8 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews continued to excavate in Area B. Filled 2 roll-offs and collected 2 composite and 2 VOC samples and submitted for headspace. Sent 2 samples to ECBC for low level analysis**
Summary:	**Crews continued to excavate in Area B. Filled 2 roll-offs and collected 2 composite samples (RA-4825GR-Area B-01-022817 and RA-4825GR-Area B-02-022817) and 2 VOC samples (RA-4825GR-Area B-VOC-022817-01 and RA-4825GR-Area B-VOC-022817-02) and submitted for headspace. Sent 2 samples to ECBC for low level analysis (RA-4825GR-Area B-01-022317 and RA-4825GR-Area B-Grab-01-022317).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**2/28/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg	
14	2-28-17
0630	SAFETY BRIEF.
0700	RADIO CHECKS.
0850	TRAFFIC SIGNS IN PLACE, MINICAMS AND BARMS UP.
0928	ROLLOFF 280191 ON SITE.
0944	VOC COLLECTED, FILLING ROLLOFF 280191
1100	ROLLOFF 280191 IS FULL & COMPOSITE COLLECTED
1109	ROLLOFF 280191 IS OFF SITE.
1131	ROLLOFF R 2649RT ON SITE.
1159	STARTING MIDDAY CHALLENGE.
1243	MIDDAY CHALLENGE COMPLETE.
1317	VOC COLLECTED ROLLOFF R2649RT BEING FILLED
1421	ROLLOFF R2649RT IS FULL & COMPOSITE COLLECTED
1440	ROLLOFF R2649RT OFF SITE.
1530	STARTING END OF DAY CHECKS.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 01 March 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cool Low 50° High 71°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Avila, Michelle
Matter, Phil	Prate, Warren	Askey, Tom
Nelms, Bobby	Vail, Todd	PalePale, Mo
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel began the day pumping water out of the excavation, water was due to rain Tuesday night. At 0930 David King, a Baltimore geologist inspected and confirmed grids -10/-70, -10/-90, -30/-70 and -30/-90 to were excavated to competent saprolite. At 1000 intrusive operations were suspended due to weather, Personnel worked on projects at the federal property site.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**3/1/2017**
Weather:	**Partly Cloudy 43-77°F, wind 0-18 mph, rain in afternoon**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Baltimore geologist on-site in the morning to confirm competent saprolite. Crews pumped water into 5 water drums and transferred 5 drums to Fed Property. Crew dumped roll-offs at Fed Property.**
Summary:	**Baltimore geologist on-site in the morning to confirm competent saprolite. Crews pumped water into 5 water drums and transferred 5drums (See Drum Transfer Manifest for IDs) to Fed Property. Crew dumped roll-offs at Fed Property.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**3/1/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg

15 3-1-17

0630 SAFETY BRIEF.

0657 RADIO CHECKS.

0800 TRAFFIC SIGNS IN PLACE. MINI CAMS & BARMS UP.

0823 STARTING TO PUMP WATER FROM EXCAVATION.

0905 DAVID KING W/ USACE ON SITE "GEOLOGIST".

0915 RA-4825 CR-AQ-542 THRU 546 FILLED.

0935 DAVID KING OFF SITE, WE ARE IN SAFE SITE AREAS -40, -70 / -10, -90 / -30, -70 & -90.

0940 STARTING END OF DAY FOR MONITORING. THE TEAMS ARE WORKING @ FED PROPERTY.

1500 SITE SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 02 March 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cool Low 48° High 59°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	Avila, Michelle
Matter, Phil	Prate, Warren	Askey, Tom
Nelms, Bobby	Vail, Todd	PalePale, Mo
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel will collect confirmation samples from grids -10/-70, -10/-90, -30/-70 and -30/-90 then continue excavating east in area B.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY (0)
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**3/2/2017**
Weather:	**Partly Cloudy 31-49°F, wind 0-23 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews collected Confirmation samples from grids (-10, -70), (-10, -90), (-30, -70), and (-30, -90) in Area B and submitted for headspace. 6 composite samples and RA-4825GR-Area B-Grab-02-022317 sent to ECBC via Phillip Matter for low level analysis.**
Summary:	**Crews collected Confirmation samples from grids (-10, -70), (-10, -90), (-30, -70), and (-30, -90) in Area B. 6 composite samples (See Low Level COC for IDs) and RA-4825GR-Area B-Grab-02-022317 sent to ECBC via Phillip Matter for low level analysis.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs
	Daily QC Logs
	UXO Safety Log (Weekly)
	COC
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**3/2/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

16	3-2-17
0630	SAFETY BRIEF.
0711	RADIO CHECKS.
0810	MINICAMS AND DAMMS PUMPS UP.
	THE TEAMS ARE MARKING GRIDS -10,-70/-10,-90
	-30,-70/-30,-90 FOR SAMPLING.
1055	SAMPLING GRID -10,-70. @ DEPTH 6.8 FEET.
1130	GRID -30,-70 SAMPLED @ DEPTH 6.9 FEET.
1141	GRID -30,-90 FLOOR SAMPLE COLLECTED
	DEPTH 6.1 FEET
1152	GRID -10,-90 SAMPLED @ DEPTH 9.1. FEET
1153	STARTING MID DAY CHALLENGE.
1216	MID DAY CHALLENGE COMPLETE.
1312	GRID -10,-90 SIDE WALL SAMPLE # 1 COMPLETE.
	@ 8.3 FEET,
1317	GRID -10-90 SIDE WALL SAMPLE #2 COMPLETE @ 4.0 FEET.
1335	GRID -10-90 SIDE WALL # 3 COMPLETE @ 6 INCHES.
1341	GRID -30-90 SIDE WALL # 1 COMPLETE @ 5.4 FEET.
1352	GRID -30-90 SIDE WALL # 2 COMPLETE @ 2.7 FEET
1403	GRID -30-90 SIDE WALL # 3 COMPLETE 6 INCHES.
1503	STARTING END OF DAY/WEEK CHECKS.
1710	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 06 March 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and cool Low 30° High 54°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Bobal, Brandon
Matter, Phil	Prate, Warren	Askey, Tom
Nelms, Bobby	Vail, Todd	PalePale, Mo
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Surveyors from CP Johnson collected boundary and elevation points from the area excavated from grids -10/-70, -10/-90, -30/-70 and -30/-90. Personnel from ACI came to the site to coordinate the temporary installation of the AC units for the 4835 residence. Personnel began to backfill grids -10/-70, -10/-90, -30/-70 and -30/-90.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**3/6/2017**
Weather:	**Sunny 33-54ºF, wind 0-8 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews backfilled grids (-10, -70), (-10, -90), (-30, -70), and (-30, -90) in Area B. Sent Grab Sample 1 to APPL for analysis. Sent 3 composite and 7 VOC samples to APPL for waste characterization. Shipped one truckload of cleared soil to Subtitle D Landfill.**
Summary:	**Crews backfilled grids (-10, -70), (-10, -90), (-30, -70), and (-30, -90) in Area B. Sent Grab Sample 1(RA-4825GR-Area B-Grab 01-022317) to APPL for analysis. Sent 3 composite and 7 VOC samples to APPL for waste characterization (See COC for IDs). Shipped one truckload of cleared soil to Subtitle D Landfill.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**3/6/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



17 3-6-17
0630 SAFETY BRIEF.
0700 RADIO CHECKS.
0730 CPT IN SITE.
1800 TRAFFIC SIGNS IN PLACE.
0825 MINICAMS AND BOOMS UP.
0850 PUMPING WATER FROM EXCAVATION.
1010 "3"AQ BARRELS FILLED
1053 BACKFILLING EXCAVATION.
1159 STARTING END OF DAY CHECKS FOR MONITORING
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 07 March 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and mild Low 50° High 62°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Bobal, Brandon
Matter, Phil	Prate, Warren	Askey, Tom
Nelms, Bobby	Vail, Todd	PalePale, Mo
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel dumped five roll off boxes of cleared soil at the federal property site. Three loads of soil were sent to the subtitle D landfill. Additional shrubbery and fence panels were removed at the 4825 Glenbrook site. Team began excavation of grid 10/-90 in are B. An electrician from E.C. Ernst worked at the federal property site making repairs to breakers and lights.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**3/7/2017**
Weather:	**Cloudy 49-66°F, wind 0-12mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews took down fence panels and repaired a small section of fence. Dumped roll-offs at Fed Property. Excavated in Grid (10, -90). Shipped 3 truckloads of cleared soil to Subtitle D Landfill. Sent 11 confirmation samples to ECBC for low level analyis. Transferred 3 water drums to Fed Property. Collected glass and submitted for headspace.**
Summary:	**Crews took down fence panels and repaired a small section of fence. Dumped roll-offs at Fed Property. Excavated in Grid (10, -90). Shipped 3 truckloads of cleared soil to Subtitle D Landfill. Sent 11 confirmation samples to ECBC for low level analyis (See COCs for IDs). Transferred 3 water drums to Fed Property (See Drum Transfer Manifest for IDs). Collected glass and submitted for headspace (RA-4825GR-SCR-488).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**3/7/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**


SAFETY BRIEF.
CHECKS.
SIGNS IN PLACE.
AND DAAMS UP.
BARBER & DAN NOBLE ON SITE.
ON SITE W/ STAFF.
MIDDAY CHALLENGE.
CHALLENGE COMPLETE.
DOUBLE BAGGED 1.5 Bs GLASS.
END OF DAY CHECKS.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 08 March 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and mild Low 53° High 66°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Bobal, Brandon
Matter, Phil	Prate, Warren	Askey, Tom
Nelms, Bobby	Vail, Todd	PalePale, Mo
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Naum, Marin

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel continued to backfill grids -10/-70, -10/-90, -30/-70 and -30/-90 then resumed excavation of grid 10/-90.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**3/8/2017**
Weather:	**Partly Cloudy 43-65°F, wind 0-17 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Personnel continued to backfill grids -10/-70, -10/-90, -30/-70 and -30/-90 then resumed excavation of grid 10/-90.**
Summary:	**Personnel continued to backfill grids -10/-70, -10/-90, -30/-70 and -30/-90 then resumed excavation of grid 10/-90.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**3/8/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg 19

3.8.17

0630 ~~RADIO CHECKS~~ SAFETY BRIEF.
0700 RADIO CHECKS.
0741 MINICAMS UP.
0800 DAAMS PUMPS RUNNING
0830 BACKFILLING EXCAVATION.
1145 MID DAY CHALLENGE.
1234 MID DAY CHALLENGE COMPLETE
1530 START UP C. END OF DAY CHECKS.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 09 March 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and mild Low 43° High 62°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Bobal, Brandon
Matter, Phil	Prate, Warren	Askey, Tom
Nelms, Bobby	Vail, Todd	PalePale, Mo
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued to excavate in grid 10/-90.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY (0)
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**3/9/2017**
Weather:	**Partly Cloudy 43-65°F, wind 0-17 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews excavated in Area B and filled one roll-off. One composite and VOC sample were collected and submitted for headspace.**
Summary:	**Crews excavated in Area B and filled one roll-off. One composite and VOC sample were collected and submitted for headspace (RA-4825GR-Area B-01-030917). Crews ensured erosion and sediment controls were in place in anticipation of weekend storms.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**3/9/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



Pg	
20	3-9-17
0630	SAFETY BRIEF. DOUG ZIMMER EXPRESSED CONCERNS ABOUT UNKNOWN PARTICULATE IN THE AIR. I WILL CONTACT OUR CIH ED GRUWALD,
0730	RADIO CHECKS.
0800	TRAFFIC SIGN IN PLACE DAAMS UP.
0823	MINICAMS UP. STARTING INTRUSIVE OPERATIONS.
0953	VOC COLLECTED, FILLING ROLLOFF 274169.
1100	CONFERENCE CALL.
1108	COMPOSITE SAMPLE COLLECTED. ROLLOFF 274169 FULL.
1126	ROLLOFF 274169 OFF SITE.
1146	ROLLOFF 279888 ON SITE.
1148	STARTING MID DAY CHALLENGE
1231	MID DAY CHALLENGE COMPLETE
1417	STARTING END OF DAY/WEEK CHECKS.
1442	TWO WEEK LOOK AHEAD.
1600	SECURED.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 13 March 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and Cold Low 27° High 44°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Burrell, Dianne
Matter, Phil	Prate, Warren	Askey, Tom
Nelms, Bobby	Vail, Todd	PalePale, Mo
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel installed 4 inch flexible pipe to the gutters on the 4835 property. We continued excavation of grid 10/-90. ACI, our plumbing contractor come on site to fix a leak in the water line to the 4835 property.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report	
Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**3/13/2017 Monday**
Weather:	**Partly Cloudy 33-44 °F, wind 0-12 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews prepared for winter storm event. Crews transferred 3 drums to Federal Property (1 water, 1 PPE, and 1 Soil drum).**
Summary:	**Crews prepared for winter storm event. Crews transferred 3 drums (1 water, 1 PPE, and 1 Soil drum) to Federal Property (See COC for IDs).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs
	Daily QC Logs
	UXO Safety Log (Weekly)
	COC
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**3/13/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



Pg

21 3-13-17

0630 SAFETY BRIEF

0700 RADIO CHECKS

0800 TRAFFIC SIGNS UP. BAAMS PUMPS RUNNING.

0820 MINICAMS UP.

0910 PPE DRUM 379, AQ DRUM 521, FSU DRUM 1031 LOADED FOR FED PROPERTY.

1000 CONFERENCE CALL, DISCUSSED CONFIRMATION SAMPLE RESULTS.

1140 STARTING MID DAY CHALLENGE. NOTE; ED GRUNWALD ON SITE @ 10:47

1236 MINICAMS UP.

1508 MINICAMS REPORT 0.43 FOR MUSTARD. TAE HAVE CLEARED THE EXCLUSION ZONE.

1516 MINICAMS 2nd CYCLE 0.51 FOR MUSTARD.

1526 MINICAMS 3rd CYCLE 0.61 FOR MUSTARD.

1536 MINICAMS 4th CYCLE 0.01 FOR MUSTARD.

1540 STARTING END OF DAY CHECKS. NOTE: ACI ON SITE @ 3:00 TO REPAIR 4835 WATERLINE.

1650 ACI COMPLETED REPAIR AND LEFT SITE.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 15 March 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and Cold Low 22° High 32°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Burrell, Dianne
Matter, Phil	Prate, Warren	McCoy, Bill
Nelms, Bobby	Vail, Todd	PalePale, Mo
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel Performed snow and ice removal at the 4825 and federal property sites. They also worked at the federal property site boxing filters for shipment to the incinerator.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**3/15/2017 Wednesday**
Weather:	**Cloudy 21-30 °F, wind 0-25 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Sent one sample to ECBC for low level analysis. Crews performed snow and ice removal at both the 4825 Glenbrook Rd and Federal Property sites. Crews boxed filters in preparation for shipment to the incinerator.**
Summary:	**Sent one sample (RA-4825GR-Area B-01-030917) to ECBC for low level analysis. Crews performed snow and ice removal at both the 4825 Glenbrook Rd and Federal Property sites. Crews boxed filters in preparation for shipment to the incinerator.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**3/13/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



Pg

23	3-15-17
0630	SAFETY BRIEF.
0700	RADIO CHECKS ED GRUNWALD IN SITE.
1130	ED GRUNWALD OFF SITE.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 16 March 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and Cold Low 28° High 37°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Burrell, Dianne
	Prate, Warren	McCoy, Bill
Nelms, Bobby	Vail, Todd	PalePale, Mo
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Vargas, Gustavo
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued to excavate in grid 10/-90. The team took samples of black material and drummed the remainder of material and associated soil in a 30 gal poly drum. Personnel also collected a grab sample from the area where the black substance came from.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**3/16/2017 Thursday**
Weather:	**Partly Cloudy 25-40 °F, wind 0-17 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crew excavated in Area B (-10, -90). Crew encountered unknown substance. Took Grab samples of unknown substance and surrounding soil. Submitted samples for headspace. Sent 1 composite and 1 VOC sample to APPL for waste characterization. Collected glass and submitted for headspace (RA-4825GR-SCR-489).**
Summary:	**Crew excavated in Area B (-10, -90). Crew encountered unknown substance. Took Grab samples of unknown substance and surrounding soil (See Headspace COC for IDs). Submitted samples for headspace. Sent 1 composite (RA-4825GR-Area B-01-030917) and 1 VOC (RA-4825GR-Area B-VOC-030917-01) sample to APPL for waste characterization. Collected glass and submitted for headspace(RA-4825GR-SCR-489).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**3/16/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg	
24	3-16-17
0630	SAFETY BRIEF.
0700	RADIO CHECKS.
0800	TRAFFIC SIGNS IN PLACE. DAAMS PUMPS RUNNING.
0805	MINICAMS UP. THE TEAMS ARE WORKING INTRUSIVE.
1100	CONFERENCE CALL.
1125	THE DOWN RANGE TEAM REPORTS FINDING A BLACK SUBSTANCE W/ BROKEN GLASS. THE DIG WAS MITIGATED AND MINICAMS ARE MONITORING.
1201	3 COMPLETE CYCLES NON DETECT. STARTING MIDDAY CHALLENGE. NOTE: THE CONFERENCE CALL WAS INFORMED ABOUT THIS FIND. A SAMPLE FOR HEAD SPACE WILL BE COLLECTED AND THE REMAINING SUBSTANCE WILL BE DRUMMED.
1231	MINICAMS BACK UP.
1340	THE "A" POINT PLACED UNDER THE MITIGATED SUBSTANCE.
1400	TWO CLEAR CYCLES.
1410	GRAB SAMPLE #3 COLLECTED "BLACK SUBSTANCE".
1458	GRAB SAMPLE #4 COLLECTED "SOIL".
1531	SCR-489 DOUBLE BAGGED "GLASS" 2.16 S.
	PDT CALL
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 20 March 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and Mild Low 38° High 57°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	DeLaPaz, Hector
Matter, Phil		McCoy, Bill
Nelms, Bobby	Vail, Todd	Dusick, Brandon
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel Filled a roll off box with staged soil. Parsons personnel transported the black substance to Edgewood Arsenal for low level agent screening. The crew began removing backfill soil from -10/-90 and -10/-90 in preparation for resampling.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**3/20/2017 Monday**
Weather:	**Cloudy 42-53 °F, wind 0-6 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Sent Grab Sample 3 (RA-4825GR-Area B-Grab-03-031617) to ECBC for low level analysis. Crew excavated in Area B (-10, -90) and collected one composite and VOC sample. Submitted sample for headspace. Crews moved clean fill.**
Summary:	**Sent Grab Sample 3(RA-4825GR-Area B-Grab-03-031617) to ECBC for low level analysis. Crew excavated in Area B (-10, -90) and collected one composite and one VOC sample. Submitted sample (RA-4825GR-Area B-01-032017) for headspace. Crews moved clean fill.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**3/20/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



Pg.	
25	3-20-17
0630	SAFETY BRIEF.
0701	RADIO CHECKS. ECBC MAINTAINS AT FED PROPERTY. BRNST AT FED PROPERTY.
0800	TRAFFIC SIGNS IN PLACE. DAAMS PUMPS RUNNING.
0815	MINI CAMS UP.
0946	VOC COLLECTED. FILLING Roll off 279888.
1103	Roll off 279888 IS FULL AND COMPOSITE CHECKED
1148	STARTING MID DAY CHALLENGE.
1152	Roll off 279888 IS OFF SITE.
1258	MID DAY CHALLENGE COMPLETE
1435	MINI CAMS REPORTS ALARM FOR NH3 STAYED 0.87 THE TRUCKS WERE NOT INTRUSIVE, ONLY MOVING CLEAN THICK FILL.
1439	MINI CAMS REPORTS ALL CLEAR
1449	MINI CAMS REPORTS ALL CLEAR.
1513	STARTING END OF DAY CHECKS.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 21 March 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and Mild Low 41° High 59°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	DeLaPaz, Hector
Matter, Phil	Prate, Warren	McCoy, Bill
Nelms, Bobby	Vail, Todd	Dusick, Brandon
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel swapped out two IHF containers at the federal property site. The MINICAMS shed at the 4825 was also swapped out.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**3/21/2017 Tuesday**
Weather:	**Cloudy 37-63 °F, wind 0-8 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Sent Grab Sample 4 (RA-4825GR-Area B-Grab-04-031617) to ECBC for low level analysis. Crane operations at Fed Property for IHF moving. Swapped out MINICAMs shed. Continued working on inventory at Fed Property.**
Summary:	**Sent Grab Sample 4 (RA-4825GR-Area B-Grab-04-031617) to ECBC for low level analysis. Crane operations at Fed Property for IHF moving. Swapped out MINICAMs shed. Continued working on inventory at Fed Property.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**3/21/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg

26 3-21-17

0630 SAFETY BRIEF

0750 RADIO CHECKS. GRUBB ECBC AND WILLIAMS ELECTRIC ARE AT FED SITE. STARTING CRANE SET UP.

0830 SAFETY BRIEF FOR CRANE OPS. WILLIAMS ELECTRIC COMPLETED JHF ALARM DISCONNECT AND OFF SITE.

0840 STARTING CRANE OPS.

1130 JHFS REPLACED AND CRANE OPS COMPLETE GRUBB OFF SITE.

1500 ECBC MAINTENANCE OFF SITE.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 22 March 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and Mild Low 42° High 48°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	DeLaPaz, Hector
Matter, Phil	Prate, Warren	McCoy, Bill
Nelms, Bobby	Vail, Todd	Dusick, Brandon
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Subcontractors worked at the federal property site to install the Intrusion detection system and lightning protection system on the new IHF containers. Parsons personnel continued removing backfill soil from -10/-90 and -10/-90 in preparation for resampling.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**3/22/2017 Wednesday**
Weather:	**Sunny 24-45 °F, wind 0-17 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Re-arranged hazardous waste storage area at Fed Property. Installed lighting protection system and intrusion detection system on the IHF. Crews moved clean fill at 4825 Glenbrook Road Site.**
Summary:	**Re-arranged hazardous waste storage area at Fed Property. Installed lighting protection system and intrusion detection system on the IHF. Crews moved clean fill at 4825 Glenbrook Road Site.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**3/22/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



R

27 3-22-17

0630 SAFETY BRIEF

0650 RADIO CHECKS

0780 ERNST & WILLIAMS ELECTRIC @ FED PROPERTY WORKING ON THE PADS

0800 MOVING CLEAN BACKFILL. THE TEAM IS ALSO MOVING WATER DRUMS AT FED SITE.

1350 ERNST AND WILLIAMS ELECTRIC OFF SITE.

1700 SECURED.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 23 March 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and Mild Low 48° High 52°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	
Matter, Phil	Prate, Warren	
Nelms, Bobby	Vail, Todd	Dusick, Brandon
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

ECBC personnel came to smoke test the new IHF containers, part of the test could not be performed due to weather. Parsons personnel worked at the federal property site dumping roll off boxes.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**3/23/2017 Thursday**
Weather:	**Sunny30-48 °F, wind 0-5 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Sent one sample to ECBC for low level analysis (RA-4825GR-Area B-01-032017). Williams Electric onsite for installing Intrusion Detection System at IHF. EC Ernst onsite to work on lightning protection system. ECBC onsite to work on IHF. Crews dumped cleared roll-offs at Fed Property.**
Summary:	**Sent one sample to ECBC for low level analysis (RA-4825GR-Area B-01-032017). Williams Electric onsite for installing Intrusion Detection System at IHF. EC Ernst onsite to work on lightning protection system. ECBC onsite to work on IHF. Crews dumped cleared roll-offs at Fed Property.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**3/23/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



Pg

28 3-23-17

0630 SAFETY BRIEF

0700 RADIO CHECKS. TEAMS WORKING @ FED PROPERTY.

0925 ECBC AT FED PROPERTY FOR SMOKE TEST.

1100 CONFERENCE CALL. CONCERNS ABOUT PPE COVER. WE WILL MEET W/ ED COMMAND FOR ADVICE.

1300 WILLIAMS ELECTRIC AT FED PROPERTY. WORKING ON ALARM SYSTEM FOR IHF'S. ECBC OFF SITE. SMOKE TEST WAS NOT COMPLETED.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 27 March 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and Mild Low 50° High 73°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	DeLaPaz, Hector
Matter, Phil	Prate, Warren	Elliot, Laura
Nelms, Bobby	Vail, Todd	Lewis, Leon
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel backfilled grids and began construction of the temporary pad for the AC units. They also continued dumping roll off boxes at the federal property site.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**3/27/2017 Monday**
Weather:	**Cloudy in the morning, sunny in the afternoon 46-76 °F, wind 0-5 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Sent two samples to APPL for disposal characterization (RA-4825GR-Area B-01-032017 and RA-4825GR-Area B-VOC-032017-01). Crews dumped cleared roll-offs at Fed Property. Crews began working on the temporary pad for the AU President's AC Units.**
Summary:	**Sent two samples to APPL for disposal characterization (RA-4825GR-Area B-01-032017 and RA-4825GR-Area B-VOC-032017-01). Crews dumped cleared roll-offs at Fed Property. Crews began working on the temporary pad for the AU President's AC Units.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**3/27/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



Pg

29	3-27-17
0630	SAFETY BRIEF.
0700	RADIO CHECKS.
0800	TRAFFIC SIGNS IN PLACE
0830	SGAH BUCKLEY ON SITE.
1130	SGAH BUCKLEY OFF SITE.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 28 March 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and Mild Low 53° High 68°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	DeLaPaz, Hector
Matter, Phil	Prate, Warren	Elliot, Laura
Nelms, Bobby	Vail, Todd	Lewis, Leon
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel backfilled grids and began construction of the temporary pad for the AC units. They also continued dumping roll off boxes at the federal property site.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**3/28/2017 Wednesday**
Weather:	**Mostly Cloudy 57-64 °F, wind 0-5 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews finished constructing the temporary pad for the AC Units. Crews dump cleared roll-offs at Fed Property.**
Summary:	**Crews finished constructing the temporary pad for the AC Units. Crews dump cleared roll-offs at Fed Property.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**3/28/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg

30	3-28-17
0630	SAFETY BRIEF
0700	RADIO CHECKS.
0800	TRAFFIC SIGNS IN PLACE.
0840	LIGHTING HOLD.
1015	OFF LIGHTNING HOLD.
1132	AQ 8 DRUM 550, PPE DRUM 380, AND
	FSW DRUM 1032 LOADED FOR FED PROPERTY.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 29 March 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and Mild Low 56° High 68°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	DeLaPaz, Hector
Matter, Phil	Prate, Warren	Elliot, Laura
Nelms, Bobby	Vail, Todd	Lewis, Leon
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Subcontractors From ACI began the installation of the AC units in the temporary location. Electricians from E.C. Ernst continued installation of the lightning protection system on the IHF containers. Parsons and Zimmer personnel assisted getting the AC units in place on the temporary pad. They also continued dumping roll off boxes at the federal property site and loaded trucks with cleared soil going to the sub-title D landfill.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**3/29/2017 Wednesday**
Weather:	**Sunny 35-69 °F, wind 0-10 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**ACI on-site for hooking up air conditioning units. Crews dumped cleared roll-offs at Fed Site. Shipped cleared soil to Subtitle D Landfill.**
Summary:	**ACI on-site for hooking up air conditioning units. Crews dumped cleared roll-offs at Fed Site. Shipped cleared soil to Subtitle D Landfill.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**3/29/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



Pc

31	3-29-17
0630	SAFETY BRIEF.
0700	ERNST ELECTRIC AT FEB PROPERTY
	WORKING ON IHF'S LPS.
0756	TRAFFIC SIGNS IN PLACE
0945	ACI ON SITE FOR 4835 AC INSTALL.
1400	ERNST ELECTRIC OFF SITE
1500	ACI OFF SITE.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 30 March 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and Mild Low 46° High 56°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	DeLaPaz, Hector
Matter, Phil	Prate, Warren	Elliot, Laura
Nelms, Bobby	Vail, Todd	Lewis, Leon
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Subcontractors From ACI will continue the installation of the AC units in the temporary location. EC Ernst finished installation of lightning protection and certification of IHF. Sampled water drums for disposal characterization. Collected 2 samples. Crews dumped cleared roll-offs at Fed Property.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**3/30/2017 Thursday**
Weather:	**Cloudy 44-54 °F, wind 0-9 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**ACI on-site for hooking up air conditioning units. EC Ernst finished installation of lightning protection and certification of IHF. Sampled water drums for disposal characterization. Collected 2 samples (RA-4825GR-IDW-(475-520)-033017 and RA-4825GR-IDW-(522-549)-033017. Crews dumped cleared roll-offs at Fed Property.**
Summary:	**ACI on-site for hooking up air conditioning units. EC Ernst finished installation of lightning protection and certification of IHF. Sampled water drums for disposal characterization. Collected 2 samples (RA-4825GR-IDW-(475-520)-033017 and RA-4825GR-IDW-(522-549)-033017. Crews dumped cleared roll-offs at Fed Property.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**3/30/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg	
32	3-30-17
0630	SAFETY BRIEF.
0700	ERNST AT FED PROPERTY, WORKING ON JMF LDS.
0730	ACI ON SITE WORKING TO INSTALL AC UNITS FOR 4885.
1100	CONFERENCE CALL.
1140	CONFERENCE CALL COMPLETE
1450	ERNST ELECTRIC COMPLETE LPS INSTALLATION AND MEGGER CHECKS.
1450	ACI OFF SITE.
1520	TWO WEEK LOOK AHEAD. THE AH WATER FOR THE ATHERIC FIELD WAS TURNED ON.
1700	SECURED.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 03 April 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and Mild Low 48° High 61°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Druyor, Chris
Matter, Phil	Prate, Warren	Nichols, Doug
Nelms, Bobby	Vail, Todd	Lewis, Leon
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Hatcher, Charles

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Subcontractors From ACI will continue the installation of the AC units in the temporary location. Crews dumped cleared roll-offs at Fed Property. UXOQC Worked on equipment inventory.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**4/3/2017 Monday**
Weather:	**Partly Cloudy 55-67°F, wind 0-6 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Conducted training on Thermo Scientific ADR 1500 dust monitor. Sent drum samples to ECBC for low level analysis. Pumped water from rain event. Transferred water drums to Fed Property. ACI on-site to set up air conditioning units at 4835 residence.**
Summary:	**Conducted training on Thermo Scientific ADR 1500 dust monitor. Sent drum samples to ECBC for low level analysis (See COC) . Pumped water from rain event. Transferred water drums to Fed Property. ACI on-site to set up air conditioning units at 4835 residence.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**4/3/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



Pg
33 43-17
0630 SAFETY BRIEF.
0750 RADIO CHECKS.
0888 MINICAMS UP. TRAFFIC SIGNS IN PLACE.
0901 DAAMS PUMPS RUNNING.
1009 WATER DRUMS 551 THRU 555 TO FED PROPERTY.
1015 ACI ON SITE
1200 STARTING MID DAY CHALLENGE
1238 MID DAY COMPLETE
1500 ACI OFF SITE.
1510 STARTING END OF DAY CHECKS.
1520 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 04 April 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and warm Low 55° High 64°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Druyor, Chris
Matter, Phil	Prate, Warren	Nichols, Doug
Nelms, Bobby	Vail, Todd	Lewis, Leon
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel conducted training on Thermo Scientific ADR 1500 dust monitor. Subcontractors from ACI completed the installation of the AC units in the temporary location. Parsons personnel continued property inventory. Zimmer personnel loaded and sent four loads of soil to the sub-title D landfill.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**4/4/2017 Tuesday**
Weather:	**Partly Sunny 56-76°F, wind 0-7 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**ACI on-site to set up air conditioning units at 4835 residence. Crews working on Fed Property**
Summary:	**ACI on-site to set up air conditioning units at 4835 residence. Crews working on Fed Property**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**4/4/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



Pg
34 #417
0630 SAFETY BRIEF.
0744 MINICAMS UP.
0845 ACI ON SITE.
0932 AMERICAN UNIVERSITY RESTORATION TEAM ON SITE.
1150 STARTING END OF DAY CHECKS FOR MINICAMS.
1435 ACI completed AIC units & departs site, Mr. Courtney closes up down below.
1530 Remainder of TM1 returns from Fld Prep. Secure all gear from down below, prepare tool & equipment for tomorrow
1700 End of day, all secure.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 05 April 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and warm Low 53° High 67°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Druyor, Chris
Matter, Phil	Prate, Warren	Nichols, Doug
	Vail, Todd	Lewis, Leon
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel resumed excavation of area B in grid 10/-90. More of the black substance was found and mitigated. After MINICAMMS alarms the substance was sampled with DAAMS tubes and analyzed, the samples came back as non-detect. A PDT call was conducted and ECBC will collect samples of the substance for lab analyses on Friday.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**4/5/2017 Wednesday**
Weather:	**Sunny 58-70°F, wind 0-5 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**MiniCAMMS detection for Mustard that was later cleared by DAAMs.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews excavating in grid (10, -90). Encountered unknown substance, performed air monitoring and mitigated.**
Summary:	**Crews excavating in grid (10, -90). Encountered unknown substance, performed air monitoring and mitigated.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**4/5/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pa

35 4-5-2017 Wednesday

0630 Daily safety + ops briefings, review 10 probability procedures.

0749 Mini CAMS up.

0800 DAMMS + our point monitors are up. Taking dust monitor + vibration monitors down range

0825 Team Beginning to pump water from excavation area

0845 Vibration Monitors are Running

0850 Water Pumping Complete Drum 556 filled + Transported to ~~Fd~~ Fed site.

0900 Began Intrusive operations

0930 Team is finding AVES Glass.

1035 Excavation team found black material like the previous mustard Heel, Team is mitigating.

1005 Began first cycle minicams.

1100 First cycle clear

1110 Second cycle clear.

1120 third cycle clear. Begin midday challenge.

1300 Team will Put A point under mitigation and Run cycles.

1310 Beginning 1st minicams cycle.

1320 First Cycle clear, Beginning 2nd.

1330 Second cycle clear, Beginning 3 RD.

1340 Third cycle clear, Team Repositioning A point under mitigation.

1350 Beginning 1st cycle.

1400 First Cycle HD 2.14. Running 2nd.

1410 Second Cycle Clear.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 06 April 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and warm Low 55° High 66°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Druyor, Chris
Matter, Phil	Prate, Warren	Nichols, Doug
Nelms, Bobby		Lewis, Leon
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Vargas, Brandon

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel collected suppliers and equipment then prepared the area for the ECBC sampling team. ECBC will collect samples of the black substance on 4-7-17.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**4/6/2017 Thursday**
Weather:	**Thunderstorms and heavy rain 48-62°F, wind 0-4 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**None**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews encountered delays due to lightening holds from thunderstorms and severe rain event in the area. Crews filled drum (4825GR-RDW-AQ-556) with decon water.**
Summary:	**Crews encountered delays due to lightening holds from thunderstorms and severe rain event in the area. Crews filled drum (4825GR-RDW-AQ-556) with decon water.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**4/6/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



PG	
37	4-6-17
0630	SAFETY BRIEF
0715	RADIO CHECKS.
0735	MINICAMS UP.
0827	LIGHTNING HOLD
0940	OFF LIGHTNING HOLD.
1030	LIGHTNING HOLD
1100	CONFERENCE CALL
1135	CONFERENCE CALL COMPLETE.
1145	STARTING MIDDAY CHALLENGE.
1218	MIDDAY CHALLENGE COMPLETE.
1328	OFF LIGHTNING HOLD.
1332	LIGHTNING HOLD.
1500	OFF LIGHTNING HOLD. STARTING
	END OF DAY CHECKS.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 10 April 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and warm Low 55° High 86°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Druyor, Chris
Matter, Phil	Prate, Warren	Nichols, Doug
Nelms, Bobby	Vail, Todd	Heard, Irvin
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel used the jackhammer to demo the concrete stairs and brick façade in grid 50/-70. The rubble was loaded into a roll off box and transported to the federal property site.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**4/10/2017 Monday**
Weather:	**Sunny 61-78°F, wind 0-6 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**None**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews jackhammered the wall in grids (50, -70) and (50, -90). Loaded rubble into roll-off. Reorganized EPDS.**
Summary:	**Crews jackhammered the wall in grids (50, -70) and (50, -90). Loaded rubble into roll-off. Reorganized EPDS.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**4/10/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



Pg

39 4-10-17

0630 SAFETY BRIEF.

0750 RADIO CHECKS.

0757 MINI CAMS UP.

0800 DAAMS PUMPS RUNNING.

1044 STARTING HYDRAULIC HAMMER OPERATIONS.

1130 HYDRAULIC HAMMER OPS STOPPED.

1155 ROLL OFF 274314 ON SITE.
STARTING MID DAY CHALLENGE.

1223 MID DAY CHALLENGE COMPLETE.

1240 FILLING ROLL 274314 W/ RUBBLE.

1500 ROLLOFF 274314 IS FULL

1508 ROLL OFF 274314 OFF SITE.

1530 STARTING END OF DAY CHECKS.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 11 April 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and warm Low 61° High 76°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Druyor, Chris
Matter, Phil	Prate, Warren	Nichols, Doug
Nelms, Bobby	Vail, Todd	Heard, Irvin
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel excavated area B in grids 50/-70 and 50/-90. Soil was inspected and staged for removal.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**4/11/2017 Tuesday**
Weather:	**Sunny 63-84°F, wind 0-3 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**None**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews excavated behind the retaining all in grids (50, -70) and (50, -90). Crews collected glass fragments and submitted for headspace.**
Summary:	**Crews excavated behind the retaining all in grids (50, -70) and (50, -90). Crews collected glass fragments and submitted for headspace(RA-4825GR-SCR-490 and RA-4825GR-SCR-491).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**4/11/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg
40 4-11-17
0630 SAFETY BRIEF.
0755 RADIO CHECKS, TRAFFIC SIGN IN PLACE.
0810 BAAMS PUMPS RUNNING
0818 MINICAMS UP.
0825 TEAM REPORTS HANDING OFF IN CAVITY TEST TUBE ½" DIA, 5" LONG. WITH GREEN RESIDUE
1035 MINI CAMS REPORTS 1.4 FOR CG "PHOSGENE"
1041 MINICAMS REPORTS 2 CLEAN CYCLES.
1217 STARTING MID DAY CHALLENGE.
1534 MINICAMS REPORTS CK @ 2.89 ALL TEAM ARE/WERE OUT OF THE EXCLUSION ZONE.
1537 MINICAMS READ ZERO.
1539 SCR 490 DOUBLE BAGGED "GLASSIB"
SCR 491 DOUBLE BAGGED "OPEN CAVITY TEST TUBE"
1544 STARTING END OF DAY CHECKS.
NOTE: MINI CAMS UP @ 13:17 AFTER MID DAY CHALLENGE.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 12 April 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and warm Low 53° High 77°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Druyor, Chris
Matter, Phil	Prate, Warren	Nichols, Doug
Nelms, Bobby	Vail, Todd	Heard, Irvin
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel began cutting the concrete pad that the AC units were located on the 4835 property. Personnel also loaded staged soil into roll off boxes and transported them to the federal property site.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY (0)
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**4/12/2017 Wednesday**
Weather:	**Sunny 55-75°F, wind 0-5 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**None**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews excavated behind the retaining all in grids (50, -70) and (50, -90). Crews filled two roll-offs. 2 composite(RA-4825GR-Area B-01-041217 and RA-4825GR-Area B-02-041217) and 2 VOC samples (RA-4825GR-Area B-VOC-041217-01 and RA-4825GR-Area B-VOC-041217-02) were collected and submitted for headspace.**
Summary:	**Crews excavated behind the retaining wall in grids (50, -70) and (50, -90). Crews filled two roll-offs. 2 composite(RA-4825GR-Area B-01-041217 and RA-4825GR-Area B-02-041217) and 2 VOC samples (RA-4825GR-Area B-VOC-041217-01 and RA-4825GR-Area B-VOC-041217-02) were collected and submitted for headspace.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs
	Daily QC Logs
	UXO Safety Log (Weekly)
	COC
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**4/12/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



Pg	
41	4-12-17
0630	SAFETY BRIEF.
0715	RADIO CHECKS.
0750	TRAFFIC SIGNS IN PLACE
0758	MINICAMS UP
0800	DAAMS PUMPS RUNNING.
0815	CUTTING RETAINING WALL w/ CIRCULAR SAW.
0930	STOP SAW OPERATION DUE TO COMPLAINT OF GASOLINE SMELL.
1000	ROLL OFF 274308 ON SITE.
1024	VOC COLLECTED.
1103	ROLLOFF 274308 IS FULL AND COMPOSITE COLLECTED
1118	ROLLOFF 274308 OFF SITE.
1139	ROLLOFF 279892 ON SITE.
1149	STARTING MID DAY CHALLENGE.
1159	MID DAY CHALLENGE COMPLETE.
1241	VOC COLLECTED FILLING ROLL OFF 279892
1330	ROLLOFF 279892 IS FULL AND COMPOSITE COLLECTED
1344	ROLLOFF 279892 OFF SITE.
1543	STARTING END OF DAY CHECKS.
	I SENT ED GRANWALD LOG ENTRIES FOR THE DAYS WE HAD MINICAMS ~~ALARMS~~ ON RING OFFS.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 13 April 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and warm Low 53° High 68°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Druyor, Chris
Matter, Phil	Prate, Warren	Nichols, Doug
Nelms, Bobby	Vail, Todd	Heard, Irvin
Oien, Joshua	Yorkshire, Bart	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel continued excavating area B in grids 50/-70 and 50/-90. They also continued cutting the concrete pad that the AC units were located on the 4835 property.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**4/13/2017 Thursday**
Weather:	**Sunny 54-69°F, wind 0-3 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**None**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews excavated behind the retaining all in grids (50, -70) and (50, -90). Crews filled 2 roll-offs and collected 2 composite (RA-4825GR-Area B-01-041317 and RA-4825GR-Area B-01-041317) and VOC (RA-4825GR-Area B-VOC-041317-01 and RA-4825GR-Area B-VOC-041317-02) samples. Submitted samples for headspace. Collected glass and submitted for headspace (RA-4825GR-SCR-493). Transferred 2 water drums, 2 PPE drums, and scrap to Federal Property (See Drum Transfer Manifest for IDs).**
Summary:	**Crews excavated behind the retaining all in grids (50, -70) and (50, -90). Crews filled 2 roll-offs and collected 2 composite (RA-4825GR-Area B-01-041317 and RA-4825GR-Area B-01-041317) and VOC (RA-4825GR-Area B-VOC-041317-01 and RA-4825GR-Area B-VOC-041317-02) samples. Submitted samples for headspace. Collected glass and submitted for headspace (RA-4825GR-SCR-493). Transferred 2 water drums, 2 PPE drums, and scrap to Federal Property (See Drum Transfer Manifest for IDs).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**4/13/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg

42 4-13-17
0630 SAFETY BRIEF.
0700 RADIO CHECKS.
0745 ~~DAAMS PUMPS RUNNING~~ MINI CAMS UP.
0800 DAAMS PUMPS RUNNING
0810 TRAFFIC SIGNS IN PLACE.
0843 PPE DRUMS 381 & 382, AQ DRUMS 557 & 558
SCR-492 LOADED FOR FED PROPERTY.
0854 VOC COLLECTED, FILLING ROLLOFF 274544.
0930 PDT CALL CALL
0940 COLLECTED COMPOSITE SAMPLE, ROLLOFF
274544 IS FULL.
0959 ROLLOFF 274544 OFF SITE.
1024 ROLLOFF 279693 ON SITE.
1030 PDT COMPLETE.
1100 CONFERENCE CALL.
1135 MID DAY CHALLENGE
1054 MID DAY CHALLENGE COMPLETE
1331 VOC COLLECTED, FILLING ROLLOFF 279693.
1422 ROLLOFF 279693 IS FULL AND COMPOSITE COLLECTED.
1444 ROLLOFF 279693 OFF SITE. SCR 493
DOUBLE BAGGED "1/8 lb GLASS"
1450 STARTING END OF DAY CHECKS.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 17 April 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and warm Low 68° High 73°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Fortier, James
Matter, Phil	Prate, Warren	Tucker, Robin
Nelms, Bobby	Vail, Todd	Heard, Irvin
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Crews jackhammered the retaining wall in grids (50, -70) and (50, -90). Sorted and loaded rubble onto roll-off. Continued to excavate behind the retaining wall. Collected and submitted glass for headspace (RA-4825GR-SCR-494).

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (0)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**4/17/2017 Monday**
Weather:	**Mostly Cloudy with some rain 57-73°F, wind 0-5 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**None**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews jackhammered the retaining wall in grids (50, -70) and (50, -90). Sorted and loaded rubble onto roll-off. Continued to excavate behind the retaining wall. Sent two samples (RA-4825GR-Area B-01-041217 and RA-4825GR-Area B-02-041217) to ECBC for low level analysis. Collected and submitted glass for headspace (RA-4825GR-SCR-494).**
Summary:	**Crews jackhammered the retaining wall in grids (50, -70) and (50, -90). Sorted and loaded rubble onto roll-off. Continued to excavate behind the retaining wall. Sent two samples (RA-4825GR-Area B-01-041217 and RA-4825GR-Area B-02-041217) to ECBC for low level analysis.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**4/17/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



Pg

43	4-17-17
0630	SAFETY BRIEF
0730	RADIO CHECKS.
0750	TRAFFIC SIGNS IN PLACE MINICAMS UP
0800	DAAMS PUMPS RUNNING.
0843	STARTING HYDRAULIC HAMMER OPS.
0954	MINICAMS REPORTS .87 FORCE.
	THE TEAMS ARE OUT OF THE EXCLUSION ZONE.
0959	MINICAMS REPORTS ALL CLEAR.
1138	ROLL OFF 274823 ET ON SITE
1143	TRAFFIC REPORTS PUBLIC ENTRUST
	IN THE REALIC SUBSTANCE COVERED IN PLASTIC.
	STARTING MID DAY CHALLENGE.
1218	MID DAY CHALENGE COMPLETE.
1427	ROLL OFF 274823 OFF SITE. RUBBLE
1530	POT CALL.
1620	POT CALL OVER.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 19 April 2017
Site Location: 4825 Glenbrook Road

Weather:
Clear and warm Low 58° High 62°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Fortier, James
Matter, Phil	Prate, Warren	Tucker, Robin
Nelms, Bobby	Vail, Todd	Heard, Irvin
	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel loaded previously excavated soil from grids(50, -70) and (50, -90) into rolloffs. Began backfill / mitigation of excavation area. Area is mitigated while the site prepares for level C operations. Collected Grab Sample 8 and submitted for headspace. Collected scrap glassware and submitted for headspace (RA-4825GR-SCR-495).

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY (4)
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**4/19/2017 Wednesday**
Weather:	**Cloudy 58-62°F, wind 0-3 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**None**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews loaded previously excavated soil from grids(50, -70) and (50, -90) into rolloffs. Collected two composite and two VOC samples and submitted for headspace. Collected Grab Sample 8 and submitted for headspace. Collected scrap glassware and submitted for headspace (RA-4825GR-SCR-495). Sent samples to APPL for disposal characterization (see COC for IDs).**
Summary:	**Crews loaded previously excavated soil from grids(50, -70) and (50, -90) into rolloffs. Collected two composite and two VOC samples and submitted for headspace. Collected Grab Sample 8 and submitted for headspace. Collected scrap glassware and submitted for headspace (RA-4825GR-SCR-495). Sent samples to APPL for disposal characterization (see COC for IDs).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**4/19/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg	
46	4.19.17
0630	SAFETY BRIEF.
0750	RADIO CHECKS
0745	MINI CAMS UP.
0800	DAHMS PUMPS RUNNING
0830	ROLLOFF 279655 ON SITE.
0841	VOC COLLECTED FILLING ROLLOFF 279655
1018	COMPOSITE SAMPLE COLLECTED, ROLLOFF FULL.
1025	ROLLOFF 279655 OFF SITE.
1046	ROLLOFF RB-21724RT ON SITE
1102	VOC COLLECTED FILLING ROLLOFF RB21724RT.
1150	COMPOSITE COLLECTED, ROLLOFF IS FULL.
1157	GRAB 8 COLLECTED "METAL BAND W/ BLACK SUBSTANCE"
1200	STARTING MID DAY CHALLENGE.
1213	MID DAY CHALLENGE COMPLETE
1315	ROLLOFF RB21724RT OFF SITE
1403	RA4925GR-SCR-495 DOUBLE BAGGED "GLASS"
1420	THE "A" POINT PLOTED. NEAR EXCAVATED EXCAVATION. ALL CLEAR. STARTING TO BACK FILL EXCAVATION.
1500	STARTING END OF DAY
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 20 April 2017
Site Location: 4825 Glenbrook Road

Weather:
Rainy and warm Low 67° High 80°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Fortier, James
Matter, Phil	Prate, Warren	Tucker, Robin
Nelms, Bobby	Vail, Todd	Heard, Irvin
	Yorkshire, Bart	
Rider, Matthew	Zimmer, Doug	
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

HNCCE and CEBAB personnel came to the site for visit and site walk thru. Parsons and Zimmer personnel completed backfill / mitigation of excavation area. Area is mitigated while the site prepares for level C operations. Personnel also prepped the site for several weeks of non-intrusive operations.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



PL

47 4-20-17

0630 SAFETY BRIEF

0700 RADIO CHECKS

0730 CENAB, CENAC AND ECBC REPRESENTATIVES ON SITE.

0800 SEAN BUCKLEY ON SITE. TRAFFIC SIGNS UP.

0820 MINICAMS UP @ 07:50 DATAMS PUMPS RUNNING @ 08:00

0840 BACKFILLING EXCAVATIONS.

1167 STAKE BED TRUCK ON SITE, LOADING PPE DRUM 383 AND AQ DRUM 559 TO FED PROPERTY. STARTING END OF DAY CHECKS. FOR MONITORING.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 24 April 2017
Site Location: 4825 Glenbrook Road

Weather:
Rainy and warm Low 51° High 56°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	
Matter, Phil	Prate, Warren	
Nelms, Bobby	Vail, Todd	
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons and Zimmer personnel worked at the federal property site packaging old CAFS filters for hazardous waste shipment. Parsons management personnel worked on work plan change pages.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**4/24/2017 Monday**
Weather:	**rain showers 53-58°F, wind 0-5 mph**
Field Instrument:	**None**
Measurements:	**None**
Calibrations:	**None**
Activities Conducted:	**Sent two samples to ECBC for low level analysis. Crews boxed 39 filters at Fed Property.**
Summary:	**Sent two samples (RA-4825GR-Area B-01-041917 and RA-4825GR-Area B-02-041917) to ECBC for low level analysis. Crews boxed 39 filters at Fed Property.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**none**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**4/24/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



Pg
48 4-24-17
0630 SAFETY BRIEF.
0700 RADIO CHECKS. THE TEAMS ARE WORKING @ FED PROPERTY PACKING FILTERS.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 25 April 2017
Site Location: 4825 Glenbrook Road

Weather:
Rainy and warm Low 55° High 59°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	
Matter, Phil	Prate, Warren	
Nelms, Bobby	Vail, Todd	
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Wunschel, Scott		

ACCUPERMIT	CENAB
Schmidt, James	
Williams, Angelo	
	Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons and Zimmer personnel worked at the federal property site packaging old CAFS filters for hazardous waste shipment. Parsons management personnel worked on work plan change pages.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	


Pg
49
4-25-17
0630 SAFETY BRIEF.
0700 RADIO CHECKS. THE TEAM IS WORKING
AT FED PROPERTY ROLLING & PACKING
FILTERS.
1700 End of day all secure.
Nothing follows

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 01 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and warm Low 68° High 79°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	
Matter, Phil		
Nelms, Bobby	Vail, Todd	
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons and Zimmer personnel worked at the federal property site packaging old CAFS filters for hazardous waste shipment. Parsons management personnel worked on work plan change pages.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Sensitive


Pg
52
5-1-17
0630
SAFETY BRIEF
0650
RADIO CHECKS. TEAM WORKING
AT FED PROPERTY!
1750
SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 02 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and warm Low 60° High 75°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	
Matter, Phil	Prate, Warren	
Nelms, Bobby	Vail, Todd	
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Wunschel, Scott		
	ACCUPERMIT	
	Schmidt, James	
	Williams, Angelo	
		CENAB

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons and Zimmer personnel worked at the federal property site packaging old CAFS filters for hazardous waste shipment. Parsons management personnel worked on work plan change pages.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg 53

5-2-17

0630 SAFETY BRIEF

0650 RADIO CHECKS. TEAMS WORKING AT FEDERAL PROPERTY.

1460 CONFERENCE CALL CONCERNING LOW PROBABILITY PPE/SUPPORT.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 03 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and warm Low 52° High 66°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	
Matter, Phil	Prate, Warren	
Nelms, Bobby	Vail, Todd	
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons and Zimmer crews performed inventories of equipment and organized supplies. Personnel also worked at the federal property site packaging old CAFS filters for hazardous waste shipment. Parsons management personnel worked on work plan change pages.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	


54 5-3-17
0630 SAFETY BRIEF.
1650 RADIO CHECKS.
1600 Mode. Safety Checks of Personnel at Fed Site.
1700 Site Secure

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 04 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and warm Low 60° High 67°

Personnel on Site

PARSONS	ZES	ECBC
Courtny, Kenneth	Mangosh, Ed	
Matter, Phil	Prate, Warren	
Nelms, Bobby	Vail, Todd	
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Wunschel, Scott		
	ACCUPERMIT	
	Schmidt, James	
	Williams, Angelo	
		CENAB

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons and Zimmer crews continued working on inventories and organizing of supplies. Personnel also performed equipment maintenance. Parsons management personnel worked on work plan change pages.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg
55

5/4/2017 Thursday breezy, overcast

0630 Daily safety inspections briefings
0644 Radio checks
0800 Begin cutting grass @ 4835 & supply inventory
1400 Vehicle inspection & equipment maintenance
1700 End of day all secure.

Nothing follows

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 08 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Cloudy and warm Low 54° High 66°

Personnel on Site

PARSONS	ZES	ECBC	
Courtny, Kenneth	Mangosh, Ed		
Matter, Phil	Prate, Warren		
Nelms, Bobby	Vail, Todd		
Oien, Joshua	Yorkshire, Bart		
Rider, Matthew			
Rockwell, Margaret			
Wunschel, Scott			
	ACCUPERMIT		
	Schmidt, James		
	Williams, Angelo		
		CENAB	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons and Zimmer personnel worked at the federal property site packaging old CAFS filters for hazardous waste shipment. Parsons personnel also purchased supplies to replace equipment contaminated during operations collecting and sampling the black substance.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg 56

5/8/2017 Monday — Cool/breezy/lo 60's

0630 Daily Safety tips briefings
0644 Radio checks
0800 Inventory checks & supply inventory.
0930 Team went on supply run.
1200 Team returns
1330 Team to Federal Property for supply inventory & Tyvek inventory. Removed all snow equipment from 4825.
1330 Shipped off handheld monitor sensors for cg/stations.
1500 Dien left for the day.
1700 End of day, all secure.

Nothing follows

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 09 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and warm Low 41° High 67°

Personnel on Site

PARSONS	ZES	ECBC	
Courtny, Kenneth	Mangosh, Ed		
Matter, Phil	Prate, Warren		
Nelms, Bobby	Vail, Todd		
Oien, Joshua	Yorkshire, Bart		
Rider, Matthew			
Wunschel, Scott			
	ACCUPERMIT		
	Schmidt, James		
	Williams, Angelo		
		CENAB	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons and Zimmer personnel worked at the federal property site packaging old CAFS filters for hazardous waste shipment. Personnel also made inspections at both sites removing any standing water that could breed mosquitos.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg 56

5/8/2017 Monday — Cool/breezy/lo 60's

0630 Daily Safety tips briefings
0644 Radio checks
0800 Inventory checks & supply inventory.
0930 Team went on supply run.
1200 Team returns
1330 Team to Federal Property for supply inventory & Tyvek inventory. Removed all snow equipment from 4825.
1330 Shipped off handheld monitor sensors for cg/stations.
1500 Dien left for the day.
1700 End of day, all secure.

Nothing follows

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 10 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and warm Low 44° High 70°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	
Matter, Phil	Prate, Warren	
Nelms, Bobby	Vail, Todd	
	Yorkshire, Bart	
Rider, Matthew		
Wunschel, Scott		
	ACCUPERMIT	
	Schmidt, James	
	Williams, Angelo	
		CENAB

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons and Zimmer personnel worked at the federal property site installing green privacy screen on additional fence panels. The panels will be used at the 4825 site. Personnel also replaces sand bags along the fence that surrounds the site trailers at 4825.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Ps

58	5-10-17
0630	SAFETY BRIEF.
0700	RADIO CHECKS. TEAMS WORKING AT FED PROPERTY.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 11 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Rainy and warm Low 43° High 66°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	
Matter, Phil	Prate, Warren	
Nelms, Bobby	Vail, Todd	
Oien, Joshua	Yorkshire, Bart	
Rider, Matthew		
Wunschel, Scott		

ACCUPERMIT	CENAB
Schmidt, James	
Williams, Angelo	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons and Zimmer personnel worked at the federal property site packaging old CAFS filters for hazardous waste shipment. The crew also worked on erosion controls both at 4825 and the federal property site.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	
Curtis Hollister	ECBC
Chuck, Kyle	ECBC

Contractors
DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Ps

58	5-10-17
0630	SAFETY BRIEF.
0700	RADIO CHECKS. TEAMS WORKING AT FED PROPERTY.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 15 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and warm Low 50° High 71°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	
Matter, Phil	Prate, Warren	
Nelms, Bobby	Yorkshire, Bart	
Oien, Joshua		
Rider, Matthew		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons and Zimmer personnel began prepping the area where the redress trailer will sit. They leveled the area and constructed a gravel pad. They also worked at the federal property site packaging old CAFS filters for hazardous waste shipment. Personnel from Williams electric and E.C. Ernst worked at the federal property site prepping the IHF box for removal.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg

60 5-15-17

0630 SAFETY BRIEF

0650 RADIO CHECKS.

0700 ERNST AND DENSLE CONTRACTORS AT FED PROPERTY.

1200 ERNST ELECTRIC OFF SITE.

1445 DENSCO OFF SITE. WILLIAMS ELECTRIC ON SITE.

1500 WILLIAMS ELECTRIC OFF SITE.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 16 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and warm Low 63° High 78°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	
Matter, Phil	Prate, Warren	
Nelms, Bobby	Yorkshire, Bart	
Oien, Joshua		
Rider, Matthew		
Rockwell, Margaret		
Wunschel, Scott		

ACCUPERMIT	CENAB
Schmidt, James	
Williams, Angelo	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel along with W.O. Grubb Swapped out the third IHF box at the federal property site. Parsons and Zimmer personnel worked at the federal property site packaging old CAFS filters for hazardous waste shipment.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Sensitive


5-16-17
0630 SAFETY BRIEF / RADIO CHECKS.
0645 CREWS AND CREW ON SITE.
0920 SHIFT SWAP COMPLETE CREW
AND CARS OFF SITE.
1000 JR MARTIN ON SITE.
1038 STEVE MILLS ON SITE.
MST SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 17 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and warm Low 72° High 88°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	
Matter, Phil	Prate, Warren	
Nelms, Bobby	Yorkshire, Bart	
Oien, Joshua		
Rider, Matthew		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Williams electric installed the intrusion detection system on the new IHF box at the federal property site. ACI made repairs to the air conditioner units that service the 4835 property. Parsons and Zimmer personnel worked at the federal property site packaging old CAFS filters for hazardous waste shipment.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	


Pg
62
5-17-17
0630 SAFETY BRIEF.
0647 RADIO CHECKS.
0715 WILLIAMS ELECTRIC ON SITE.
1400 WILLIAMS ELECTRIC OFF SITE.
1700 Secure

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 18 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and hot Low 72° High 88°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	
Matter, Phil	Prate, Warren	
Nelms, Bobby	Yorkshire, Bart	
Oien, Joshua		
Rider, Matthew		
Wunschel, Scott		

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel from Williams Electric completed installation of the intrusion detection system on the new IHF box. Davey tree service cut grass at the federal property site. Parsons and Zimmer personnel completed packaging old CAFS filters for hazardous waste shipment.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg
63 5-18-17
0630 SAFETY BRIEF.
0650 RADIO CHECKS.
0820 WILLIAMS ELECTRIC ON SITE
0850 DAVEY LAWN SERVICE ON SITE.
1058 WILLIAMS ELECTRIC OFF SITE
1130 DAVEY LAWN SERVICE OFF SITE
NOTE: 11:00 CONFERENCE CALL
1780 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 22 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Raint and warm Low 58° High 72°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Ponce, Juan
	Prate, Warren	Glorioso, Mike
Nelms, Bobby	Yorkshire, Bart	Dusick, Brendon
Oien, Joshua		
Rider, Matthew		
Wunschel, Scott		

CHENC
Boles, Judson

ACCUPERMIT
Schmidt, James
Williams, Angelo

CENAB

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons and Zimmer personnel Received and positioned the redress conex trailer. After the conex was in position the team worked to level an area for the PDS tent. A layer of gravel was placed on the tent area. ECBC personnel were at the federal property site to smoke test the new IHF box. The rainy weather interfered with the smoke test and personnel will return tomorrow and try again.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



PG

64 5-22-A

0630 SAFETY BRIEF. JUDSON BATES ON SITE.

0650 RADIO CHECKS.

1051 LIGHTNING HOLD

1121 OFF LIGHTNING HOLD.

1130 CONTAINER OFFICE WAS DELIVERED.

1750 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 23 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Partly cloudy and warm Low 55° High 70°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Ponce, Juan
Mantell, Dawn	Prate, Warren	Glorioso, Mike
Marion, Jedidiah	Yorkshire, Bart	Dusizc, Brendon
Matter, Phil		
Nelms, Bobby		Wood, Frank
Oien, Joshua		Wooten, Mike
Rider, Matthew		Bridges, Teresa
		Blacklock, Gary
Sprouce, Mark		Bartosh, Ian
Wunschel, Reina		Rowell, Will
Wunschel, Scott		
	ACCUPERMIT	**CHENC**
	Schmidt, James	Boles, Judson
	Williams, Angelo	
		CENAB

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons had four new personnel on site, they began site familiarization and site specific training. Other Parsons and Zimmer personnel completed the gravel pad for the PDS tent and worked on E&S controls around the tent. Parsons electrical contractor began installation of the lightning protection system at the federal property site and began wiring in equipment at the 4825 site. ECBC personnel arrived on site today and began setting up the PDS.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg
65 5-23-17.
0630 SAFETY BRIEF.
0730 RADIO CHECKS.
0800 ECBC SETTING UP HQS.
1300 TRAINING W/ NEW PARSONS PEOPLE.
1500 TRAINING COMPLETE.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 24 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Partly cloudy and warm Low 60° High 71°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Ponce, Juan
Mantell, Dawn	Prate, Warren	Glorioso, Mike
Marion, Jedidiah	Yorkshire, Bart	
Matter, Phil		
Nelms, Bobby		Wood, Frank
Oien, Joshua		Wooten, Mike
Rider, Matthew		Bridges, Teresa
		Blacklock, Gary
Sprouce, Mark		Bartosh, Ian
Wunschel, Reina		Rowell, Will
Wunschel, Scott		
	ACCUPERMIT	**CHENC**
	Schmidt, James	Boles, Judson
	Williams, Angelo	
		CENAB

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons new personnel continued with site specific training and performed fit testing for the M 40 respirators. Other Parsons and Zimmer personnel completed work on E&S controls around the tent and began bringing equipment from the fed property site. Parsons electrical contractor completed wiring in equipment at the 4825 site.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg

66 5-24-17

0630 SAFETY BRIEF.

0730 RADIO CHECKS.

0833 M40 FIT TEST FOR NEW PERSONNEL.

0920 ERNST ELECTRIC ON SITE, CONNECTED ELECTRIC TO REDRESS AND THE AC UNIT.

1350 HAND HELD MONITOR TRAINING AND ACTION LEVELS.

1750 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 25 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Partly cloudy and warm Low 65° High 80°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Ponce, Juan
Mantell, Dawn	Prate, Warren	Glorioso, Mike
Marion, Jedidiah	Yorkshire, Bart	
Matter, Phil		
Nelms, Bobby		Wood, Frank
Oien, Joshua		Wooten, Mike
Rider, Matthew		Bridges, Teresa
		Blacklock, Gary
Sprouce, Mark		Bartosh, Ian
Wunschel, Reina		Rowell, Will
Wunschel, Scott		
	ACCUPERMIT	**CHENC**
	Schmidt, James	Boles, Judson
	Williams, Angelo	
		CENAB

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons, Zimmer and ECBC personnel began scenario training, they began with a table top conversation and then moved into dressed out training. Site personnel performed end of week maintenance and clean up.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg

67 5-25-17

0630 SAFETY BRIEF

0700 RADIO CHECKS, EC ERNST AT FED PROPERTY

LDS TEST.

1100 CONFERENCE CALL

1200 PDS TRAINING W/ NEW PERSONNEL

1700 SECURED.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 30 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Partly cloudy and warm Low 64° High 81°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Elliot, Laura
Mantell, Dawn	Prate, Warren	Glorioso, Mike
Marion, Jedidiah	Yorkshire, Bart	Askew, Thomas
Matter, Phil		
Nelms, Bobby		Wood, Frank
Oien, Joshua		Wooten, Mike
Rider, Matthew		Bridges, Teresa
Rockwell, Margaret		Blacklock, Gary
Sprouce, Mark		Bartosh, Ian
Wunschel, Reina		Rowell, Will
Wunschel, Scott		
	ACCUPERMIT	**CHENC**
	Schmidt, James	Boles, Judson
	Williams, Angelo	
		CENAB

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel conducted training in modified level D and level C PPE. The teams ran scenarios with simulated MINICAMS alarms and personnel decontamination. Parsons personnel also conducted training on the demolition saw.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg

68 5-30-17

0630 SAFETY BRIEF

0650 RADIO CHECKS.

0850 TRAINING WITH OG TEAMS AND PDS.

1200 BREAKING FOR LUNCH.

1245 TRAINING W/ OIC TEAMS AND PDS.

1550 THE TEAMS TO FEED PROPERLY FOR CONCRETE SAW TRAINING.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 31 May 2017
Site Location: 4825 Glenbrook Road

Weather:
Partly cloudy and warm Low 60° High 82°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Elliot, Laura
Mantell, Dawn	Prate, Warren	Glorioso, Mike
Marion, Jedidiah	Yorkshire, Bart	Askew, Thomas
Matter, Phil		
Nelms, Bobby		Wood, Frank
Oien, Joshua		Wooten, Mike
Rider, Matthew		Bridges, Teresa
Rockwell, Margaret		Blacklock, Gary
Sprouce, Mark		Bartosh, Ian
Wunschel, Reina		Rowell, Will
Wunschel, Scott		
	ACCUPERMIT	**CHENC**
	Schmidt, James	Boles, Judson
	Williams, Angelo	
		CENAB
		Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued training. Parsons personnel conducted training on soil sampling, hazardous waste packaging and chain of custody control. Parsons filled Air bottles for the SCBA units. A reported from DC channel 7 came to the site and interviewed representatives from CENAB.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg

69 5-31-17

0630 SAFETY BRIEF.

0700 RADIO CHECKS.

0830 DAILY TREE AT FED PROPERTY.

1015 BRENDA BARBER ON SITE. THE TEAMS ARE TRAINING TAKING SOIL SAMPLES.

CHRIS GARDNER W/ BALTIMORE DAO ON SITE.

1100 RICH REEVE AND MARTIN DEALE W/ WILA ON SITE.

1239 BRENDO BARBER, CHRIS GARDNER, RICH REEVE AND MARTIN DEALE OFF SITE.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 01 June 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and warm Low 65° High 84°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Elliot, Laura
Mantell, Dawn	Prate, Warren	Glorioso, Mike
Marion, Jedidiah	Yorkshire, Bart	Askew, Thomas
Matter, Phil		
Nelms, Bobby		Wood, Frank
Oien, Joshua		Wooten, Mike
Rider, Matthew		Bridges, Teresa
Rockwell, Margaret		Blacklock, Gary
Sprouce, Mark		Bartosh, Ian
Wunschel, Reina		Rowell, Will
Wunschel, Scott		
	ACCUPERMIT	**CHENC**
	Schmidt, James	Boles, Judson
	Williams, Angelo	
		CENAB
		Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons performed mask fit testing for the SCBA units and trained on level B operations. Parsons and Zimmer personnel took down sections of wooden fence between 4825 and 4835.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

On the weekly conference call we were given permission to start (noisy) work at 0700 instead of 0800.

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg	
70	6-1-A
0630	SAFETY BRIEF
0757	RADIO CHECKS.
0800	TRAFFIC SIGNS IN PLACE
	"SCBA TRAINING".
0900	PDS & SCBA SCENERO TRAINING.
1100	CONFERENCE CALL.
1130	RESCUE DRILLS
1200	LUNCH.
1515	STARTED FIT TESTING FOR SCOTT MASK.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 05 June 2017
Site Location: 4825 Glenbrook Road

Weather:
`Rain with thunder storms Low 61° High 74°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Hall, Stephen	
Mantell, Dawn	Prate, Warren	Fortier, James	
Marion, Jedidiah	Yorkshire, Bart	Askew, Thomas	
Matter, Phil			
Nelms, Bobby		Wood, Frank	
Oien, Joshua		Wooten, Mike	
Rider, Matthew		Bridges, Teresa	
Rockwell, Margaret		Blacklock, Gary	
Sprouce, Mark		Bartosh, Ian	
Wunschel, Reina		Rowell, Will	
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel resumed intrusive operations in area B. They excavated a portion of the area behind the curved retaining wall in grid 10/-90 using hand digging procedures. Teams filled nine soil drums and collected the associated soil samples.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**06/5/2017 Monday**
Weather:	**Mostly Cloudy 62-76ºF, wind 0-4 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews excavated and raked soil by hand behind the retaining wall in grid (10, -90). Filled 9 soil drums and collected 3 composite (RA-4825GR-Area B-01-060517, RA-4825GR-Area B-02-060517, and RA-4825GR-Area B-03-060517) and 3 VOC samples (RA-4825GR-Area B-VOC-060517 -01, RA-4825GR-Area B-VOC-060517 -02, and RA-4825GR-Area B-VOC-060517 -03) and submitted for headspace. Transferred 11 drums from 4825 Glenbrook Road to Fed Property.**
Summary:	**Crews excavated and raked soil by hand behind the retaining wall in grid (10, -90). Filled 9 soil drums and collected 3 composite (RA-4825GR-Area B-01-060517, RA-4825GR-Area B-02-060517, and RA-4825GR-Area B-03-060517) and 3 VOC samples (RA-4825GR-Area B-VOC-060517 -01, RA-4825GR-Area B-VOC-060517 -02, and RA-4825GR-Area B-VOC-060517 -03) and submitted for headspace. Transferred 11 drums (See COC for IDs) from 4825 Glenbrook Road to Fed Property.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**6/5/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



Pg

7/ 6-5-17

0630 SAFETY BRIEF

0750 RADIO CHECKS. TRAFFIC SIGNS IN PLACE

0730 DAMS / MINICAMS UP

0830 TEAM 1 DOWN RANGE FOR INTENSIVE OPS.

1048 LIGHTNING HOLD.

1118 OFF LIGHTNING HOLD, STARTING MID DAY CHALLENGE.

1203 MID DAY CHALLENGE COMPLETE

1249 VOC COLLECTED.

1316 SOIL DRUMS 1033-1035 FILLED AND COMPOSITE COLLECTED.

1323 VOC COLLECTED.

1345 SOIL DRUMS 1036-1038 FILLED AND COMPOSITE FILLED

1351 VOC COLLECTED.

1409 SOIL DRUMS 1039-1041 FILLED AND COMPOSITE FILLED.

1446 LIGHTNING HOLD.

1446 OFF LIGHTNING HOLD.

1524 LIGHTNING HOLD.

1555 OFF LIGHTNING HOLD.

1750 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 06 June 2017
Site Location: 4825 Glenbrook Road

Weather:
Partly cloudy and warm Low 62° High 73°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Hall, Stephen	
Mantell, Dawn	Prate, Warren	Fortier, James	
Marion, Jedidiah	Yorkshire, Bart	Askew, Thomas	
Matter, Phil	Zimmer, Doug		
Nelms, Bobby		Wood, Frank	
Oien, Joshua		Wooten, Mike	
Rider, Matthew		Bridges, Teresa	
Rockwell, Margaret		Blacklock, Gary	
Sprouce, Mark		Bartosh, Ian	
Wunschel, Reina		Rowell, Will	
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James	Boles, Judson	
	Vargas, Brandon		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued intrusive operations in area B. They excavated a portion of the area behind the curved retaining wall in grid 10/-90 using hand digging procedures. Teams filled eighteen soil drums and collected the associated soil samples. Densel Company worked at the federal property site making repairs to the AC units.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**6/6/2017 Tuesday**
Weather:	**Partly Cloudy 57-77°F, wind 0-12 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews excavated and raked soil by hand behind the retaining wall in grid (10, -90). Filled 18 soil drums and collected 6 composite and 6 VOC samples and submitted for headspace. Collected geocloth and empty sandbags (RA-4825GR-SCR-497) and marked as Haz due to association with area with material previously deemed as Haz. Transferred 19 drums from 4825 Glenbrook Road to Fed Property.**
Summary:	**Crews excavated and raked soil by hand behind the retaining wall in grid (10, -90). Filled 18 soil drums and collected 6 composite (RA-4825GR-Area B-01-060617, RA-4825GR-Area B-02-060617, and RA-4825GR-Area B-03-060617, RA-4825GR-Area B-04-060617, RA-4825GR-Area B-05-060617, RA-4825GR-Area B-06-060617) and 6 VOC samples (RA-4825GR-Area B-VOC-060617 -01, RA-4825GR-Area B-VOC-060617 -02, and RA-4825GR-Area B-VOC-060617 -03, RA-4825GR-Area B-VOC-060617 -04, RA-4825GR-Area B-VOC-060617 -05, RA-4825GR-Area B-VOC-060617 -06) and submitted for headspace.Collected geocloth and empty sandbags (RA-4825GR-SCR-497) and marked as Haz due to association with area with material previously deemed as Haz. Transferred 19 drums from 4825 Glenbrook Road to Fed Property.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**6/6/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



EA

72 6-6-17

0630 SAFETY BRIEF.

0650 RADIO CHECKS.

0658 MONICAMS UP DAAMS PUMPS RUNNING.

0700 SOIL DRUMS 1033-41, SCR DRUM 496, PPE DRUM 384 LOADED ON STAGE BAY FOR FED PROPERTY.

0908 VOC COLLECTED.

0930 SOIL DRUMS 1042-1044 & COMPOSITE COLLECTED

0952 SOIL DRUMS 1045-1047 FILLED & COMPOSITE COLLECTED

NOTE: VOC COLLECTED 09:32.

1058 STARTING MID DAY CONVOYAGE.

1154 MID DAY COMPLETE.

1213 VOC COLLECTED.

1233 SOIL DRUMS 1048-1050 FILLED & COMPOSITED COLLECTED

1405 SOIL DRUMS 1042-1050 LOADED FOR FED PROPERTY.

1422 VOC COLLECTED

1443 SOIL DRUMS 1051-1053 FILLED & COMPOSITE COLLECTED.

1446 VOC COLLECTED.

1501 SOIL DRUMS 1054 1056 FILLED & COMPOSITE COLLECTED.

1505 VOC COLLECTED.

1521 SOIL DRUMS 1057-1059 FILLED & COMPOSITE COLLECTED

1535 SOIL DRUMS 1051-1059 LOADED. SCR 497 LOADED FOR FED PROPERTY.

1750 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 07 June 2017
Site Location: 4825 Glenbrook Road

Weather:
Partly cloudy and warm Low 57° High 67°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Hall, Stephen	
Mantell, Dawn	Prate, Warren	Fortier, James	
Marion, Jedidiah	Yorkshire, Bart	Askew, Thomas	
Matter, Phil			
Nelms, Bobby		Wood, Frank	
Oien, Joshua		Wooten, Mike	
Rider, Matthew		Bridges, Teresa	
Rockwell, Margaret		Blacklock, Gary	
Sprouce, Mark		Bartosh, Ian	
Wunschel, Reina		Rowell, Will	
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James	Boles, Judson	
	Vargas, Brandon		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued intrusive operations in area B. They excavated a portion of the area behind the curved retaining wall in grid 10/-90 using hand digging procedures. Teams filled twenty-seven soil drums and collected the associated soil samples.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**6/7/2017 Wednesday**
Weather:	**Cloudy 54-66°F, wind 0-9mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews excavated and raked soil by hand behind the retaining wall in grid (10, -90). Filled 18 soil drums and collected 10 composite and 10 VOC samples and submitted for headspace. Transferred 27 drums from 4825 Glenbrook Road to Fed Property. Sent 3 samples to ECBC for Low Level Analysis. Collected glass (RA-4825GR-SCR-498) and submitted for headspace.**
Summary:	**Crews excavated and raked soil by hand behind the retaining wall in grid (10, -90). Filled 18 soil drums and collected 10 composite and 10 VOC samples and submitted for headspace. Transferred 27 drums from 4825 Glenbrook Road to Fed Property (See Drum Manifests 1-3 for IDs). Sent 3 samples to ECBC for Low Level Analysis (See Low Level COC for IDs). Collected glass (RA-4825GR-SCR-498) and submitted for headspace.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**6/7/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



73	6-7-17
0630	SAFETY BRIEF.
0650	RADIO CHECKS.
0750	MINICAMS UP, DAAMS OUT, TRAFFIC SIGNS IN PLACE:
0735	STARTING INTRUSIVE OPERATIONS.
1100	STARTING MID DAY CHALLENGE.
1125	MINICAMS UP.
1146	TEAM FILLING DRUMS.
1154	VOC COLLECTED.
1204	SOIL DRUMS 1060-1062 FILLED & COMPOSITE COLLECTED.
1209	VOC COLLECTED.
1221	SOIL DRUMS 1063-1065 FILLED & COMPOSITE COLLECTED.
1223	VOC COLLECTED.
1235	SOIL DRUMS 1066-168 FILLED & COMPOSITE COLLECTED.
1300	SOIL DRUMS 106?-1068 LOADED FOR FEED SITE.
1307	VOC COLLECTED.
1318	SOIL DRUMS 1069-1071 FILLED & COMPOSITE COLLECTED.
1319	VOC COLLECTED.
1326	SOIL DRUMS 1072-1074 FILLED & COMPOSITE COLLECTED.
1331	VOC COLLECTED.
1342	SOIL DRUMS 1075-1077 FILLED & COMPOSITE COLLECTED.
1357	SOIL DRUMS 169-1077 LOADED FOR FEED PROPERLY.
1423	VOC COLLECTED.
1438	SOIL DRUMS 1078-1080 FILLED & COMPOSITE COLLECTED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 08 June 2017
Site Location: 4825 Glenbrook Road

Weather:
Partly cloudy and warm Low 60° High 72°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Hall, Stephen	
Mantell, Dawn	Prate, Warren	Fortier, James	
Marion, Jedidiah	Yorkshire, Bart	Askew, Thomas	
Matter, Phil		Bagley, Rob	
Nelms, Bobby		Wood, Frank	
Oien, Joshua		Wooten, Mike	
Rider, Matthew		Bridges, Teresa	
Rockwell, Margaret		Blacklock, Gary	
Sprouce, Mark		Bartosh, Ian	
Wunschel, Reina		Rowell, Will	
Wunschel, Scott		Smith, Ethan	
	ACCUPERMIT	CHENC	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Crews cut the wall with the demo saw and attempted to jackhammer the wall. Crews used demo saw on the concrete air conditioning slab. Crews removed four sections of wooden fence at the 4825 and 4835 properties.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**6/8/2017 Thursday**
Weather:	**Mostly Cloudy 57-74ºF, wind 0-7 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Sent 6 samples to ECBC for Low Level Analysis. Crews cut the wall with the demo saw and attempted to jackhammer the wall. Crews used demo saw on the concrete air conditioning slab. Crews removed four sections of wooden fence at the 4825 and 4835 properties. Transported one PPE drum to Fed Property.**
Summary:	**Sent 6 samples to ECBC for Low Level Analysis (See Low Level COC for IDs). Crews cut the wall with the demo saw and attempted to jackhammer the wall. Crews used demo saw on the concrete air conditioning slab. Crews removed four sections of wooden fence at the 4825 and 4835 properties. Transported one PPE drum (4825GR-RDW-PPE-385) to Fed Property.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**6/8/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



75 6-8-17

0630 RADIO CHECKS / SAFETY BRIEF.

0653 MINICAMS UP.

0850 ALL MONITORS IN PLACE EXCLUSION ZONE ESTABLISHED AND STARTING TO CUT RETAINING WALL / FOOTER

1048 STARTING MIDDAY CHALLENGE.

1118 CONFERENCE CALL

1104 MINICAMS BACK UP.

1440 STARTING END OF DAY CHECKS

NOTE: ATTEMPTED TO USE THE HYDRAULIC HAMMER TO BREAK THE RETAINING WALL. THE VIBRATION EXCEED THE ALLOWABLE LIMIT AND THE OPERATION WAS SUSPENDED.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 12 June 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and hot Low 74° High 94°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Hall, Stephen
Mantell, Dawn	Prate, Warren	Fortier, James
Marion, Jedidiah	Yorkshire, Bart	Heard, Irvin
Matter, Phil		Bagley, Rob
Nelms, Bobby		Smith, Ethan
Oien, Joshua		Miller, Jonathan
Rider, Matthew		Guyer, Gary
Rockwell, Margaret		Jones, LaMarcus
Sprouce, Mark		Foor, Adam
Wunschel, Reina		Hollister, Curtis
Wunschel, Scott		Henderson, Amos
	ACCUPERMIT	**CHENC**
	Schmidt, James	Boles, Judson
	Williams, Angelo	
		CENAB
		Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel ran three training scenarios with the new ECBC personnel. Parsons and Zimmer personnel moved concrete rubble from last week out of the way then resumed excavation of grid 10/-90. At 14 intrusive operations were suspended due to heat.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**6/12/2017 Monday**
Weather:	**Sunny 72-94°F, wind 0-4 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Sent 9 samples to ECBC for Low Level Analysis. Sent samples to APPL for disposal characterization. Crews continued hand digging in grid 10, -90. Conducted training in the morning with new ECBC PDS crew. Consolidated concrete from retaining wall.**
Summary:	**Sent 9 samples to ECBC for Low Level Analysis (See Low Level COC for IDs). Sent samples to APPL for disposal characterization (See APPL COC for IDs). Crews continued hand digging in grid 10, -90. Conducted training in the morning with new ECBC PDS crew. Consolidated concrete from retaining wall.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**6/12/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

2

76 6-12-17

0630 SAFETY BRIEF.

0700 RADIO CHECKS, TRAFFIC SIGNS UP.

0730 MINICAMS & DAAMS UP.

0744 STARTING TRAINING W/NEW PDS CREW.

0759 WBGT @ 79.6 WORK/REST 75/25

0834 TEAM WORKING DOWN RANGE CLEARING CONCRETE DUST FROM 4835 SIDING.

WBGT @ 82.6 50/50 FOR HEAVY WK.

0930 WBGT @ 88.2 50/50 FOR MODERATE WK.

1140 STARTING MIDDAY CHALLENGE

1155 MIDDAY COMPLETE

1210 WBGT @ 84.6 50/50 HEAVY WK

1315 WBGT @ 87.4 25/75 HEAVY WK.

1345 STARTING END OF DAY CHECKS.

INTRUSIVE OPERATIONS SUSPENDED DUE TO HEAT.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 13 June 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and hot Low 78° High 93°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Hall, Stephen	
Mantell, Dawn	Prate, Warren	Fortier, James	
Marion, Jedidiah	Yorkshire, Bart	Heard, Irvin	
Matter, Phil		Bagley, Rob	
Nelms, Bobby		Smith, Ethan	
Oien, Joshua		Miller, Jonathan	
Rider, Matthew		Guyer, Gary	
Rockwell, Margaret		Jones, LaMarcus	
Sprouce, Mark		Foor, Adam	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued excavation of grid 10/-90. Personnel also filled six soil drums and collected the associated soil samples. At 1445 intrusive operations were suspended due to heat.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report	
Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**6/13/2017 Tuesday**
Weather:	**Sunny 72-95°F, wind 0-5 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews continued excavating in grid (10, -90). Collected 2 composite and 2 VOC samples and submitted for headspace. Transported 7 drums to Fed Property.**
Summary:	**Crews continued excavating in grid (10, -90). Collected 2 composite (RA-4825GR-Area B-01-061317 and RA-4825GR-Area B-02-061317) and 2 VOC (RA-4825GR-Area B-VOC- 061317-01 and RA-4825GR-Area B-VOC- 061317-02) samples and submitted for headspace. Transported 7 drums to Fed Property (See Drum Transfer Manifest for IDs).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**6/13/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**



R2

77 6/13-17

0630 SAFETY BRIEF/ SECURITY BRIEF.

0700 RADIO CHECKS. TRAFFIC SIGNS IN PLACE

0712 MINICHAMS & BARRELS UP.

0903 WBGT @ 85.0 50/50 HEAVY WORK.

0934 WBGT @ 86.2. 25/75 HEAVY WORK.

1007 WBGT @ 83.5 50/50 HEAVY WORK.

1026 WBGT @ 82.7 50/50 HEAVY WORK.

1112 STARTING MID DAY CHALLENGE.

1129 MID DAY COMPLETE.

1151 WBGT @ 84.9 50/50 HEAVY WORK

1248 WBGT @ 86.3 25/75 HEAVY WORK.

1335 LIGHTNING HOLD.

1485 OFF LIGHTNING HOLD.

1412 FILLING DRUMS VOC COLLECTED.

1421 SOIL DRUMS 1087. 1089 FILLED, COMPOSITE COLLECTED.

1423 VOC COLLECTED.

1436 SOIL DRUMS 1090-1092 FILLED, COMPOSITE COLLECTED.

1500 SOIL DRUMS 1087-1092 & PPE 386 LOADED FOR FED PROPERTY.

1510 STARTING END OF DAY CHECKS.

105 SITE OPERATIONS SUSPENDED DUE TO HEAT WBGT @ 91.7.

1710 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 14 June 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and hot, possible T-storms Low 74° High 88°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Hall, Stephen	
Mantell, Dawn	Prate, Warren	Fortier, James	
Marion, Jedidiah	Yorkshire, Bart	Heard, Irvin	
Matter, Phil		Bagley, Rob	
Nelms, Bobby		Smith, Ethan	
Oien, Joshua		Miller, Jonathan	
Rider, Matthew		Guyer, Gary	
Rockwell, Margaret		Jones, LaMarcus	
Sprouce, Mark		Foor, Adam	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued intrusive operations in area B. They excavated a portion of the area behind the curved retaining wall in grid 10/-90 using hand digging procedures. Teams filled twenty-four soil drums and collected the associated soil samples.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report	
Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**6/14/2017 Wednesday**
Weather:	**Partly Cloudy 68-89°F, wind 0-7 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews continued excavating in grid (10, -90). Collected 8 composite and 8 VOC samples and submitted for headspace. Transfered 24 drums to Fed Property.**
Summary:	**Crews continued excavating in grid (10, -90). Collected 8 composite and 8 VOC samples and submitted for headspace (See COC for IDs). Transfered 24 drums to Fed Property.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**6/14/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

78	6-14-17
0630	SAFETY BRIEF.
1700	RADIO CHECKS TRAFFIC SIGNS IN PLACE
0743	MINICAMS & DARMS UP.
0946	WBGT@ 77.7
0850	WBGT@ 82.4 50/50 HEAVY WORK.
0937	WBGT@ 78.4 75/25 HEAVY WORK.
1037	WBGT@ 80.0 75/25 HEAVY WORK
1201	STARTING MID DAY CHALLENGE
1218	MID DAY COMPLETE.
1240	WBGT@ 85.4 CONTINUOUS WORK FOR LIGHT
1248	VOC COMPLETE.
1259	SOIL DRUMS 1093-1095 FILLED & COMPOSITE COLLECTED.
1301	VOC COLLECTED.
1311	SOIL DRUMS 1096-1098 FILLED & COMPOSITE COLLECTED.
1312	VOC COLLECTED.
1321	SOIL DRUMS 1099-1101 FILLED & COMPOSITE COLLECTED
1328	VOC COLLECTED.
1338	SOIL DRUMS 1102-1104 FILLED & COMPOSITE COLLECTED.
1339	VOC COLLECTED
1348	SOIL DRUMS 1105-1107 FILLED & COMPOSITE COLLECTED
1400	WBGT@ 84.8
1414	SOIL DRUMS 1093-1107 LOADED FOR FED PROPERTY
1426	VOC COLLECTED.
1444	SOIL DRUMS 1108-1110, FILLED COMPOSITE COMPLETED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 15 June 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and hot Low 72° High 86°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Hall, Stephen	
Mantell, Dawn	Prate, Warren	Fortier, James	
	Yorkshire, Bart	Heard, Irvin	
Matter, Phil		Bagley, Rob	
Nelms, Bobby		Smith, Ethan	
Oien, Joshua		Miller, Jonathan	
Rider, Matthew		Guyer, Gary	
Rockwell, Margaret		Jones, LaMarcus	
Sprouce, Mark		Foor, Adam	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued intrusive operations in area B. They excavated a portion of the area behind the curved retaining wall in grid 10/-90 using hand digging procedures. Teams filled nine soil drums and collected the associated soil samples.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report	
Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**6/15/2017 Thursday**
Weather:	**Partly Cloudy 69-85°F, wind 0-6 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews continued excavating in grid (10, -90). Sent 2 samples to ECBC for low level analysis. Collected 3 composite and 3 VOC samples and submitted for headspace. Collected 1 bag of glass and 2 bags of metal and submitted for headspace. Transferred 11 drums from 4825 to fed property.**
Summary:	**Crews continued excavating in grid (10, -90). Sent 2 samples to ECBC for low level analysis (See Low Level COC for IDs). Collected 3 composite and 3 VOC samples and submitted for headspace and collected 1 bag of glass and 2 bags of metal and submitted for headspace (See Headspace COC for IDs). Transferred 11 drums from 4825 to fed property (See Drum Transfer Manifest for IDs).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**6/15/2017**
Phone Number:	**571-721-9804**
Copies sent to:	**Tammy Chang, Beth Driskill, Phil Matter, Scott Wunschel, Janelle Boncal**

Pg	
80	6-15-17
0630	SAFETY BRIEF.
1650	RADIO CHECKS.
0710	MINICAMS & DAMS UP
0718	WBGT @ 68.0
0727	STARTING INTRUSIVE OPERATIONS.
0800	AU REP ON SITE. INTRUSIVE OPS SUSPENDED.
0856	ALL REP'S OFF SITE, STARTING INTRUSIVE OPS.
0940	WBGT @ 74.5
1040	WBGT @ 80.6
1110	STARTING MID DAY CHALLENGE
1125	MID DAY COMPLETE.
1142	STARTING INTRUSIVE OPS
1149	WBGT @ 80.5 75/25 HEAVY WORK.
1229	WBGT @ 82.4 50/50 HEAVY WORK.
1429	VOC COLLECTED.
1443	SOIL DRUMS 1117-1119 FILLED, COMPOSITE COLLECTED.
1444	VOC COLLECTED.
1456	SOIL DRUMS 1120-1122 FILLED COMPOSITE COLLECTED.
1457	WBGT=78.6, VOC COLLECTED.
1508	SOIL DRUMS 1123-1125 FILLED, COMPOSITE COLLECTED.
1521	SCP-501 DOUBLE BAGGED GLASS 4.5 lbs
	SCP-502 DOUBLE BAGGED METAL 4.5 lbs
	SCP-503 DOUBLE BAGGED METAL 2.39 lbs.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 19 June 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and hot Low 68° High 89°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Nichols, Doug	
Mantell, Dawn	Prate, Warren	Leach, Mark	
Marion, Jed	Yorkshire, Bart	Heard, Irvin	
Matter, Phil		Bagley, Rob	
Nelms, Bobby		Smith, Ethan	
Oien, Joshua		Miller, Jonathan	
Rider, Matthew		Guyer, Gary	
		Jones, LaMarcus	
Sprouce, Mark		Foor, Adam	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel resumed excavation of grid 10/-90. Parsons personnel used the concrete cutting chainsaw to cut the concrete pad that the AC units were on at 4835 Glenbrook. The team also removed the brick façade from the retaining wall with the excavator.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Sensitive



82	6-19-17
0630	SAFETY BRIEF
0700	RADIO CHECKS.
0726	MINICAMS & DRAMS UP.
0810	TEAM 2 DOWN RANGE
0900	WBGT @ 80.2 75/25 HEAVY WORK.
1030	WBGT @ 86.8 25/75 HEAVY WORK
1040	WBGT @ 87.0 75/25 HEAVY WORK.
1130	STARTING MIDDAY CHALLENGE.
1150	MIDDAY COMPLETE.
1220	WBGT @ 83.6
1349	WBGT @ 83.7
1430	WBGT @ 94.3
1530	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 20 June 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and hot Low 70° High 88°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Nichols, Doug	
Mantell, Dawn		Leach, Mark	
Marion, Jed	Yorkshire, Bart	Heard, Irvin	
Matter, Phil		Bagley, Rob	
Nelms, Bobby		Smith, Ethan	
Oien, Joshua		Miller, Jonathan	
Rider, Matthew		Guyer, Gary	
Rockwell, Margaret		Jones, LaMarcus	
		Foor, Adam	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued excavation of grid 10/-90. Personnel also completed removing the concrete AC pad on the 4835 property then loaded the concrete and brick rubble into a roll off box. After lunch the team began excavating a portion of grid 30/-90.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**6/20/2017 Tuesday**
Weather:	**Partly Cloudy 66-87°F, wind 0-9 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews continued work in grid(10, -90) and (30, -90). Completed removing the concrete air conditioner pad. Used the demo saw to cut the retaining wall and loaded concrete and brick debris into a roll-off (278356).**
Summary:	**Crews continued work in grid(10, -90) and (30, -90). Completed removing the concrete air conditioner pad. Used the demo saw to cut the retaining wall and loaded concrete and brick debris into a roll-off (278356).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**6/20/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**



83	6-20-17
0630	SAFETY BRIEF
0700	RADIO CHECKS TRAFFIC SIGNS IN PLACE.
0739	MINICAMS & DRAMS UP.
0745	ROAD WORK AHEAD CONCRETE PAD.
0925	ROLLOFF 278356 ON SITE.
1115	ROLLOFF 278356 IS FULL & OFF SITE "BURBEE".
1123	STARTING UP MID DAY CHALLENGE.
1150	MIDDAY CHALLENGE COMPLETE.
1220	STARTING CONCRETE CUTTING OPS. WET @ 827.
1545	STARTING END OF DAY CHECKS.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 21 June 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and hot Low 72° High 87°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Nichols, Doug	
Mantell, Dawn	Prate, Warren	Leach, Mark	
	Yorkshire, Bart	Heard, Irvin	
Matter, Phil	Zimmer, Doug	Bagley, Rob	
Nelms, Bobby		Smith, Ethan	
Oien, Joshua		Miller, Jonathan	
Rider, Matthew		Guyer, Gary	
Rockwell, Margaret		Jones, LaMarcus	
		Foor, Adam	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel filled one roll off box with (backfill soil) from grid 30/-90 and collected the associated soil sample. Team personnel continued intrusive operations in area B, grid 30/-90 removing more of the Backfill material using hand and mechanical techniques.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report	
Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**6/21/2017 Wednesday**
Weather:	**Partly Cloudy 68-88°F, wind 0-10 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews continued work in grid(10, -90) and (30, -90). Sent 11 samples to ECBC for Low Level Analysis. Filled one roll-off with excavated backfill soil and collected 1 composite and 1 VOC sample and submitted for headspace.**
Summary:	**Crews continued work in grid(10, -90) and (30, -90). Sent 11 samples to ECBC for Low Level Analysis (See COC for IDs). Filled one roll-off with excavated backfill soil and collected 1 composite (RA-4825GR-Area B-01-062117) and 1 VOC (RA-4825GR-Area B-VOC- 062117-01) sample and submitted for headspace.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**6/21/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**



TG	
94	6-21-17
0630	SAFETY BRIEF.
0700	RADIO CHECKS TRAFFIC SIGNS IN PLACE
0720	MINI CANES & BARRELS UP.
0726	ROLLOFF R25359RT ON SITE.
0827	VAC COLLECTED.
0905	ROLLOFF R25359RT IS FULL & COMPOSIT COLLECTED.
0930	ROLLOFF R25359RT IS OFF SITE.
1040	WBGT @ 84.4
1115	STARTING MID DAY CHALLENGE.
1135	MID DAY COMPLETE
1353	WBGT @ 86.3
1429	WBGT @ 85.5
1527	STARTING END OF DAY CHECKS.
1710	SECURED.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 22 June 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and hot Low 78° High 89°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Nichols, Doug
Mantell, Dawn	Prate, Warren	Leach, Mark
Marian, Jed	Yorkshire, Bart	Heard, Irvin
Matter, Phil	Zimmer, Doug	Bagley, Rob
Nelms, Bobby		Smith, Ethan
Oien, Joshua		Miller, Jonathan
Rider, Matthew		Guyer, Gary
Rockwell, Margaret		Jones, LaMarcus
		Foor, Adam
Wunschel, Reina		
Wunschel, Scott		

ACCUPERMIT	CHENC
Schmidt, James	Boles, Judson
Williams, Angelo	

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Team personnel continued intrusive operations in area B, grid 10/-90 using hand digging techniques. Personnel filled one roll off box with soil from grid 30/-90.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**6/22/2017 Thursday**
Weather:	**Mostly Cloudy 73-88ºF, wind 0-6 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews continued work in grid(10, -90) and (30, -90). Filled one roll-off with backfill soil and collected composite and VOC sample.**
Summary:	**Crews continued work in grid(10, -90) and (30, -90). Filled one roll-off with backfill soil and collected composite and VOC sample and submitted for headspace.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**6/22/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**



Pg
85

6-22-17

0630 SAFETY BRIEF
0700 RADIO CHECKS
0723 MINICAMS & DADMS UP.
0736 STARTING INTRUSIVE OPS. WBGT @ 75.0.
0840 WBGT@ 82
0926 WBGT@ 84.1
1105 STARTING MCD Day CHALLENGE.
1120 MIDDAY COMPLETE.
1130 WBGT.@ 84.3
1155 TEAM 1 DOWN RANGE.
1218 TEAM 1 AT POS.
1237 TEAM 2 DOWN RANGE. WBGT@ 79.3
1306 TEAM 2 @ POS.
1320 ROLLOFF RB3677ART ON SITE.
1342 TEAM 1 FILLING ROLLOFF WBGT@ 83.7
1343 TEAM 1 OUT TO POS.
1403 TEAM 2 DOWN RANGE FILLING ROLLOFF
1406 VOC COLLECTED
1446 ROLLOFF RB3677ART IS FULL
1450 COMPOSITE COLLECTED
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 29 June 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and warm Low 75° High 89°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Copeland, Eric
Mantell, Dawn	Prate, Warren	Leach, Mark
Marian, Jed	Yorkshire, Bart	Tucker, Robin
Matter, Phil		Bagley, Rob
Nelms, Bobby		Smith, Ethan
Oien, Joshua		Miller, Jonathan
Rider, Matthew		Guyer, Gary
Rockwell, Margaret		Jones, LaMarcus
Sprouse, Mark		Foor, Adam
Wunschel, Reina		
Wunschel, Scott		
	ACCUPERMIT	**CHENC**
	Schmidt, James	Boles, Judson
	Buhl, John	
		CENAB
		Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel loaded staged soil into drums and collected the associated soil samples. Intrusive teams continued demo of the straight portion of the retaining wall using the concrete cutting chainsaw and large excavator.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**6/29/2017 Thursday**
Weather:	**Partly Cloudy 70-89°F, wind 0-9 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Intrusive teams resumed demo of the straight portion of the retaining wall using the concrete cutting chainsaw. Team personnel continued intrusive operations in Area B, grid (30, -90) removing more material using hand and mechanical techniques. Sent 2 composite and VOC samples to APPL for disposal characterization. Filled 15 drums with excaveted soil, collected 6 composite and 6 VOC and submitted for headspace. Transported 18 soil drums, 1 PPE, and 2 scrap drums to Fed Property.**
Summary:	**Intrusive teams resumed demo of the straight portion of the retaining wall using the concrete cutting chainsaw. Team personnel continued intrusive operations in Area B, grid (30, -90) removing more material using hand and mechanical techniques. Sent 2 composite and VOC samples to APPL for disposal characterization (See APPL COC for IDs). Filled 18 drums with excaveted soil, collected 6 composite and 6 VOC and submitted for headspace. Transported 18 soil drums, 1 PPE, and 2 scrap drums to Fed Property (See Drum Transfer Manifest for IDs).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**6/29/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**



89	6-29-17
0630	SAFETY BRIEF
0650	RADIC CHECKS
0703	PDS UP, TRAFFIC SIGNS IN PLACE.
0714	MINICAMS & BAAMS UP.
0730	TEAM 1 DOWN RANGE, CUTTING RETAINING WALL.
0905	TEAM 1 THRU PDS.
0954	TEAM 2 DOWN RANGE CUTTING RETAINING WALL
1041	TEAM 2 THRU PDS.
1059	ROLLOFF 279889 OFF SITE "RUBBLE"
1134	STARTING MID DAY CHALLENGE.
1130	MID DAY CHALLENGE COMPLETE.
1209	TEAM 3 DOWN RANGE, FILLING SOIL DRUMS.
	WBGT@ 82.7.
1226	VOC 108 COLLECTED.
1238	SOIL DRUMS 1141-1143 FILLED & COMPOSITE COLLECTED.
1248	VOC 109 COLLECTED.
1257	SOIL DRUMS 1144-1146 FILLED & COMPOSITE COLLECTED
1258	VOC 110 COLLECTED.
1314	SOIL DRUMS 1147-1149 FILLED & COMPOSITE COLLECTED.
1318	TEAM 3 THRU PDS.
1332	TEAM 1 DOWN RANGE.
1333	VOC 111 COLLECTED
1143	SOIL DRUMS 1150-1152 FILLED & COMPOSITE COLLECTED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 05 July 2017
Site Location: 4825 Glenbrook Road

Weather:
Sunny and warm Low 73° High 88°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Copeland, Eric
Mantell, Dawn	Prate, Warren	Leach, Mark
Marian, Jed	Yorkshire, Bart	Avila, Michelle
Matter, Phil		
Nelms, Bobby		Guyer, Gary
Oien, Joshua		Jones, LaMarcus
Rider, Matthew		Smith, Eathan
Rockwell, Margaret		Wootan, Mike
Sprouse, Mark		Landers, Brian
Wunschel, Reina		McGill, Andre
Wunschel, Scott		
	ACCUPERMIT	**CHENC**
	Schmidt, James	Boles, Judson
	Williams, Angelo	
		CENAB
		Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Intrusive teams continued demo of the remainder of the AC pad using the concrete cutting chainsaw. Team personnel continued intrusive operations in area B, grid 10/-90 and 30/-90 removing more material using hand and mechanical techniques.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**7/5/2017 Wednesday**
Weather:	**Mostly Cloudy 72-85ºF, wind 0-9 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Intrusive teams continued demo of the remainder of the AC pad using the concrete cutting chainsaw. Team personnel continued intrusive operations in area B, grid 10/-90 and 30/-90 removing more material using hand and mechanical techniques.**
Summary:	**Intrusive teams continued demo of the remainder of the AC pad using the concrete cutting chainsaw. Team personnel continued intrusive operations in area B, grid 10/-90 and 30/-90 removing more material using hand and mechanical techniques.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**7/5/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**



Pg	
91	7-5-17
0630	SAFETY BRIEF.
0700	RADIO CHECKS, TRAFFIC SIGNS IN PLACE, PDS UP
0723	MINI CAMS AND DAAMS UP.
0800	TEAM 1 DOWN RANGE, CUTTING CONCRETE WALL W/ CHAIN SAW.
0952	TEAM 1 CLEARED PDS.
1000	TEAM 2 DOWN RANGE.
1131	TEAM 2 CLEARED PDS, STARTING MIDDAY CHALLENGE
1149	MID DAY CHALLENGE COMPLETE.
1209	TEAM 3 DOWN RANGE.
1330	WBGT @ 83.6
1335	TEAM 3 CLEARED PDS.
1347	TEAM 1 DOWN RANGE.
1426	TEAM 1 CLEARED PDS.
1428	TEAM 2 DOWN RANGE. WBGT @ 81.1
1547	TEAM 2 CLEARED PDS.
1550	STARTING END OF DAY CHECKS.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 06 July 2017
Site Location: 4825 Glenbrook Road

Weather:
Hot and Rainy Low 73° High 89°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Copeland, Eric
Malone, Forrest	Prate, Warren	Leach, Mark
Mantell, Dawn	Yorkshire, Bart	Avila, Michelle
Marian, Jed		
Matter, Phil		Guyer, Gary
Nelms, Bobby		Jones, LaMarcus
Oien, Joshua		Smith, Eathan
Pilato, Bryan		Wootan, Mike
Rider, Matthew		Landers, Brian
Rockwell, Margaret		McGill, Andre
Sprouse, Mark		
Wunschel, Reina		
Wunschel, Scott	**ACCUPERMIT**	**CHENC**
	Schmidt, James	Boles, Judson
	Williams, Angelo	
		CENAB
		Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons personnel conducted training with two new personnel. Two sections of the wooden fence were removed, Brush and trees cut back and temporary fence was installed. No intrusive operations were conducted due to inclement weather.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report	
Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**7/6/2017 Thursday**
Weather:	**Rain 71-77°F, wind 0-7 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**No intrusive operations were conducted due to inclement weather. Two sections of the wooden fence were removed. Brush and trees were cut back and temporary fencing was installed. Six samples were sent to ECBC for low level analysis.**
Summary:	**No intrusive operations were conducted due to inclement weather. Two sections of the wooden fence were removed. Brush and trees were cut back and temporary fencing was installed. Six samples were sent to ECBC for low level analysis (See COC for IDs).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**7/6/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**



92
7-6-17
0630 SAFETY BRIEF
0700 RADIO CHECKS. TRAFFIC SIGN IN PLACE.
0718 MINICAMS UP. MALONE AND PILATO ON SITE. STARTING SITE TRAINING.
1050 MALONE AND PILATO FIT TESTED.
1100 CONFERENCE CALL.
1119 STARTING MID DAY CHALLENGE.
1129 MID DAY CHALLENGE COMPLETE.
1133 CONFERENCE CALL COMPLETE.
1158 Teams begin to tear down sections of fence panels between 4825 & 4835 Glenbrook Rd.
506 Two fence panels removed & replaced w/ temporary fence panels. Port-O-Potties cleaned.
545 Begin end of day challenge.
1700 End of day all secure.
Nothing follows

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 07 July 2017
Site Location: 4825 Glenbrook Road

Weather:
AM showers then hot Low 75° High 87°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Copeland, Eric	
Malone, Forrest	Prate, Warren	Leach, Mark	
Mantell, Dawn	Yorkshire, Bart	Avila, Michelle	
Marian, Jed			
Matter, Phil		Davis, Torry	
Nelms, Bobby		Ford, Bonnie	
Oien, Joshua		McClellan, Dale	
Pilato, Bryan		Wootan, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margaret		McGill, Andre	
Sprouse, Mark		Smith, Ethan	
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons and Zimmer personnel dumped three roll off boxes at the federal property site. Personnel pumped excess rainwater from area B into poly drums and transported them to the storage area. Intrusive teams filled a roll off box with backfill soil from area B and collected the associated soil sample. Site personnel continued intrusive operations in area B, grid 10/-90 and 30/-90 and removed the footer from the curved section of retaining wall.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**7/7/2017 Friday**
Weather:	**Rain in the morning, partly cloudy 71-89°F, wind 0-12 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews pumped water from rainstorms into 10 drums and transported to Fed Property. Site personnel continued intrusive operations in Area B, grid 10/-90 and 30/-90, removing more material using hand and mechanical techniques. Backfill soil sampled (1 VOC (RA-4825GR-Area B-VOC- 070717-01) and 1 Composite(RA-4825GR-Area B-01-070717)) and submitted for headspace.**
Summary:	**Crews pumped water from rainstorms into 10 drums and transported to Fed Property (See Drum Transfer Manifest for IDs). Site personnel continued intrusive operations in Area B, grid 10/-90 and 30/-90, removing more material using hand and mechanical techniques. Backfill soil sampled (1 VOC (RA-4825GR-Area B-VOC- 070717-01) and 1 Composite(RA-4825GR-Area B-01-070717)) and submitted for headspace.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**7/7/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

(93)

7-7-2017 Friday Cloudy lo 80's

0630 Daily safety & operations briefings
0652 PDS up & operational
0712 Mini CAMS up, wait on RAAMS until digging.
0830 Teams return from Fed Prop dumped 3 rolloffs
0845 Truck with water drums arrives to pump at rain water.
0905 Begin pumping water, Rider & Rockwell depart to pick up new rental vehicles.
0930 Reina Wunschel continues training with new ~~hires~~ hires.
1055 Water is finished being pumped. Drums 560 thru 569 filled.
1108 Truck departs w/ AQ drums & manifest.
1126 Rolloff truck on site w/ rolloff # 280191
1126 Midday / Lunch.
1215 WBGT 81° Team 2 Reina, Jed & Eddie in to load rolloff w/ clean top soil.
1317 VOC collected
1340 Composite Sample 114 collected
1355 TM 2 is out TM1 button up rolloff.
1415 TM3 is in dig out old retaining wall try to move w/ big excavator.
1447 Big excavator broke curved retaining wall faster.
515 TM2 out of EZ begin maintainance / end of day checks.
700 End of day, all secure.

Nothing follows

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 07 July 2017
Site Location: 4825 Glenbrook Road

Weather:
AM showers then hot Low 75° High 87°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Alvano, Lou	
Malone, Forrest	Prate, Warren	Leach, Mark	
Mantell, Dawn	Yorkshire, Bart	PalePale, Magareth	
Marian, Jed			
Matter, Phil		Davis, Torrey	
Nelms, Bobby		Ford, Bennie	
Oien, Joshua		McClellan, Dale	
Pilato, Bryan		Wootan, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margaret		McGill, Andre	
Sprouse, Mark		Smith, Ethan	
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued intrusive operations in area B, grid 10/-90 and 30/-90 removing more material using hand digging techniques. Teams were attempting to determine where the waterline enters the 4835 home. Teams also loaded clean concrete, wood fencing and shrubbery into a roll off for transport to the federal property site. After lunch teams loaded excavated soil into drums and collected the associated soil samples.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 11 July 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 77° High 93°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Alvano, Lou	
Malone, Forrest	Prate, Warren	Leach, Mark	
Mantell, Dawn	Yorkshire, Bart	PalePale, Magareth	
Marian, Jed	Zimmer, Doug		
Matter, Phil		Davis, Torry	
Nelms, Bobby		Ford, Bennie	
Oien, Joshua		McClellan, Dale	
Pilato, Bryan		Wootan, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margaret		McGill, Andre	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued intrusive operations in area B, grid 10/-90 and 30/-90, they created a stockpile for future barrel filling operations. Maintenance contractor from ACI made repairs to the AC unit that cools the PDS tent. At 1500 Parsons and Zimmer personnel went to the federal property site to dump roll off boxes.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**7/11/2017 Tuesday**
Weather:	**Mostly Cloudy 74-88ºF, wind 0-10 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Site personnel continued intrusive operations in Area B, grid 10/-90 and 30/-90. Crews created a stockpile for future drum filling operations. Maintenancec contractor from ACI made repairs to the AC unit that cools the PDS tent. Crews dumped roll-off boxes at federal property.**
Summary:	**Site personnel continued intrusive operations in Area B, grid 10/-90 and 30/-90. Crews created a stockpile for future drum filling operations. Maintenancec contractor from ACI made repairs to the AC unit that cools the PDS tent. Crews dumped roll-off boxes at federal property.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**7/11/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

96

11 July 2017 Tuesday hot, humid 90's

0630 Daily safety & operations briefings.
0652 PDS is up & ready.
0715 Min. CAMs/BAMs/personal monitors up.
0720 TCam 1 in level D.
0820 TM1 out TM2 next in WBGT 81.4°
0830 75/25 work/rest
0834 TM2 in
0850 81.6 WBGT
0915 TM2 out
0920 TM3 in w/ Pilato new guy 83.1 WBGT
0950 TM3 out of EZ
1120 TM1 in 83.1 WBGT digging
1145 TM1 out
1156 TM2 in digging
1230 TM2 out midday/Lunch
1245 Midday complete ACI A/C repair on site
1312 81.4° 75/25 TM3 in
1400 TM3 clear EZ found glass & geo
1405 TM1 in 81.9° 75/25 Heime from AH on site
1415 Heime reports TM1 begins to dig
1445 89.1 WBGT 25/75 TM 3 pulled out.
1455 TM1 clear of PDS, begin end of day, TM3 supply run
TM1+2 dump roll off

continued ⇒

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 12 July 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 75° High 96°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Alvano, Lou	
Malone, Forrest	Prate, Warren	Leach, Mark	
Mantell, Dawn	Yorkshire, Bart	PalePale, Magareth	
Marian, Jed			
Matter, Phil		Davis, Torry	
Nelms, Bobby		Ford, Bennie	
Oien, Joshua		McClellan, Dale	
Pilato, Bryan		Wootan, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margaret		McGill, Andre	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Team personnel continued intrusive operations in area B, grid 10/-90 and 30/-90 removing more material using hand and mechanical techniques. Teams loaded excavated soil into drums and collected the associated soil samples. At 1400 Parsons and Zimmer personnel went to the federal property site to dump roll off boxes. Maintenance contractor from ACI made an inspection of the AC units for the 4835 property, he will return tomorrow with parts.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**7/12/2017 Wednesday**
Weather:	**Sunny 75-93°F, wind 0-6 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Site personnel continued intrusive operations in Area B, grid 10/-90 and 30/-90. Sent 7 samples to ECBC for low level analysis. Crews filled 15 soil drums and collected 5 VOC and 5 composite samples and submitted for headspace. Transported 15 soil drums and 1 PPE drum to the federal property site. Crews dumped cleared roll-offs in the afternoon at federal property site.**
Summary:	**Site personnel continued intrusive operations in Area B, grid 10/-90 and 30/-90. Sent 7 samples to ECBC for low level analysis (see low level COC for IDs). Crews filled 15 soil drums and collected 5 VOC and 5 composite samples and submitted for headspace (See headspace COC for IDs). Transported 15 soil drums and 1 PPE drum to the federal property site (see Drum Manifest for IDs). Crews dumped cleared roll-offs in the afternoon at federal property site.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**7/12/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

98

7-12-17

0630 SAFETY BRIEF.

0700 TRAFFIC SIGNS IN PLACE. RADIO CHECKS. ACI ON SITE TO REPAIR PDS & 4835 AC UNITS.

0820 ACI COMPLETED REPAIRS ON PDS AC. THE AC UNIT FOR 4835 NEEDS PARTS, AND ACI WILL RETURN TOMORROW TO COMPLETE REPAIRS.

0835 TEAM 2 DOWN RANGE WBGT @ 81.4 75/25 HEAVY WORK. R. WUNSCHEL, MARION

0916 TEAM 2 CLEARED PDS WBGT @ 89.5 50/50 HEAVY WORK. (SPONSE, MANTELL, PINATO)

0917 TEAM 3 DOWN RANGE.

0946 TEAM 3 CLEARED PDS WBGT @ 86.5

0955 TEAM 1 DOWN RANGE, 87.4 WBGT FIBER GLOVES, CANTEEN MANTISA

1012 VOC COLLECTED 121

1028 SOIL DRUMS 1177-1179 FILLED & COMPOSITE COLLECTED.

1030 VOC COLLECTED 122

1045 SOIL DRUMS 1180-1182 FILLED & COMPOSITE COLLECTED

1049 TEAM 1 CLEARED PDS.

1051 TEAM 2 DOWN RANGE. R. WUNSCHEL, MARION, MANOSA.

1054 VOC 123 COLLECTED.

1112 SOIL DRUMS. 1183-1185 FILLED & COMPOSITE COLLECTED.

1115 TEAM 2 CLEARED PDS.

1114 STARTING MID DAY CHALLENGE

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 13 July 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 80° High 96°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Alvano, Lou	
Malone, Forrest	Prate, Warren	Leach, Mark	
Mantell, Dawn	Yorkshire, Bart	PalePale, Magareth	
Marian, Jed			
Matter, Phil		Davis, Torry	
Nelms, Bobby		Ford, Bennie	
Oien, Joshua		McClellan, Dale	
Pilato, Bryan		Wootan, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margaret		McGill, Andre	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Teams loaded staged soil into drums and collected the associated soil samples. 1000 Intrusive operations were suspended for the day due to excessive heat. Site personnel performed end of week vehicle and equipment maintenance.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**7/13/2017 Thursday**
Weather:	**Mostly Sunny 75-95°F, wind 0-7 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Site personnel continued intrusive operations in Area B, grid 10/-90 and 30/-90. Crews filled 15 soil drums and collected 5 VOC and 5 composite samples and submitted for headspace. Transported 15 soil drums and 1 water drum to the federal property site. Intrusive work ended early due to heat.**
Summary:	**Site personnel continued intrusive operations in Area B, grid 10/-90 and 30/-90. Crews filled 15 soil drums and collected 5 VOC and 5 composite samples and submitted for headspace (See COC for IDs). Transported 15 soil drums and 1 water drum to the federal property site (See Drum Manifest for IDs). Intrusive work ended early due to heat.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**7/13/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Pg	
1500	7-13-17
0630	SAFETY BRIEF.
0700	RADIO CHECKS. PDS UP
0709	TRAFFIC SIGNS IN PLACE.
0716	MINICAMS & DRAMS OP.
0738	TEAM 3 DWN RANGE. FILLING DRUMS.
	SPONSE, MANTELL MANGOSH.
0748	VOC 126 COLLECTED. WBGT @ 82.0
0800	SOIL DRUMS 1192 1194 FILLED & COMPOSITE COLLECTED
0801	VOC 127 COLLECTED.
0814	SOIL DRUMS 1195-1197 FILLED & COMPOSITE COLLECTED.
0815	VOC 128 COLLECTED
0826	SOIL DRUMS 1198 - 1200 FILLED & COMPOSITE COLLECTED.
0843	VOC 129 COLLECTED. WBGT @ 89.0
0857	SOIL DRUMS 1201-1203 FILLED & COMPOSITE COLLECTED.
0858	VOC 130 COLLECTED.
0909	SOIL DRUMS 1204-1206 FILLED & COMPOSITE COLLECTED.
0912	TEAM 3 CLEARED PDS.
0925	TEAM 1 DOWN RANGE WBGT @ 90.1
	SOIL DRUMS 1192-1206 AND AQ DRUM 570
	LOADED FOR FED PROPERTY.
0950	TEAM 1 CLEARED PDS.
1005	INTRUSIVE OPS SECURED DUE TO HEAT WBGT @ 90.1
1100	CONFERENCE CALL
1140	CONFERENCE CALL COMPLETE

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 17 July 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot W/ thunder storms Low 80° High 96°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Nguyen, Phuong	
Malone, Forrest	Prate, Warren	Privett, Arlita	
	Yorkshire, Bart	PalePale, Magareth	
Marian, Jed			
Matter, Phil		Davis, Torry	
Nelms, Bobby		Ford, Bennie	
Oien, Joshua		McClellan, Dale	
Pilato, Bryan		Wootan, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margaret		McGill, Andre	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel worked to expose both ends of the water line going to the 4835 property in preparation for the reroute on Thursday. Maintenance contractor from ACI made repairs to the AC units for the 4835 property. Teams dumped roll off boxes and performed equipment inventory. At 1400 after lightning holds the team prepared to resume filling drums with staged soil, more lightning holds stopped this effort. At 1515 Teams began marking the line for an 8 foot right of way from the property line and take photographs. At 1535 this effort was again interrupted by lightning.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**7/17/17 Monday**
Weather:	**Thunderstorms in the afternoon 75-85ºF, wind 0-11 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Site personnel continued intrusive operations in Area B, grid 10/-90 and 30/-90. Sent samples to APPL for low characterization. Crews excavated area around water pipe. Crews dumped cleared roll-offs at Federal Property and conducted inventory. Lightening hold in the afternoon.**
Summary:	**Site personnel continued intrusive operations in Area B, grid 10/-90 and 30/-90. Sent samples (2 composites and 7 VOC) to APPL for low characterization (See APPL COC for IDs). Crews excavated area around water pipe. Crews dumped cleared roll-offs at Federal Property and conducted inventory. Lightening hold in the afternoon.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**7/17/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Pg	
1	7-17-17
0630	SAFETY BRIEF.
0650	RADIO CHECKS.
0652	PDS UP.
0733	MINICAMS UP.
0740	DAAMS PUMPS RUNNING
0744	TEAM 1 DOWN RANGE WBGT @ 79.2
0826	TEAM 1 CLEARED PDS. RIBER, DION, COURTNEY
0835	TEAM 2 DOWN RANGE. WURSCHER, MARION, MAJOR.
0933	TEAM 2 CLEARED PDS
0939	TEAM 3 DOWN RANGE SPROUSE, PIJADO
0944	WBGT @ 86.0
1008	TEAM 3 CLEARED PDS.
1019	TEAM 1 DOWN RANGE, RIBER, DION, COURTNEY
	WBGT @ 90.3
1035	TEAM 1 CLEARED PDS.
1050	ACI NC REPAIR ON SITE.
1130	STARTING MID DAY CHALLENGE, ACI OFF SITE.
1154	MID DAY CHALLENGE COMPLETE
1240	LIGHTNING HOLD.
1315	OFF LIGHTNING HOLD.
1404	LIGHTNING HOLD.
1434	OFF LIGHTNING HOLD.
1438	LIGHTNING HOLD.
1508	OFF LIGHTNING HOLD.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 18 July 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot W/ thunder storms Low 71° High 93°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Nguyen, Phuong	
Malone, Forrest	Prate, Warren	Privett, Arlita	
	Yorkshire, Bart	PalePale, Magareth	
Marian, Jed			
Matter, Phil		Davis, Torry	
Nelms, Bobby		Ford, Bennie	
Oien, Joshua		McClellan, Dale	
Pilato, Bryan		Wootan, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margaret		McGill, Andre	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel completed exposing both ends of the water line going to the 4835 property in preparation for the reroute on Thursday. Teams filled 55 gallon poly drums with staged soil. Site personnel continued intrusive operations in area B, grid 10/-90 and 30/-90, they created a stockpile for future barrel filling operations.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**7/18/2017 Tuesday**
Weather:	**Mostly Cloudy 73-90ºF, wind 0-8 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Site personnel continued intrusive operations in Area B, grid 10/-90 and 30/-90. Sent samples to ECBC for low level analysis. Collected 5 composite and 5 VOC samples. Submitted samples for headspace. Transported 15 soil drums and 1 PPE drum to federal property site.**
Summary:	**Site personnel continued intrusive operations in Area B, grid 10/-90 and 30/-90. Sent samples to ECBC for low level analysis (See Low Level COC for IDs). Collected 5 composite and 5 VOC samples. Submitted samples for headspace (See Headspace COC for IDs). Transported 15 soil drums and 1 PPE drum to federal property site (See Drum Manifest for IDs). Thunderstorms and lightening hold in the afternoon.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**7/18/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**



Pg

4 7-18-17

1110 SOIL DRUMS 1216-1218 FILLED & COMPOSITE COLLECTED.

1111 VOC 135 COLLECTED.

1124 SOIL DRUMS 1219-1221 FILLED & COMPOSITE COLLECTED.

1131 TEAM 3 CLEARED PDS.

1132 STARTING MIDDAY CHALLENGE

1200 MIDDAY COMPLETE. WBGT@ 93.5

1250 SOIL DRUMS 1207 THRU 1221 AND PPE DRUM 391 LOADED FOR FED PROPERTY.

1330 WBGT@ 82.4

1332 TEAM 2 DOWN RANGE, WONSCHEL, MARION, MALONE.

1406 TEAM 2 CLEARED PDS.

1410 TEAM 3 DOWN RANGE SEMONSE, PICATO

1422 LIGHTNING HOLD.

1424 TEAM 3 CLEARED PDS.

1518 OFF LIGHTNING HOLD.

1527 STARTING END OF DAY CHECKS.

1701 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 19 July 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 76° High 98°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Nguyen, Phuong	
Malone, Forrest	Prate, Warren	Privett, Arlita	
Mantell, Dawn	Yorkshire, Bart	PalePale, Magareth	
Marian, Jed			
Matter, Phil		Davis, Torry	
Nelms, Bobby		Ford, Bennie	
Oien, Joshua		McClellan, Dale	
Pilato, Bryan		Wootan, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margaret		McGill, Andre	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Team personnel continued intrusive operations in area B, grid 10/-90 and 30/-90 removing more material using hand excavation techniques. Teams loaded excavated soil into drums and collected the associated soil samples. At 1400 Parsons and Zimmer personnel went to the federal property site to dump roll off boxes.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**7/19/2017 Wednesday**
Weather:	**Mostly Cloudy 73-90°F, wind 0-8 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Site personnel continued intrusive operations in Area B, grid 10/-90 and 30/-90. Sent samples to ECBC for low level analysis (See Low Level COC for IDs). Collected 5 composite and 5 VOC samples. Submitted samples for headspace (See Headspace COC for IDs). Transferred 15 soil drums and 1 scrap drum to federal property (See Drum Manifest for IDs).**
Summary:	**Site personnel continued intrusive operations in Area B, grid 10/-90 and 30/-90. Sent samples to ECBC for low level analysis (See Low Level COC for IDs). Collected 5 composite and 5 VOC samples. Submitted samples for headspace (See Headspace COC for IDs). Transferred 15 soil drums and 1 scrap drum to federal property (See Drum Manifest for IDs).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**7/19/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

PG

5 7-19-17

0630 SAFETY BRIEF.

0646 PDS UP.

0700 RADIO CHECKS.

0725 MINICAMS UP

0736 DAAMS PUMPS RUNNING

0737 TEAM 1 DOWN RANGE, RIDER, OLEN WGT @ 75.0

0836 TEAM 1 CLEARED. PDS WGT @ 82.5

0832 TEAM 2 DOWN RANGE. WONSCHET, MARION, MALONE

0902 TEAM 2 CLEARED PDS "101.2"

0906 TEAM 3 DOWN RANGE. SPROUSE, PALATO, MANTELL
WGT @ 88.3

0923 TEAM 3 CLEARED PDS. "99.0"

0951 TEAM 1 DOWN RANGE RIDER, OLEN, WGT @ 84.7

1036 TEAM 1 CLEARED PDS "99.7"

1038 TEAM 2 DOWN RANGE. WONSCHET, MARION, MANLOSH
WGT @ 89.8

1050 VOC 136 COLLECTED.

1104 SOIL DRUMS 1222-1224 FILLED & COMPOSITE COMPLETED

1108 TEAM 2 CLEARED PDS "100.1"

1120 TEAM 3 DOWN RANGE. SPROUSE, MANTELL, MANLOSH

1115 VOC 137 COLLECTED

1126 SOIL DRUMS 1225-1227 FILLED & COMPOSITE COMPLETED.

1127 VOC 138 COLLECTED.

1136 SOIL DRUMS 1228-1230 FILLED & COMPOSITE COMPLETED.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 20 July 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 74° High 99°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Nguyen, Phuong	
Malone, Forrest	Prate, Warren	Privett, Arlita	
Mantell, Dawn	Yorkshire, Bart	PalePale, Magareth	
Marian, Jed			
Matter, Phil		Davis, Torry	
Nelms, Bobby		Ford, Bennie	
Oien, Joshua		McClellan, Dale	
Pilato, Bryan		Wootan, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margaret		McGill, Andre	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons and Zimmer personnel worked at the federal property site weighing soil drums in preparation for shipment. Parsons subcontractor ACI worked at the 4825 Glenbrook site installing the temporary reroute of the waterline.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**7/20/2017 Thursday**
Weather:	**Partly Cloudy 78-96°F, wind 0-8 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**None**
Activities Conducted:	**No intrusive activities for today. Teams weighed soil drums and recorded measurements at federal property. ACI on-site for temporary re-route**
Summary:	**No intrusive activities for today. Teams weighed soil drums and recorded measurements at federal property. ACI on-site for temporary re-route**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**7/20/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Pg 1	7-20-17
0630	SAFETY BRIEF.
0640	ACI ON SITE. NO INTRUSIVE OPERATIONS. ACI WILL WORK TO REMOVE TEMPORARY WATER LINE FOR 4135. THE TEAMS WILL BE WORKING AT FEDERAL PROPERTY.
0649	TRAFFIC SIGNS IN PLACE.
1150	CONFERENCE CALL
1130	CONFERENCE CALL OVER.
1434	ACI OFF SITE.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 21 July 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 74° High 99°

Personnel on Site

PARSONS	ZES	ECBC	
Nelms, Bobby			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
		CENAB	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons subcontractor ACI worked at the 4825 Glenbrook site completing the temporary reroute of the waterline.

End of Day: 1130

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Sensitive



PG

8 7-21-17

0630 SAFETY BRIEF

0724 AC I ON SITE, WORKING TO TIE TOWER.

TEMPORARY WATER LINE TO 4835.

1100 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 24 July 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 71° High 92°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Bobal, Brandon	
Malone, Forrest		Privett, Arlita	
Mantell, Dawn	Yorkshire, Bart	Askew, Tom	
Marian, Jed			
Matter, Phil		Davis, Torry	
Nelms, Bobby		Ford, Bennie	
Oien, Joshua		McClellan, Dale	
Pilato, Bryan		Bagley, Robert	
Rider, Matthew		Myers, Royce	
Rockwell, Margaret		Baker, Dawn	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Teams pumped water that had ponded over the weekend due to severe rainstorms experienced over the weekend. Transported water drums to federal property. No intrusive operations were conducted today.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**7/24/2017 Monday**
Weather:	**Partly Cloudy 69-90°F, wind 0-8 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Teams pumped water that had ponded over the weekend due to severe raintstorms experienced over the weekend. Transported water drums to federal property.**
Summary:	**Teams pumped water that had ponded over the weekend due to severe raintstorms experienced over the weekend. Transported water drums to federal property (See Drum Transfer Manifests 1, 2, and 3 for IDs).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**7/24/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Sensitive

Pg 9

7-24-17

0630 SAFETY BRIEF

0645 RADIO CHECKS.

0654 PDS UP & TRAFFIC SIGNS IN PLACE.

0745 STAKE BED TRUCK ON SITE, PUMPING WATER. TEAM 1 DOWN RANGE.

1049 WATER DRUMS 572 THRU 589 FILLED, LOADED FOR FED PROPERTY.

1215 TEAM 2 PUMPING WATER

1346 WBGT@ 87.6

1350 WATER DRUMS 590 THRU 604 LOADED FOR FED PROPERTY.

1453 TEAM 1 PUMPING WATER.

1540 WATER DRUMS 605 THRU 610 LOADED FOR FED PROPERTY.

1550 STARTING END OF DAY CHECKS.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 25 July 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 70° High 88°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Bobal, Brandon
Malone, Forrest	Prate, Warren	Privett, Arlita
Mantell, Dawn	Yorkshire, Bart	Askew, Tom
Marian, Jed		
Matter, Phil		Davis, Torry
Nelms, Bobby		Ford, Bennie
Oien, Joshua		McClellan, Dale
Pilato, Bryan		Bagley, Robert
Rider, Matthew		Myers, Royce
Rockwell, Margaret		Baker, Dawn
Sprouse, Mark		
Wunschel, Reina		
	ACCUPERMIT	**CHENC**
	Schmidt, James	Boles, Judson
	Buhl, John	
		CENAB
		Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Teams removed about 9ft of the retaining wall and excavated behind it using hand digging techniques. Teams swept construction pad. Sent 5 samples to ECBC for low level analysis.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**7/25/2017 Tuesday**
Weather:	**Partly Cloudy 66-80°F, wind 0-9 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Teams removed about 9ft of the retaining wall and excavated behind it using hand digging techniques. Teams swept construction pad. Sent 5 samples to ECBC for low level analysis.**
Summary:	**Teams removed about 9ft of the retaining wall and excavated behind it using hand digging techniques. Teams swept construction pad. Sent 5 samples to ECBC for low level analysis (See Low Level COC for IDs).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**7/25/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Pg

10 7-25-17

0630 SAFETY BRIEF

0650 REINA WONSCHEL REPORTS THAT FORREST MALONE HURT HIS RIGHT HAND ON 7/24/17. SHE SAID THAT FORREST TOLD HER YESTERDAY THAT HE HAD HURT IT, BUT SHE FORGOT TO REPORT IT. THERE IS BRUISING TO HIS RIGHT PALM. MR. MALONE WAS INSTRUCTED TO CONTACT WORK CARE.

RADIO CHECKS, TRAFFIC SIGNS IN PLACE.

0734 MINICAMS & DAAMS UP.

0740 TEAM 1 DOWN RANGE. RIVER, OLON, COURTNEY MANGOSH. CUTTING RETAINING WALL W/ ROCK SAW.

0917 TEAM 1 CLEARED PDS. APPROXIMATELY 89' OF RETAINING WALL WAS CUT AND MOVED FOR SAMPLING. CALM & GLASS WAS UNDERWALL.

0924 TEAM 2 DOWN RANGE. WONSCHEL, MARION, MALONE, MANGOSH. WBGT @ 74.5

1100 TEAM 2 CLEARED PDS.

STARTING MID DAY CHALLENGE.

1127 MID DAY CHALLENGE COMPLETE.

1151 TEAM 3 DOWN RANGE. SPROOSE, PILATO, MANTELL. WBGT @ 77.8

1313 TEAM 3 CLEARED PDS.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 26 July 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 73° High 84°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Bobal, Brandon
Malone, Forrest	Prate, Warren	Privett, Arlita
Mantell, Dawn	Yorkshire, Bart	Askew, Tom
Marian, Jed		
Matter, Phil		Davis, Torry
Nelms, Bobby		Ford, Bennie
Oien, Joshua		McClellan, Dale
Pilato, Bryan		Bagley, Robert
Rider, Matthew		Myers, Royce
Rockwell, Margaret		Baker, Dawn
Sprouse, Mark		
Wunschel, Reina		
	ACCUPERMIT	**CHENC**
	Schmidt, James	Boles, Judson
	Williams, Angelo	
		CENAB
		Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Teams continued intrusive activities in grid (30, -90). Cut retaining wall and excavated behind retaining wall using hand and mechanical techniques. Filled 39 soil drums and collected 13 associated composite and VOC soil samples. Submitted samples for headspace. Transferred 30 soil drums to federal property.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**7/26/2017 Wednesday**
Weather:	**Partly Cloudy 69-82°F, wind 0-4 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Teams continued intrusive activities in grid (30, -90). Cut retaining wall and excavated behind retaining wall using hand and mechanical techniques. Filled 39 soil drums and collected 13 associated composite and VOC soil samples. Submitted samples for headspace. Transfered 30 soil drums to federal property.**
Summary:	**Teams continued intrusive activities in grid (30, -90). Cut retaining wall and excavated behind retaining wall using hand and mechanical techniques. Filled 39 soil drums and collected 13 associated composite and VOC soil samples. Submitted samples for headspace. Transfered 30 soil drums to federal property.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**7/26/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Pg	
12	7-26-17
0630	SAFETY BRIEF.
0650	RADIO CHECKS. PDS UP
•	TRAFFIC SIGNS IN PLACE.
0733	MINICAMS & DAAMS UP.
0755	TEAM 1 DOWN RANGE. RIDER, OLEN, COURTNEY
	WBGT @ 65.9 CUTTING RETAINING WALL
	w/ ROCK SAW.
1009	TEAM 1 CLEARED PDS.
1011	TEAM 2 DOWN RANGE WONSCHEL, MARION, MALONE
1038	VOC 141 COLLECTED
1059	SOIL DRUMS 1237-1239 FILLED & COMPOSITE COLLECTED.
1102	VOC 142 COLLECTED.
1114	SOIL DRUMS 1240-1242 FILLED & COMPOSITE COLLECTED
1117	VOC 143 COLLECTED
1130	SOIL DRUMS 1243-1245 FILLED & COMPOSITE COLLECTED.
1135	VOC 144 COLLECTED.
1149	SOIL DRUMS 1246-1248 FILLED & COMPOSITE COLLECTED.
1153	VOC 145 COLLECTED.
1207	SOIL DRUMS 1249-1251 FILLED & COMPOSITE COLLECTED.
1214	TEAM 2 CLEARED PDS. STARTING MID DAY
	CHALLENGE
1243	MID DAY CHALLENGE COMPLETE
1255	TEAM 3 DOWN RANGE. SPROUSE, PICATO, MANTELL
	WBGT @ 85.8. MWGOSH

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 27 July 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 77° High 88°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Bobal, Brandon
Malone, Forrest	Prate, Warren	Privett, Arlita
Mantell, Dawn	Yorkshire, Bart	Askew, Tom
Marian, Jed		
Matter, Phil		Davis, Torry
Nelms, Bobby		Ford, Bennie
Oien, Joshua		McClellan, Dale
Pilato, Bryan		Bagley, Robert
Rider, Matthew		Myers, Royce
Rockwell, Margaret		Baker, Dawn
Sprouse, Mark		
Wunschel, Reina		
Wunschel, Scott	**ACCUPERMIT**	**CHENC**
	Schmidt, James	Boles, Judson
	Williams, Angelo	
		CENAB
		Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Teams continued intrusive activities in grid 30/-90. Teams filled 18 drums and collected 6 associated composite and VOC samples. Submitted samples for headspace. Sent samples to APPL for disposal characterization.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**7/27/2017 Thursday**
Weather:	**Cloudy 72-87°F, wind 0-8 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Teams continued intrusive activities in grid 30/-90. Teams filled 18 drums and collected 6 associated composite and VOC samples. Submitted samples for headspace. Sent samples to APPL for disposal characterization.**
Summary:	**Teams continued intrusive activities in grid 30/-90. Teams filled 18 drums and collected 6 associated composite and VOC samples. Submitted samples for headspace (See headspace COC for IDs). Transported drums to federal property (See Drum Manifest 1 and 2 for IDs). Sent samples to APPL for disposal characterization (See APPL COC for IDs).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**7/27/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**



Pc	
15	7-27-17
0630	SAFETY BRIEF
0651	PDS UP
0700	RADIO CHECKS
0725	MINICAMS & DAAMS UP.
0732	TEAM 2 DOWN RANGE WUNSCHEL, MARION, MALONE
	MANGOSH. WBGT@ 71.4
0741	VOC 154 COLLECTED
0755	SOIL DRUMS 1276-1278 FILLED & COMPOSITE COLLECTED.
0813	SOIL DRUMS 1267 THRU 1278 LOADED FOR
	FED PROPERTY.
0910	TEAM 2 CLEARED PDS. WBGT @ 73
0916	TEAM 3 DOWN RANGE SPROUSE, MANTELL, PICATO
1002	TEAM 3 CLEARED PDS.
1013	TEAM 1 DOWN RANGE RIDER, OLEN, COURTNEY.
	MANGOSH. WBGT @ 82.5
1028	VOC 155 COLLECTED
1036	THE "A" POINT DAAMS CONFIRMATION PUMP
	WAS REPLACED.
1049	SOIL DRUMS 1279-1281 FILLED & COMPOSITE COLLECTED.
1051	VOC 156 COLLECTED.
1103	SOIL DRUMS 1282-1284 FILLED & COMPOSITE COLLECTED.
1106	VOC 157 COLLECTED
1121	SOIL DRUMS 1285-1287 FILLED & COMPOSITE COLLECTED.
1129	TEAM 1 CLEARED PDS.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 31 July 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 67° High 87°

Personnel on Site

PARSONS	ZES	ECBC	
	Mangosh, Ed	Dusick, Brandon	
Malone, Forrest	Prate, Warren	Harris, Tom	
Mantell, Dawn	Yorkshire, Bart	Askew, Tom	
Marian, Jed	Zimmer, Doug		
Matter, Phil		Bagley, Robert	
Nelms, Bobby		Myers, Royce	
Oien, Joshua		Baker, Dawn	
Pilato, Bryan		Rowell, Will	
Rider, Matthew		Guyer, Gary	
Rockwell, Margaret		Shavers, Dedrick	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James		
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel worked to pump rainwater from the excavation, Approximately 4,250 gallons were pumped and transferred to the federal property site. In the afternoon teams excavated and staged soil in grid 30/-90.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report	
Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**7/31/2017 Monday**
Weather:	**Mostly Sunny 68-85°F, wind 0-4 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Teams pumped water that had accumulated from the weekend storms and transported to Fed Property using tanks. Pumped approximately 4250 gallons of water. Sent samples to APPL for disposal characterization. Teams excavated cleaned up area that had the ponded water from the weekend storms.**
Summary:	**Teams pumped water that had accumulated from the weekend storms and transported to Fed Property using tanks. Sent samples to APPL for disposal characterization (See COC for IDs).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**7/31/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**



Pg	
17	7-31-17
0630	SAFETY BRIEF.
0700	RADIOCHECKS TRAFFIC SIGNS IN PLACE
0730	MINICAMS UP.
0800	PUMPING WATER
1148	DAAMS PUMPS RUNNING, STARTING MIDDAY CHALLENGE.
1300	MIDDAY CHALLENGE COMPLETE.
1308	TEAM 3 DOWN RANGE. SPROUSE, MANTELL, PILATO MANGOSH. WBGT @ 86.4
1404	TEAM 3 CLEARED PDS.
1408	TEAM 1 DOWN RANGE RIDER, OLEN, MANGOSH.
1508	TEAM 1 CLEARED PDS.
1522	TEAM 3 DOWN RANGE. SPROUSE MANTELL, PILATO.
1545	CONFERENCE CALL W/ SEAN BACKLEY, ED GRUNWALD, SCOTT WUNSCHEL, & JANELLE RENICAL. TOPIC: CONCRETE SAMPLING SOP/AHA.
1700	SECURED.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 01 August 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 73° High 88°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Dusick, Brandon	
Malone, Forrest	Prate, Warren	Harris, Tom	
Mantell, Dawn	Yorkshire, Bart	Askew, Tom	
Marian, Jed	Zimmer, Doug		
Matter, Phil		Bagley, Robert	
Nelms, Bobby		Myers, Royce	
Oien, Joshua		Baker, Dawn	
Pilato, Bryan		Rowell, Will	
Rider, Matthew		Guyer, Gary	
Rockwell, Margaret		Shavers, Dedrick	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Buhl, John		
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

One team worked at the federal property site pumping storm water from drums into a large storage tank. Intrusive teams continued excavating and staging soil in grid 30/-90. In the afternoon personnel drummed up the staged soil and transported drums to the federal property site. 26 drums were filled.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**8/1/2017 Tuesday**
Weather:	**Mostly Sunny 68-85°F, wind 0-4 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Teams continued intrusive operations in grid (30, -90). Sent samples to ECBC for low level analysis. Teams excavated in grid (30, -90) using hand and mechanical techniques. Transported drums to federal property. Collected one composite and VOC sample and submitted for headspace. Submitted scrap glass for headspace. Filled 26 drums.**
Summary:	**Teams continued intrusive operations in grid (30, -90). Sent 19 samples to ECBC for low level analysis (See Low Level for IDs). Teams excavated in grid (30, -90) using hand and mechanical techniques. Transported drums to federal property (See Drum Manifest 1 for IDs). Collected one composite (RA-4825GR-Area B-01-080117) and VOC sample(RA-4825GR-Area B-VOC-080117-01) and submitted for headspace. Submitted scrap glass for headspace (RA-4825GR-SCR-510). Filled 26 drums.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**8/1/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Pa	
18	8-1-17
0630	SAFETY BRIEF
0700	RADIO CHECKS TRAFFIC SIGNS IN PLACE
0728	MINICAMS & DARMS UP.
0800	SEAN BULLIEY & FRANK CANTWELL ON SITE.
0855	TEAM 1 DOWN RANGE, RIDER, OIEN, COURTNEY
0900	WBGT @ 80.0
0945	TEAM 1 CLEARED PDS.
1004	TEAM 3 DOWN RANGE, SPROUSE, MANTELL, PILATO
	WBGT @ 82.6
1037	TEAM 3 CLEARED PDS.
1104	TEAM 1 DOWN RANGE, RIDER, OIEN, COURTNEY
1139	TEAM 1 CLEARED PDS.
	STARTING MID DAY CHALLENGE.
1231	MID DAY CHALLENGE COMPLETE WBGT @ 87.4
1238	TEAM 3 DOWN RANGE, SPROUSE, MANTELL, PILATO MANGOSA
1254	VOC 160 COLLECTED
1327	~~SOIL DRUMS 1294-1296 FILLED & COMPOSITE COLLECTED~~
1327	TEAM 3 CLEARED PDS.
1333	TEAM 1 DOWN RANGE, RIDER, OIEN, COURTNEY, MANGOSA
1359	DRUMS 1294-1311 FILLED.
1427	DRUMS 1294-1311 LOADED FOR FED PROPERTY.
	TEAM 1 CLEARED PDS.
1446	TEAM 2 DOWN RANGE, WUNSCHEL, MARION, MALONE
	MANGOSA.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 02 August 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 74° High 89°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Dusick, Brandon	
Malone, Forrest	Prate, Warren	Harris, Tom	
	Yorkshire, Bart	Askew, Tom	
Marian, Jed			
Matter, Phil		Bagley, Robert	
Nelms, Bobby		Myers, Royce	
Oien, Joshua		Baker, Dawn	
Pilato, Bryan		Rowell, Will	
Rider, Matthew		Guyer, Gary	
Rockwell, Margaret		Shavers, Dedrick	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Buhl, John		
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel pumped 700 gallons of water from the excavation area, water is from previous night's rain. Team personnel continued intrusive operations in area B, grid 10/-90 and 30/-90 removing more material using hand excavation techniques. Teams loaded excavated soil into drums and collected the associated soil samples.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**8/2/2017 Wednesday**
Weather:	**Mostly Sunny 70-89°F, wind 0-10 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Teams continued intrusive operations in grid (30, -90). Pumped 700 gallons of water from last night's rain event and transported to Baker Tank at federal property. Teams excavated in grid (30,-90) using hand and mechanical techniques. Filled 28 drums and collected one composite and one VOC sample and submitted for headspace.**
Summary:	**Teams continued intrusive operations in grid (30, -90). Pumped 700 gallons of water from last night's rain event and transported to Baker Tank at federal property. Teams excavated in grid (30,-90) using hand and mechanical techniques. Filled 28 drums and collected one composite and one VOC sample and submitted for headspace (See Headspace COC).**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**8/3/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Pg	
20	8-2-17
0630	SAFETY BRIEF.
0700	RADIO CHECKS, TRAFFIC SIGNS UP.
0726	TEAM 1 DOWN RANGE RIDER, OIEN, COURTNEY
	"PUMPING WATER."
0730	MINICAMS UP.
0804	DAAMS PUMPS RUNNING.
0835	TEAM 1 CLEARED PDS.
0838	TEAM 2 DOWN RANGE, WUNSCHEL, MALONE, MARION.
0910	TEAM 2 CLEARED PDS.
0914	TEAM 3 DOWN RANGE, SPRMSE, PZLATO, MANGOSA.
0945	TEAM 3 CLEARED PDS.
0955	TEAM 1 DOWN RANGE, RIDER, OIEN, COURTNEY
	WBGT @ 84.5
1028	TEAM 1 CLEARED PDS.
1032	TEAM 2 DOWN RANGE WBGT @ 88.1 WUNSCHEL,
	MALONE, MARION.
1100	TEAM 2 CLEARED PDS
1126	SOLC DRUMS 1312. 1319, PPE DRUM 395,
	SCR DRUM 509 LOAD FOR FED PROPERTY
1129	STARTING MID DAY CHALLENGE.
1210	MIDDAY CHALLENGE COMPLETE. WBGT @ 89.6
1243	TEAM 1 DOWN RANGE, RIDER, OIEN, COURTNEY.
1307	TEAM 1 CLEARED PDS.
1311	TEAM 2 DOWN RANGE, WUNSCHEL, MARION, MALONE DRAPE

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 03 August 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 73° High 92°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Dusick, Brandon	
Malone, Forrest	Prate, Warren	Harris, Tom	
	Yorkshire, Bart	Askew, Tom	
Marian, Jed			
Matter, Phil		Bagley, Robert	
Nelms, Bobby		Myers, Royce	
Oien, Joshua		Baker, Dawn	
Pilato, Bryan		Rowell, Will	
Rider, Matthew		Guyer, Gary	
Rockwell, Margaret		Shavers, Dedrick	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Buhl, John		
	Williams, Angelo		
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Teams continued intrusive operations in grid (30, -90) using hand and mechanical techniques. Transferred previously filled drums to federal property. Parsons personnel conducted training on concrete sampling procedures.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**8/3/2017 Thursday**
Weather:	**Mostly Sunny 71-88°F, wind 0-4 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Teams continued intrusive operations in grid (30, -90). Teams excavated in grid (30,-90) using hand and mechanical techniques. Transferred drums to federal property (See drum Manifest)**
Summary:	**Teams continued intrusive operations in grid (30, -90). Teams excavated in grid (30,-90) using hand and mechanical techniques. Transferred drums to federal property (See drum Manifest)**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**8/3/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**



PL	
22	8-3-17
0630	SAFETY BRIEF
0700	RADIO CHECKS. TRAFFIC SIGNS IN PLACE.
0810	MINICAMS UP. DAAMS UP @ 07:36
0819	TEAM 2 DOWN RANGE, WONSCHEL, MARION, MALONE MANGOSH.
0916	TEAM 2 CLEARED PDS.
0927	TEAM 3 DOWN RANGE, SPOUSE, PILATO WBGT @ 81.6
1000	TEAM 3 CLEARED PDS.
1013	TEAM 1 DOWN RANGE, RIDER, OLEN, COURTNEY.
1048	TEAM 1 CLEARED PDS.
1052	TEAM 2 DOWN RANGE, WONSCHEL, MALONE, MARION
1129	TEAM 2 CLEARED PDS STARTING MIDDLE.
1143	~~MAN~~ TEAM BACK-UP
1213	TEAM 3 DOWN RANGE, SPOUSE, PILATO, MANGOSH WBGT @ 89.6.
1236	WBGT @ 91.6
1244	TEAM 3 CLEARED PDS.
1249	TEAM 1 DOWN RANGE, LOADING BARRELS. RIDER, OLEN, COURTNEY, MANGOSH.
1300	SOIL DRUMS 1335 THRU 1347 LOADED FOR FED PROPERTY.
1303	TEAM 1 CLEARED PDS.
1400	STARTING END OF DAY CHECKS
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 07 August 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 66° High 75°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Burrell, Dianne	
Malone, Forrest	Prate, Warren	Harris, Brian	
Mantell, Dawn	Yorkshire, Bart	PalePale, Margareth	
Marian, Jed	Zimmer, Doug		
Matter, Phil		Bagley, Robert	
Nelms, Bobby		Myers, Royce	
Oien, Joshua		Baker, Dawn	
Pilato, Bryan		Rowell, Will	
Rider, Matthew		Guyer, Gary	
Rockwell, Margaret		Shavers, Dedrick	
Sprouse, Mark			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James		
	Williams, Angelo		
		CENAB	
		Martin, JR	
		Marks, Scott	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

No intrusive operations due to rain. Site personnel inspected all soil and water drums for dry rotting and cracking. Personnel pumped 2,250 gallons of water from the excavation at 4825 Glenbrook.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report	
Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**8/7/2017 Monday**
Weather:	**Raining throughout the day 66-72°F, wind 0-9 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**No intrusive activities due to rain event. Teams inspected barrels for sun damage at federal property. Teams transferred water to Baker Tank. Sent cleared samples to APPL for waste characterization.**
Summary:	**No intrusive activities due to rain event. Teams inspected barrels for sun damage at federal property. Teams transferred water to Baker Tank. Sent cleared samples to APPL for waste characterization.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**8/7/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**


Po,
23 8-7-17
0630 SAFETY BRIEF
0700 RADIO CHECKS.
1330 LIGHTNING HOLD.
1400 OFF LIGHTNING HOLD.
1430 PUMPING WATER.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 08 August 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 68° High 77°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Burrell, Dianne	
Malone, Forrest	Prate, Warren	Harris, Brian	
Mantell, Dawn	Yorkshire, Bart	PalePale, Margareth	
Marian, Jed	Zimmer, Doug		
Matter, Phil		Bagley, Robert	
Nelms, Bobby		Myers, Royce	
Oien, Joshua		Baker, Dawn	
Pilato, Bryan		Rowell, Will	
Rider, Matthew		Guyer, Gary	
Rockwell, Margaret		Shavers, Dedrick	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James		
	Williams, Angelo		
		CENAB	
		Martin, JR	
		Marks, Scott	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel pumped 450 gallons of water from the excavation/sump area. Intrusive teams continued intrusive operations in area B, grid 50/-90 removing more material using hand excavation techniques. Teams continue to find AUES glass and CACM.

End of Day: 17:00

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**8/8/2017 Tuesday**
Weather:	**Mostly Cloudy 62-80°F, wind 0-8 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Teams continued intrusive operations in grid (50, -90). Teams excavated in grid (50,-90) using hand and mechanical techniques. Sent 2 composite and 2 VOC samples to APPL for disposal characterization. Collected glass (RA-4825GR-SCR-512) and submitted for headspace.**
Summary:	**Teams continued intrusive operations in grid (50, -90). Teams excavated in grid (50,-90) using hand and mechanical techniques. Sent 2 composite and 2 VOC samples to APPL for disposal characterization (See COC for IDs). Collected glass (RA-4825GR-SCR-512) and submitted for headspace.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**8/8/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Sensitive



Pg	
24	8-8-17
0630	SAFETY BRIEF
0650	RADIO CHECKS.
0638	TRAFFIC SIGNS IN PLACE.
0725	MINICAMS UP
0728	TEAM 3 DOWN RANGE PUMPING WATER
	SPROUSE, MANTELL, PILATO
0737	TEAM 3 CLEARED PDS.
0845	TEAM 1 DOWN RANGE. RIDER, OLEN, COURTNEY.
1039	TEAM 1 CLEARED PDS
1117	STARTING MID DAY CHALLENGE.
1135	MID DAY CHALLENGE COMPLETE.
1153	TEAM 2 DOWN RANGE, WUNSCHEL, MARION, MALONE
1321	TEAM 2 CLEARED PDS.
1324	TEAM 3 DOWN RANGE SPROUSE, MANTELL, PILATO
1445	TEAM 3 CLEARED PDS.
1450	TEAM 1 DOWN RANGE. RIDER, OLEN, COURTNEY
1548	TEAM 1 CLEARED PDS. SCR-512- DOUBLE BAGGED
	FOR HEAD SPACE (807 GLASS). STARTING
	END OF DAY CHECKS.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 09 August 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 67° High 89°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Burrell, Dianne	
Malone, Forrest	Prate, Warren	Harris, Brian	
Mantell, Dawn	Yorkshire, Bart	PalePale, Margareth	
Marian, Jed	Zimmer, Doug		
Matter, Phil		Bagley, Robert	
Nelms, Bobby		Myers, Royce	
Oien, Joshua		Baker, Dawn	
Pilato, Bryan		Rowell, Will	
Rider, Matthew		Guyer, Gary	
Rockwell, Margaret		Shavers, Dedrick	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James		
	Williams, Angelo		
		CENAB	
		Martin, JR	
		Marks, Scott	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Intrusive teams continued intrusive operations in area B, grid 50/-90 removing more material using hand excavation techniques. Teams continue to find AUES glass and CACM. Site personnel worked with Veolia loading soil drums for transport the incinerator. At approximately 1430 after clearing the PDS team 3 TL came to the CP and reported that he and another team member had nausea and the TL experienced vomiting. All intrusive operations were suspended and the site safety spoke with both intrusive teams. Both teams had experienced some symptoms, team 1 symptoms were not initially associated with intrusive operations. Parsons site safety notified our CIH, and the on site Baltimore representative. At 1550 Parsons site safety transported seven personnel, teams 1 and 3 to GW Memorial Hospital. At 1600 team 2 who had not been previously down range went in level C to mitigate the excavation area and spoils pile. At 1615 mitigation was complete and team 2 cleared the PDS. At approximately 2050 I received a call from our UXO safety, Bobby Nelms, that all of our personnel have been released from the hospital and are well. At the hospital they were required to shower then had blood and urine samples collected as well as vitals monitored. At this time we do not know when the lab results will be available.

End of Day: 2100

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**8/9/2017 Wednesday**
Weather:	**Sunny 70-83 °F, wind 0-9 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Teams conducted intrusive activities in grid 50, -90. Digging using hand and mechanical techniques, stockpiling soil. Teams aided Veolia at federal property with the waste shipment. Intrusive activities suspended in afternoon due to safety incident.**
Summary:	**Teams conducted intrusive activities in grid 50, -90. Digging using hand and mechanical techniques, stockpiling soil. Teams aided Veolia at federal property with the waste shipment. Intrusive activities suspended in afternoon due to safety incident.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**8/9/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**



Pg

25 8-9-17

0630 SAFETY BRIEF

0700 RADIO CHECKS. TRAFFIC SIGNS IN PLACE.

0725 MINICAMS - 8 AAMS.

0736 TEAM 3 DOWN RANGE SPROUSE, MANTELL, PILATO.

0919 TEAM 3 CLEARED PDS.

0910 TEAM 1 DOWN RANGE, RIDER, GIBSON, COURTNEY

1015 TEAM 1 CLEARED PDS. WBGT @ 82.0

1047 TEAM 3 DOWN RANGE SPROUSE, MANTELL, PILATO

MCINTOSH. WBGT @ 81.1

1130 TEAM 3 CLEARED PDS. STARTING MID DAY CHALLENGE

1148 MID DAY CHALLENGE COMPLETE.

1220 TEAM 1 DOWN RANGE RIDER, GIBSON, COURTNEY

1308 TEAM 1 CLEARED PDS.

1331 TEAM 3 DOWN RANGE, SPROUSE, MANTELL, PILATO

1405 WBGT @ 81.9

1416 TEAM 3 CLEARED PDS.

1427 MARK SPROUSE COMPLAINED OF VOMITING AND NAUSEA. SHAWN MANTELL ALSO REPORTS NAUSEA

1430 3 SPIKE W/ MATT RIDER. HE REPORTS BARKING / ITCHY EYES. BRUCE COURTNEY REPORTS NAUSEA. JOSH GIBSON REPORTS HAVING DIARRHEA.

1448 SR MARTIN AND ED CRUNNARD NOTIFIED ABOUT THE REPORTED SYMPTOMS.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 10 August 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 68° High 88°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Burrell, Dianne	
Malone, Forrest	Prate, Warren	Harris, Brian	
Mantell, Dawn	Yorkshire, Bart	PalePale, Margareth	
Marian, Jed	Zimmer, Doug		
Matter, Phil		Bagley, Robert	
Nelms, Bobby		Myers, Royce	
		Baker, Dawn	
Pilato, Bryan		Rowell, Will	
		Guyer, Gary	
Rockwell, Margaret		Shavers, Dedrick	
Sprouse, Mark		Landers, Brian	
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James		
	Williams, Angelo		
		CENAB	
		Martin, JR	
		Marks, Scott	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Teams continued conducted general site cleanup and maintenance at the federal property site. CP personnel spent the entirety of the day on conference calls discussing the Wednesday afternoon incident.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



28 1-10-17

0630 SAFETY BRIEF

0758 RADIO CHECKS.

0958 FBG RAINWALD, JANELLE BOUCAL AND MIKE COSH WERE UPDATED ON YESTERDAY'S EVENTS.

1100 CONFERENCE CALL / PDT CALL.

1210 CALLS COMPLETE

1245 CONFERENCE CALL W/ PARSONS

1415 CALL COMPLETE.

1500 PDT CONFERENCE CALL.

1550 CALL COMPLETE

NOTE: DR. DORSEY W/ EDGEWOOD MEDICAL WILL CALL JAMES BETZ WITH GW HOSPITAL ABOUT BLOOD PANELS.

1710 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 11 August 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 71° High 91°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	
Malone, Forrest	Prate, Warren	
Matter, Phil		Landers, Brian
Nelms, Bobby		McGill, Andre
		Wooten, Mike
		Rowell, Will
		Guyer, Gary
		Shavers, Dedrick
Sprouse, Mark		Landers, Brian
Wunschel, Reina		
Wunschel, Scott	**ACCUPERMIT**	**CHENC**
	Arteaga, Carlos	
	Williams, Angelo	
		CENAB
		Martin, JR
		Marks, Scott

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

A small crew of Parsons and Zimmer personnel worked for a few hours bolstering the mitigation of the spoils pile and the excavation area.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



28 1-10-17

0630 SAFETY BRIEF

0758 RADIO CHECKS.

0958 FBG RAINWALD, JANELLE BOUCAL AND MIKE COSH WERE UPDATED ON YESTERDAY'S EVENTS.

1100 CONFERENCE CALL / PDT CALL.

1210 CALLS COMPLETE

1245 CONFERENCE CALL W/ PARSONS

1415 CALL COMPLETE.

1500 PDT CONFERENCE CALL.

1550 CALL COMPLETE

NOTE: DR. DORSEY W/ EDGEWOOD MEDICAL WILL CALL JAMES BETZ WITH GW HOSPITAL ABOUT BLOOD PANELS.

1710 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 14 August 2017
Site Location: 4825 Glenbrook Road

Weather:
sunny and hot Low 67° High 83°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Elliot, Laura	
Malone, Forrest	Prate, Warren	Harris, Brian	
Mantell, Dawn	Yorkshire, Bart	PalePale, Margareth	
Marian, Jed	Zimmer, Doug		
Matter, Phil		Rowell, Will	
Nelms, Bobby		Guyer, Gary	
Oien, Joshua		Shavers, Dedrick	
Pilato, Bryan		Wooten, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margaret		McGill, Andre	
Sprouse, Mark		Henderson, Amos	
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Marks, Scott	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel pumped water from the sump area then added clean soil on plastic and geo textile cloth along the basement wall of the 4835 house.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**8/14/2017 Monday**
Weather:	**Cloudy 71-77°F, wind 0-3 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Teams pumped water that had ponded from weekend rainstorms and transported to federal property. Crews brought in clean backfill, lined previously excavated areas in prepartion to backfill in order to mitigate ponding.**
Summary:	**Teams pumped water that had ponded from weekend rainstorms and transported to federal property. Crews brought in clean backfill, lined previously excavated areas in prepartion to backfill in order to mitigate ponding.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**8/14/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Pg	
30	8-14-17
0630	SAFETY BRIEF
0700	RADIO CHECKS. THE TEAMS ARE WORKING ON STATEMENT
0730	MINICAMS UP
0935	DAMS PUMPS RUNNING
1015	TEAM 2 IN TYVEK "F" WUNSHER MALONE COURTNEY, PRATT. PUMPING WATER FROM EXCAVATION
1125	TEAM 2 CLEARED PDS. 100-2 STARTING MIDDAY CHALLENGE
1209	MIDDAY CHALLENGE COMPLETE.
1230	TEAM 3 DOWN RANGE. NON-INTRUSIVE OPERATIONS. GEO & BACK FILL. SPOUSE MANTELL PILATO.
1404	TEAM 3 CLEARED PDS 99.8
1409	TEAM 1 DOWN RANGE. RIDER OIEN COURTNEY. BACKFILLING HOUSE WALL @ 835
1500	PDT CALL
1507	TEAM 1 CLEARED PDS 100.4
1640	PDT CALL OVER
1700	Day Complete.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 15 August 2017
Site Location: 4825 Glenbrook Road

Weather:
Hot with rain showers Low 74° High 81°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Elliot, Laura	
Malone, Forrest	Prate, Warren	Harris, Brian	
Mantell, Dawn	Yorkshire, Bart	PalePale, Margareth	
Marian, Jed	Zimmer, Doug		
Matter, Phil		Rowell, Will	
Nelms, Bobby		Guyer, Gary	
Oien, Joshua		Shavers, Dedrick	
Pilato, Bryan		Wooten, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margaret		McGill, Andre	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Marks, Scott	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel performed general site maintenance at the federal property site in the morning. In the late morning the site experienced a large rain event, 3.12 inches. After the rain subsided teams pumped water from the sump and surrounding area, 7,500 gallons was pumped. We estimate 2 to 3 thousand gallons remain.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
Campbell, Ralph	
Roeske, Ashley	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**8/15/2017 Tuesday**
Weather:	**Cloudy with severe rainstorms in the morning 70-78°F, wind 0-3 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews conducted maintenance activities at Federal Property. Teams pumped approximately 7,500 gallons of water that had ponded from severe rainstorms experienced today.**
Summary:	**Crews conducted maintenance activities at Federal Property. Teams pumped approximately 7,500 gallons of water that had ponded from severe rainstorms experienced today.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**8/15/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Pg

31 8-15-17

0630 SAFETY BRIEF

0750 RADIO CHECKS. TRAFFIC SIGNS IN PLACE.

1145 STARTING TO PUMP WATER.

1655 COMPLETED WATER PUMPING, FOR A TOTAL OF 10 LOADS.
NOTE: RALPH CAMPBELL AND ASHLEY ROESKE W/ USAGE ON SITE.

1700 SECURED

SF

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 16 August 2017
Site Location: 4825 Glenbrook Road

Weather:
Hot with rain showers Low 73° High 84°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Elliot, Laura	
Malone, Forrest	Prate, Warren	Harris, Brian	
Mantell, Dawn	Yorkshire, Bart	PalePale, Margareth	
Marian, Jed	Zimmer, Doug		
Matter, Phil		Rowell, Will	
Nelms, Bobby		Guyer, Gary	
Oien, Joshua		Shavers, Dedrick	
Pilato, Bryan		Wooten, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margaret		McGill, Andre	
Sprouse, Mark		Henderson, Amos	
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Marks, Scott	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel performed sampling of the spoils pile and excavation area with DAMMS pumps. After the sampling operation was complete personnel resumed the water pumping operation from Tuesdays rain event.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**8/16/2017 Wednesday**
Weather:	**Heavy Fog in morning 71-87°F, wind 0-2 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews conducted level B operations to place DAAMS tubes and run them for 2 hours to collect samples. Crews pumped ponded water in the afternoon from rain event on 8/15/2017.**
Summary:	**Crews conducted level B operations to place DAAMS tubes and run them for 2 hours to collect samples. Crews pumped ponded water in the afternoon from rain event on 8/15/2017.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**8/16/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Pg	
32	8-16-17
0630	SAFETY BRIEF
0700	RADIO CHECKS TRAFFIC SIGN IN PLACE.
0710	OPERATIONAL BRIEF.
0728	MINICAMS UP.
0803	TEAM 1 DOWN RANGE, MOD "Q" SET UP FOR DRAMS SAMPLING OPERATION, RIDER GIEN COURTNEY
0813	TEAM 1 CLEARED PDS.
0829	TEAM 3 DOWN RANGE DRAMS SAMPLING IN LEVEL "B" SPROUSE, MANTELL
0835	ALL DRAMS PUMPS IN PLACE AT EXCAVATION AND SPOILS, THIS IS START TIME.
0843	TEAM 3 CLEARED PDS.
1052	TEAM 3 DOWN RANGE LEVEL "B" SPROUSE & MANTELL, COLLECTING DRAMS PUMPS. WBGT @ 86.0
1106	TEAM 3 CLEARED PDS
1112	STARTING MID DAY CHALLENGE.
1138	MID DAY CHALLENGE COMPLETE.
1149	WBGT @ 86.6
1155	PUMPING WATER
1256	COMPLETED PUMPING WATER FOR A TOTAL OF TWO LOADES

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 17 August 2017
Site Location: 4825 Glenbrook Road

Weather:
Hot with rain showers Low 70° High 86°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Elliot, Laura	
Malone, Forrest	Prate, Warren	Harris, Brian	
Mantell, Dawn	Yorkshire, Bart	PalePale, Margareth	
Marian, Jed			
Matter, Phil		Rowell, Will	
Nelms, Bobby		Guyer, Gary	
Oien, Joshua		Shavers, Dedrick	
		Wooten, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margaret		McGill, Andre	
Sprouse, Mark		Henderson, Amos	
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Marks, Scott	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel performed re-sampling of the spoils pile and excavation area with DAMMS pumps. Personnel performed site maintenance at both work sites.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**8/17/2017**
Weather:	**Partly Cloudy 75-88°F, wind 0-6 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews conducted level B operations to place DAAMS tubes and run them for 2 hours to collect samples. Crews pumped ponded water that had seeped into the sump area.**
Summary:	**Crews conducted level B operations to place DAAMS tubes and run them for 2 hours to collect samples. Crews pumped ponded water that had seeped into the sump area.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**8/17/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Pg	
34	8-17-17
0630	SAFETY BRIEF
0700	RADIO CHECKS, TRAFFIC SIGNS IN PLACE.
0715	DAAMS UP
0725	MINICAMS UP
0739	TEAM 1 DOWN RANGE FOR SETUP IN MOB "O" TIBER, DIEN, COURTNEY
0745	TEAM 1 CLEARED PDS.
0753	TEAM 3 DOWN RANGE IN LOVEL "B" DAAMS SAMPLING SPOILS & EXCAVATION.
0757	DAAMS PUMPS IN PLACE STARTING RUN TIME.
0806	TEAM 3 CLEARED PDS.
1015	TEAM 3 DOWN RANGE LEVEL "B" TO RETRIEVE DAAMS PUMPS.
1023	TEAM 3 CLEARED PDS.
1100	CONFERENCE CALL
1123	STARTING MIDDAY CHALLENGE
1147	MIDDAY CHALLENGE COMPLETE.
1152	CONFERENCE CALL ENDS
1211	WBGT @ 92.5 25/75 FOR ALL WORK
1328	WBGT @ 92.6
1500	LIGHTNING HOLD.
1530	OFF LIGHTNING HOLD.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 18 August 2017
Site Location: 4825 Glenbrook Road

Weather:
Hot with rain showers Low 75° High 88°

Personnel on Site

PARSONS	ZES	ECBC
Malone, Forrest	Prate, Warren	
Mantell, Dawn	Yorkshire, Bart	
Nelms, Bobby		
Wunschel, Reina		
Wunschel, Scott	**ACCUPERMIT**	**CHENC**
	Schmidt, James	
	Williams, Angelo	
		CENAB
		Marks, Scott

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel pumped water from the sump / low area that collected late Thursday afternoon. The team also placed some hay bales along the 4835 exposed wall to help hold up the plastic.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg
35 8-18-17
0700 SAFETY BRIEF
0720 RADIO CHECKS, TRAFFIC SIGNS IN PLACE
0740 THE TOWN IS PUMPING WATER AND PLACING STRAW BALES.
0920 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 21 August 2017
Site Location: 4825 Glenbrook Road

Weather:
Hot Low 72° High 84°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Askew, Tom	
Malone, Forrest	Prate, Warren	Harris, Brian	
Mantell, Dawn	Yorkshire, Bart	Hall, Stephen	
Marian, Jed			
Matter, Phil		Collins, Torry	
Nelms, Bobby		Jones, LaMarcus	
Oien, Joshua		McClellan, Dale	
Pilato, Bryan		Wooten, Mike	
Rider, Matthew		Landers, Brian	
		McGill, Andre	
Sprouse, Mark		Henderson, Amos	
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Marks, Scott	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel pumped approximately 1600water from the sump area then added more hay bales along the 4835 basement wall. Personnel also moved the small excavator out of the low area onto higher ground. Teams also added gravel to the entrance of the truck gate.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Pg	
36	8-21-17
0630	SAFETY BRIEF.
0650	RADIO CHECKS.
0764	TRAFFIC SIGNS IN PLACE.
0750	MINICAMS AND DAMS UP & RUNNING. THE TEAMS ARE SPREADING GRANT AT THE GATE ENTRANCE. PUMPING WATER.
0928	WBGT @ 82.0
1022	WBGT @ 86.8
1105	STARTING MID DAY CHALLENGE.
1120	MID DAY CHALLENGE COMPLETE
1354	WBGT @ 96.4
1515	LIGHTNING HOLD.
1545	OFF LIGHTNING HOLD.
1600	CONFERENCE CALL.
1530	CONFERENCE CALL COMPLETE.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 22 August 2017
Site Location: 4825 Glenbrook Road

Weather:
Hot Low 74° High 86°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Askew, Tom	
Malone, Forrest	Prate, Warren	Harris, Brian	
Mantell, Dawn	Yorkshire, Bart	Hall, Stephen	
Marian, Jed			
Matter, Phil		Collins, Torry	
Nelms, Bobby		Jones, LaMarcus	
Oien, Joshua		McClellan, Dale	
Pilato, Bryan		Wooten, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margartet		McGill, Andre	
Sprouse, Mark		Henderson, Amos	
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Marks, Scott	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel cut brush and grass along a portion of the fence line at the 4835 site and performed clean up and organizing of the roll off storage area. The BOI convened at 1200 and spoke with the SUXOS.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg
37 8-22-17
0630 SAFETY BRIEF.
1700 RADIO CHECKS, TRAFFIC SIGNS IN PLACE. THE TEAMS ARE WORKING AT FED PROPERTY.
0855 DAWG LAWN SERVICE CUTTING GRASS AT FED PROPERTY.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 23 August 2017
Site Location: 4825 Glenbrook Road

Weather:
Hot Low 70° High 85°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Askew, Tom	
Malone, Forrest	Prate, Warren	Harris, Brian	
Mantell, Dawn	Yorkshire, Bart	Hall, Stephen	
Marian, Jed			
Matter, Phil		Collins, Torry	
Nelms, Bobby		Jones, LaMarcus	
Oien, Joshua		McClellan, Dale	
Pilato, Bryan		Wooten, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margartet		McGill, Andre	
Sprouse, Mark		Henderson, Amos	
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Marks, Scott	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel performed more cutting of grass and weeds at the 4825 site. Teams also worked at the federal property dumping roll off boxes of cleared soil. BOI made a visit to the site and spoke to several site personnel.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Sensitive



Pg
38 8-23-17
0630 SAFETY BRIEF.
0780 RADIO CHECKS
0830 BOI ON SITE AND BRIEFED.
1000 AT APPROXIMATELY 10:00 DR ROBERT MCINTOSH TRIPPED & FELL IN THE MDS. NO MEDICAL TREATMENT WAS REQUIRED.
1042 BOI MEMBERS OFF SITE.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 24 August 2017
Site Location: 4825 Glenbrook Road

Weather:
Hot Low 70° High 83°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Askew, Tom	
Malone, Forrest	Prate, Warren	Harris, Brian	
Mantell, Dawn	Yorkshire, Bart	Hall, Stephen	
Marian, Jed		Smith, Ethan	
Matter, Phil		Collins, Torry	
Nelms, Bobby		Jones, LaMarcus	
Oien, Joshua		McClellan, Dale	
Pilato, Bryan		Wooten, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margartet		McGill, Andre	
Sprouse, Mark		Henderson, Amos	
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Marks, Scott	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel performed some preparation of supplies for the soil sampling operation on Friday. They also weighed soil drums in preparation for shipment to the incinerator.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Pg	
39	8-24-17
0630	SAFETY
0700	RADIO CHECKS. TRAFFIC SIGNS IN PLACE.
0830	MEETING WITH [redacted] @ FED PROPERTY.
1140	MEETING WITH [redacted] COMPLETE. CONFERENCE CALL @ 11:00 SAMPLING PLAN DISCUSSION.
1700	SECURED



SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 25 August 2017
Site Location: 4825 Glenbrook Road

Weather:
Hot Low 73° High 87°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Askew, Tom	
Malone, Forrest	Prate, Warren	Harris, Brian	
Mantell, Dawn	Yorkshire, Bart	Hall, Stephen	
Marian, Jed		Smith, Ethan	
Matter, Phil		Collins, Torry	
Nelms, Bobby		Jones, LaMarcus	
Oien, Joshua		McClellan, Dale	
Pilato, Bryan		Wooten, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margartet		McGill, Andre	
Sprouse, Mark		Henderson, Amos	
Wunschel, Reina		Henery, Amos	
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Arteaga, Carlos		
		CENAB	
		Marks, Scott	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel anticipate assisting ECBC with collecting soil samples from the spoils pile and excavation area. Teams also performed end of week clean up and maintenance.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



40 8.25-17
0630 SAFETY BRIEF
0700 RADIO CHECKS
0714 MINICAMS & DAAMS UP
0723 WBGT @ 61.9.
0733 ECBC DOWN RANGE IN LEVEL "B"
COLLECTING SOIL SAMPLES FROM
EXCAVATION AND SPILLS.
0916 ALL SAMPLES HAVE BEEN COLLECTED
TEAM AT THE PDS.
1530 SECURED SITE

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 28 August 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild with late showers Low 60° High 77°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Askew, Tom	
Malone, Forrest	Prate, Warren	Owens, Julius	
Mantell, Dawn	Yorkshire, Bart	PalePale, Margareth	
Marian, Jed			
Matter, Phil		Collins, Torry	
Nelms, Bobby		Jones, LaMarcus	
Oien, Joshua		McClellan, Dale	
Pilato, Bryan		Wooten, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margartet		McGill, Andre	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Marks, Scott	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Teams dumped roll off boxes of cleared soil at the federal property site. Personnel also weighed soil drums in preparation for shipment to the incinerator and performed general site maintenance. BOI continued their investigation.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	


Pg
41
8-27-17
0630 SAFETY BRIEF.
1700 RADIO CHECKS TEAMS
WORKING AT FED SITE.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 29 August 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild with showers Low 63° High 72°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Askew, Tom	
Malone, Forrest	Prate, Warren	Owens, Julius	
Mantell, Dawn	Yorkshire, Bart	PalePale, Margareth	
Marian, Jed			
Matter, Phil		Collins, Torry	
Nelms, Bobby		Jones, LaMarcus	
Oien, Joshua		McClellan, Dale	
		Wooten, Mike	
Rider, Matthew		Landers, Brian	
Rockwell, Margartet		McGill, Andre	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued to weigh soil drums in preparation for shipment to the incinerator. They also worked on E&S controls at the federal property site and performed general maintenance.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	


PR

42 8-29-17

0630 SAFETY BRIEF.

0700 RADIO CHECKS. TEAMS WORKING AT FEDERAL PROPERTY.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 30 August 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild Low 68° High 79°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	Askew, Tom
Malone, Forrest	Prate, Warren	Owens, Julius
Mantell, Dawn	Yorkshire, Bart	PalePale, Margareth
Marian, Jed		
Matter, Phil		Collins, Torry
Nelms, Bobby		Jones, LaMarcus
Oien, Joshua		McClellan, Dale
		Wooten, Mike
Rider, Matthew		Smith, Ethan
Rockwell, Margartet		
Sprouse, Mark		
Wunschel, Reina		
Wunschel, Scott	**ACCUPERMIT**	**CHENC**
	Schmidt, James	Boles, Judson
	Williams, Angelo	
		CENAB

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel pumped 1200 gallons of water from the 4825 site then continued to weigh soil drums in preparation for shipment to the incinerator. They also worked inventory of Interspiro equipment.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Pg
43 8-30-17
0630 SAFETY BRIEF.
0700 RADIO CHECKS.
0732 THE TEAMS ARE PUMPING WATER.
1700 End of day all secure.

Nothing follows



SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 30 August 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, partly cloudy Low 61° High 85°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Askew, Tom	
Mantell, Dawn	Prate, Warren	Owens, Julius	
	Yorkshire, Bart	PalePale, Margareth	
Matter, Phil		Collins, Torry	
		Jones, LaMarcus	
		McClellan, Dale	
		Wooten, Mike	
		Smith, Ethan	
Rockwell, Margartet		McGill, Andre	
Sprouse, Mark			
Wunschel, Reina			
Wunschel, Scott	**ACCUPERMIT**	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Teams dumped roll off boxes of cleared soil at the federal property site. Personnel also weighed soil drums in preparation for shipment to the incinerator and performed end of week maintenance.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



(44)

31 Aug 2017 Thursday 83/61° p. cloudy

0630 Daily safety & ops briefings. Nelms, Dion, Rider + Mason out

0700 Teams go to Fed Prop to finish guard shack, weigh drums.

1100 Conference call

1130 Call ends

1400 Teams doing vehicle inspections & gear maintenance. Teams reviewing concrete sampling S.O.P.

1700 End of day all secure.

Nothing Follows

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 5 September 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, partly cloudy Low 63° High 87°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Tucker, Robin	
Mantell, Dawn		Leach, Mark	
Marion, Jedidiah	Yorkshire, Bart	PalePale, Margareth	
Matter, Phil	Zimmer, Doug		
		Collins, Torry	
Oien, Joshua		Jones, LaMarcus	
Pilato, Brian		McClellan, Dale	
Rider, Mattew		Tucker, Willie	
Rockwell, Margartet		Smith, Ethan	
Sprouse, Mark		Crawford, Stephen	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel pumped 1200 gallons of water from the sump / low area of the site. The team also cut up copper and PVC pipe in preparation for shipment to the incinerator. Personnel attempted to move concrete wall sections in preparation for backfilling the site.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

(45) 5 Sept 2017 Tuesday 87/66 cloudy

0630 Daily safety & ops briefings. Pumping water & Moving Concrete.
0710 Traffic control in place, signs are out.
0735 Refilled eye wash station
0745 Truck w/ water tanks in
0805 Truck out Drums to leave: AQ 611, 612, 613 PE 396 397 398 399 400 / AQ 571 / SCR 511, 513, 574.
0857 Truck back in site
0912 Truck off site full load
0950 Truck on site w/ water - pumping tanks
1000 3rd truck left w/ approx 250 gal 2 full loads & 250 gallons
1306 Drums listed above being loaded & leaving site.
1330 TM 2 Wunschel / Marion cutting up pipes
1350 87.5 WBGT Moderate work load 30/30 work/rest
1417 TM2 clear - PDS TM1 headed to PDS
1425 TM1 in 87.1° WBGT cutting pipes, tools - Matt, Bruce, Josh attempt to cut Concrete Wall piece in half
1510 TM1 out TM3 dressing out High temp 99.9° on people
1515 TM3 in Sprouse, Mankell, Pilato
1555 TM3 out.
1615 End of day preparations.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 6 September 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 57° High 72°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Tucker, Robin	
Mantell, Dawn	Prate, Warren	Leach, Mark	
Marion, Jedidiah	Yorkshire, Bart	PalePale, Margareth	
Matter, Phil	Zimmer, Doug		
		Collins, Torry	
Oien, Joshua		Jones, LaMarcus	
Pilato, Brian		McClellan, Dale	
Rider, Mattew		Tucker, Willie	
Rockwell, Margartet		Smith, Ethan	
Sprouse, Mark		Crawford, Stephen	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel pumped 725 gallons of water from the 4825 site then completed cutting up scrap pipes in preparation for shipment to the incinerator. Teams then moved the concrete wall pieces and began backfill of the site.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



(96) 6 Sept 2017 Wednesday 68/57 rainy

0630 Daily safety & operations briefings. Pumping water & attempting to cut and move concrete. J.R. Martin back on site.
0740 Radio checks, traffic control in place
0745 Min. CAMs + PAAMs up
0745 Water tank truck on site
0750 Begin pumping w/ TM 3.
0820 Water truck has left 1 load only. Begin cutting up scrap.
0850 TM 3 out all scrap cut up. TM 1 gearing up.
0900 TM 1 in. Cutting rebar moving concrete.
1040 Concrete cut & moved TM 3 out.
1055 TM 2 & 3 begin backfilling pipes. Layout Eco
1132 1st backfill truck is in
1515 Last and 6th load of backfill in
1552 Teams complete covering the backfill area.
1600 Heavy equip operations halted, covering backfill.
1700 End of day all secure

Nothing follows

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 7 September 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 56° High 74°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Tucker, Robin
Mantell, Dawn	Prate, Warren	Leach, Mark
Marion, Jedidiah	Yorkshire, Bart	PalePale, Margareth
Matter, Phil	Zimmer, Doug	
		Collins, Torry
Oien, Joshua		Jones, LaMarcus
Pilato, Brian		McClellan, Dale
Rider, Mattew		Tucker, Willie
Rockwell, Margartet		Smith, Ethan
Sprouse, Mark		Crawford, Stephen
Wunschel, Reina		
Wunschel, Scott		
	ACCUPERMIT	**CHENC**
	Schmidt, James	Boles, Judson
	Williams, Angelo	
		CENAB
		Martin, Lowell

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons personnel re-collected soil samples from the excavation area and the spoils pile. After samples were collected site personnel continued backfill of the site and installation of additional E&S controls. Several loads of soil was brought in and spread over geo cloth.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**9/7/2017**
Weather:	**Partly Cloudy 59-75 F, wind 0-3 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Parsons Team re-collected VOC samples from the grab sample locations in the spoils pile and excavation area that were sampled on 8/25/2017. Samples were submitted to ECBC for transportation to Edgewood for low level analysis.**
Summary:	**Parsons Team re-collected VOC samples from the grab sample locations in the spoils pile and excavation area that were sampled on 8/25/2017. Samples were submitted to ECBC for transportation to Edgewood for low level analysis.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**9/7/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

(47) 7 Sept 2017 Thursday lo 70's mostly sunny

0630 Daily safety & ops briefings. Resample for VOC's & continue backfilling.
0650 PDS up & running.
0715 Mini CAMS, DAAMS, Handhelds & Traffic & PDS all up.
0718 TM1 down range removing plastic & set up sample area.
0743 TM1 out
0800 TM3 on air 3800 psi going down range to sample in Level B
0822 2100 psi starting sample 445.
0830 Move to spoils pile
0835 SCBA bottle change.
0846 TM3 back in 3800 psi level B
0853 TM3 sampling complete move to PDS.
0905 TM1 in level D cleaning up & prepping for backfill ops
1006 TM1 in for backfilling
1018 Traffic reports man w/ camera taking pictures in the street.
1025 Site Manager confronts man with camera reporter w/ WTOP
1039 Back to work backfilling
1212 Backfill continuing
1535 Last truckload of backfill begin preparing site for weekend shutdown Begin equipment maintenance.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 11 September 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 58° High 79°

Personnel on Site

PARSONS	ZES	ECBC	
	Mangosh, Ed	Tucker, Robin	
Mantell, Dawn	Prate, Warren	Leach, Mark	
	Yorkshire, Bart	PalePale, Margareth	
Matter, Phil	Zimmer, Doug		
Nelms, Bobby			
Oien, Joshua		Bagley, Robert	
Pilato, Brian		Miller, Jonathan	
Rider, Mattew		Tucker, Willie	
Rockwell, Margartet		Blaylock, Gary	
Sprouse, Mark		Crawford, Stephen	
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, Lowell	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Personnel continued backfill of the site and installation of additional E&S controls. Several loads of gravel were brought in and spread over geo cloth.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Pg 48

9-1-17

0630 SAFETY BRIEF.

0700 RADIO CHECKS. THE TEAMS ARE BACK FILLING W/CLEAN BACK FILL AND GRAVEL.

1435 TEAMING W/ TEAMS REVIEWED THE CONCRETE SAMPLING SOP.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 12 September 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 64° High 77°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Tucker, Robin
Mantell, Dawn	Prate, Warren	Leach, Mark
	Yorkshire, Bart	PalePale, Margareth
Matter, Phil	Zimmer, Doug	
Nelms, Bobby		Smith, Ethan
Oien, Joshua		Myers, Royce
Pilato, Brian		Miller, Jonathan
Rider, Mattew		Tucker, Willie
Rockwell, Margartet		Blaylock, Gary
Sprouse, Mark		Crawford, Stephen
Wunschel, Scott		
	ACCUPERMIT	**CHENC**
	Schmidt, James	Boles, Judson
	Williams, Angelo	
		CENAB
		Martin, Lowell

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel Collected concrete dust samples from three of the four section of concrete retaining wall. After samples were collected the teams continues to work on backfill and completed the gravel layer.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**9/12/2017**
Weather:	**Partly Cloudy 65-76°F, wind 0-4 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Collected concrete samples from 3 grids for a total of 12 sample locations. 12 samples submitted for headspace.**
Summary:	**Collected concrete samples from 3 grids for a total of 12 sample locations. 12 samples submitted for headspace.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**9/12/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Pg

49 9-12-17

0630 SAFETY BRIEF.

0655 RADIO CHECKS PDS UP.

0715 MINICAMS AND DAAMS UP.

0750 THE TEAMS ARE POSITIONING CONCRETE WALL SECTIONS FOR SAMPLING.

0841 TEAM 1 DOWN RANGE BRUSHING CLEANING / WALL

0850 AIRCHER 52 SILICA PUMPS STARTED
P987 w/ CART 73008433
P984 w/ CART 73040275
P1446 w/ CART 73040285
P1491 w/ CART 73040254
CART # 73040259 IS THE BLANK.

0928 TEAM 1 CLEARED PDS.

0950 TEAM 1 DOWN RANGE LEVEL "C" FOR CONCRETE SAMPLING. MATT RIDER PUMP ~~73008433~~ P987 w/CART 73008433
JOSH OLEN PUMP P1446 w/CART 73040285

1047 CONCRETE WALL SECTION 1 SAMPLING COMPLETE (SECTIONS 1 THRU 4)

1113 SECTIONS 1 & 2 OF SECTION 2/GRID 2 COMPLETED.

1115 TEAM 1 CLEARED PDS, STARTING MID DAY CHALLENGE.

1135 MID DAY CHALLENGE COMPLETE.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 13 September 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 66° High 78°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Tucker, Robin	
Mantell, Dawn	Prate, Warren	Leach, Mark	
	Yorkshire, Bart	PalePale, Margareth	
Matter, Phil	Zimmer, Doug		
Nelms, Bobby		Smith, Ethan	
Oien, Joshua		Myers, Royce	
Pilato, Brian		Miller, Jonathan	
Rider, Mattew		Tucker, Willie	
Rockwell, Margartet		Blaylock, Gary	
Sprouse, Mark		Crawford, Stephen	
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James	Boles, Judson	
	Williams, Angelo		
		CENAB	
		Martin, Lowell	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel Completed sampling fourth section of retaining wall that was previously removed and staged. After sampling was complete teams began installation of silt fencing and straw bales.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**9/13/2017**
Weather:	**Cloudy with intermittent rain 66-86F, wind 0-3 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Collected concrete samples from 1grid for a total of 4 sample locations. 4 samples submitted for headspace.**
Summary:	**Collected concrete samples from 1grid for a total of 4 sample locations. 4 samples submitted for headspace.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**9/13/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Pg	
51	9-13-17
0630	SAFETY BRIEF
0730	POS UP RADIO CHECKS.
0715	MINICAMS UP.
0757	DAAMS PUMPS RUNNING.
1013	TEAM 3 DOWN RANGE "LEVEL C" COLLECTING CONCRETE SAMPLES. FROM SECTION/GRID 4.
1055	SAMPLING FOR SECTION/GRID 4 COMPLETED.
1058	TEAM 3 CLEARED POS. STARTING MID DAY CHALLENGE.
1125	MIDDAY CHALLENGE COMPLETE
1413	SCR DRUMS 517 THRU 519. PPE DRUMS 401 & 402 TRANSFERED TO FED PROPERTY.
1700	SECURED



SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 14 September 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 68° High 81°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Tucker, Robin
Mantell, Dawn	Prate, Warren	Leach, Mark
	Yorkshire, Bart	PalePale, Margareth
Matter, Phil	Zimmer, Doug	
Nelms, Bobby		Smith, Ethan
		Bagley, Robert
		Miller, Jonathan
Rider, Mattew		Tucker, Willie
Rockwell, Margartet		Blaylock, Gary
Sprouse, Mark		Crawford, Stephen
Wunschel, Scott		
	ACCUPERMIT	**CHENC**
	Schmidt, James	
	Williams, Angelo	
		CENAB
		Martin, Lowell

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Teams completed installation of silt fencing and straw bales, then performed end of week clean up and equipment maintenance.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	


Pg
52
9-14-17
0630 SAFETY BRIEF.
0700 RADIO CHECKS. THE TEAMS ARE
INSTALLING SUPER SILT FENCE.
1710 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 18 September 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 66° High 80°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Askew, Tom	
Mantell, Dawn	Prate, Warren	Burrell, Dianne	
	Yorkshire, Bart	Fortier, James	
Matter, Phil	Zimmer, Doug		
Nelms, Bobby		Smith, Ethan	
Oien, Joshua		Bagley, Robert	
Pilato, Bryan		Miller, Jonathan	
Rider, Mattew			
Rockwell, Margartet		Blaylock, Gary	
Sprouse, Mark		Crawford, Stephen	
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James		
	Williams, Angelo		
		CENAB	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons personnel conducted training with the manual sampling geo probe. After the training the team transferred rain water that had previously been collected in 55 gallon drums into the Baker tank. They also dumped one roll off box of cleared soil in preparation for transfer to the land fill.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	


53 9-18-17
0630 SAFETY BRIEF.
0780 RADIO CHECKS THE TEAMS
WORKING AT FEDERAL PROPERTY
AND TRAINING W/GEO PROB.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 19 September 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 64° High 81°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Askew, Tom
Mantell, Dawn	Prate, Warren	Burrell, Dianne
Matter, Phil	Yorkshire, Bart	Fortier, James
Nelms, Bobby		
Oien, Joshua		Smith, Ethan
Pilato, Bryan		Bagley, Robert
Rider, Mattew		Miller, Jonathan
Rockwell, Margartet		Tucker, Willie
Sprouse, Mark		Blaylock, Gary
Wunschel, Scott		Crawford, Stephen

ACCUPERMIT	CHENC
Schmidt, James	
Williams, Angelo	

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel completed transferring rain water that had previously been collected in 55 gallon drums into the Baker tank. Parsons and Zimmer personnel dumped three more roll off box of cleared soil in preparation for transfer to the land fill. Two Parsons personnel transported concrete samples to Edgewood for low level sampling.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Sensitive


Pg
54 9-19-17
0630 SAFETY BRIEF.
0700 RADIO CHECKS TOOLS WORKING
AT FEDERAL PROPERTY.
1430 POT CALL TO DISCUSS FINDING
FOR CONCRETE SAMPLING.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 20 September 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 70° High 85°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Askew, Tom
Mantell, Dawn		Burrell, Dianne
Matter, Phil	Yorkshire, Bart	Fortier, James
Nelms, Bobby		
Oien, Joshua		Smith, Ethan
		Bagley, Robert
Rider, Mattew		Miller, Jonathan
Rockwell, Margartet		Tucker, Willie
Sprouse, Mark		Blaylock, Gary
Wunschel, Scott		Crawford, Stephen

ACCUPERMIT	CHENC
Schmidt, James	
Williams, Angelo	

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel began construction of the concrete demolition sump area. They also began gathering and staging supplies and equipment for the concrete demolition operation.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 21 September 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 69° High 86°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Askew, Tom
Mantell, Dawn	Prate, Warren	Burrell, Dianne
Matter, Phil	Yorkshire, Bart	Fortier, James
Nelms, Bobby	Zimmer, Doug	
Oien, Joshua		Smith, Ethan
Pilato, Bryan		Bagley, Robert
		Miller, Jonathan
Rockwell, Margartet		Tucker, Willie
Sprouse, Mark		Blaylock, Gary
Wunschel, Scott		Crawford, Stephen

ACCUPERMIT	CHENC
Schmidt, James	
Williams, Angelo	

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel completed construction of the concrete demolition sump area. They also completed gathering and staging supplies and equipment for the concrete demolition operation.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
Curtis Hollister	
Todd Duff	DAVEY ( )
Mike Knudsen	ACCUPERMIT (2)
Amos Henderson	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg

55 9-20-17

0630 SAFETY BRIEF.

0750 RADIO CHECKS.

0800 THE TEAMS RECEIVING M40's AND CHANGING FILTERS. THIS IS DUE TO CONCRETE SAMPLING RESULTS.

1000 THE TEAMS ARE WORKING TO INSTALL SUMP FOR CONCRETE BOOMING.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 25 September 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 70° High 89°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	
	Prate, Warren	
Matter, Phil	Yorkshire, Bart	
Nelms, Bobby		
Oien, Joshua		
Pilato, Bryan		
Rider, Matthew		
Rockwell, Margartet		
Sprouse, Mark		
Wunschel, Scott		

ACCUPERMIT	CHENC
Schmidt, James	
Williams, Angelo	

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel worked at the federal property site cleaning three water transfer tanks, a 350 gal, 500 gal and 1,000 gal. Personnel also began organizing equipment in the Quonset hut.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
Curtis Hollister	
Todd Duff	DAVEY ( )
Mike Knudsen	ACCUPERMIT (2)
Amos Henderson	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	


Pg
57 9-25-17
0630 SAFETY BRIEF.
0700 RADIO CHECKS. THE TEAMS WORKING
AT FEDERAL PROPERTY.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 26 September 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 72° High 82°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	
Courtney, Kenneth	Prate, Warren	
Matter, Phil	Yorkshire, Bart	
Nelms, Bobby		
Oien, Joshua		
Pilato, Bryan		
Rider, Matthew		
Rockwell, Margartet		
Sprouse, Mark		
Wunschel, Scott		

ACCUPERMIT	CHENC
Schmidt, James	
Williams, Angelo	

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel brought several loads of sand from the federal property site. The sand was used to make a soft protective layer between the gravel and the sump pond liner. The team also continued organizing and removing trash from the Quonset hut.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
Curtis Hollister	
Todd Duff	DAVEY ( )
Mike Knudsen	ACCUPERMIT (2)
Amos Henderson	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	


Pg
58 9-26-17
0630 SAFETY BRIEF
0700 RADIO CHECKS TRAFFIC
SIGNS IN PLACE.
0736 PULLING SUMP
1600 TEAMS WORKING AT FEDERAL
PROPERTY
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 27 September 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 72° High 87°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	
Courtney, Kenneth	Prate, Warren	
Matter, Phil	Yorkshire, Bart	
Nelms, Bobby		
Oien, Joshua		
Pilato, Bryan		
Rider, Matthew		
Rockwell, Margartet		
Sprouse, Mark		
Wunschel, Scott		

ACCUPERMIT	CHENC
Schmidt, James	
Williams, Angelo	

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel transferred extra straw bales and sand bags from the 4825 site to the federal property site. The team also inspected and tested heat trace lines for the above ground water line to the AU athletic field. Personnel then worked at the federal property site disposing of old pallets and lagging boards.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
Curtis Hollister	
Todd Duff	DAVEY ( )
Mike Knudsen	ACCUPERMIT (2)
Amos Henderson	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg

59 9-27-17

0630 SAFETY BRIEF.

0700 RADIO CHECKS.

0739 THE TEAMS ARE WORKING AT FEDERAL PROPERTY.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 28 September 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 68° High 80°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	
Courtney, Kenneth	Prate, Warren	
Matter, Phil	Yorkshire, Bart	
Nelms, Bobby		
Rider, Matthew		
Rockwell, Margartet		
Sprouse, Mark		
Wunschel, Scott		

ACCUPERMIT	CHENC
Schmidt, James	
Williams, Angelo	

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Teams will continue with disposal of old pallets, Finish the Quonset hut, reorganize scrap drums and do end of week equipment maintenance.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
Curtis Hollister	
Todd Duff	DAVEY ( )
Mike Knudsen	ACCUPERMIT (2)
Amos Henderson	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	


Pg
1
9-28-17
0630 SAFETY BRIEF.
0700 RADIO CHECKS
0740 THE TEAMS WORKING AT FEDERAL
PROPERTY.
1100 WEEKLY CONFERENCE CALL.
1800 TWO WEEK LOOK AHEAD.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 02 October 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 50° High 75°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	
Matter, Phil	Yorkshire, Bart	
Nelms, Bobby		
Oien, Joshua		
Pilato, Brian		
Rider, Matthew		
Sprouse, Mark		
Wunschel, Scott		

ACCUPERMIT	CHENC	CENAB
		Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel worked at the federal property site removing weeds from the perimeter fence and drum yard fence. The team also made repairs to the fences at the 4825 site. Prepped scrap drums for movement to the covered storage area. Equipment was removed from one of the rental vehicles and the vehicle turned in.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	


PG

6/ 10-2-17

0630 SAFETY BRIEF.

0700 RADIO CHECKS

0753 TEAMS WORKING AT FEDERAL PROPERTY

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 03 October 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 53° High 76°

Personnel on Site

PARSONS	ZES	ECBC	
	Mangosh, Ed		
	Prate, Warren		
Matter, Phil	Yorkshire, Bart		
Nelms, Bobby			
Oien, Joshua			
Pilato, Brian			
Rider, Matthew			
Rockwell, Margaret			
Sprouse, Mark			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel transferred scrap drums to the covered storage area. The team used jersey barriers to construct a gravel holding area. Organized old tent parts and inspected the temporary fence panels for possible use at the 4835 driveway.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	


RG
62 10-3-17
0630 SAFETY BRIEF.
0700 RADIO CHECKS.
0747 THE TEAMS ARE WORKING AT FEDORA PROPERTY.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 04 October 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 57° High 80°

Personnel on Site

PARSONS	ZES	ECBC	
	Mangosh, Ed		
	Prate, Warren		
Matter, Phil	Yorkshire, Bart		
Nelms, Bobby			
Oien, Joshua			
Rider, Matthew			
Rockwell, Margaret			
Sprouse, Mark			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel completed removing weeds from the perimeter fence and drum yard fence at the federal property site. They repaired the large roll up door on the Quonset hut. They reset silt fences at the 4825 site. The team organized equipment in the wooden storage shed.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg 63

10-4-17

0630 SAFETY BRIEF

0700 RADIO CHECKS.

0800 TEAMS WORKING AT FEDERAL PROPERTY.

1900 ARMY LAWN SERVICE WORKING AT FEDERAL PROPERTY.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 05 October 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 65° High 83°

Personnel on Site

PARSONS	ZES	ECBC	
	Mangosh, Ed		
	Prate, Warren		
Matter, Phil	Yorkshire, Bart		
Nelms, Bobby			
Rider, Matthew			
Rockwell, Margaret			
Sprouse, Mark			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
		CENAB	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel covered the soil pile at the federal property site. Inspected roll off covers for damage / sun rot. They cut up and removed fallen branches from the federal property site and performed end of week clean up and maintenance.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	


64
10-5-17
0630 SAFETY BRIEF
0700 TEAMS WORKING AT FEDERAL PROPERTY
1100 CONFERENCE CALL.
1800 TWO WEEK LOOK AHEAD.
1900 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 10 October 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 70° High 84°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	
	Prate, Warren	
Matter, Phil	Yorkshire, Bart	
Nelms, Bobby		
Oien, Joshua		
Pilato, Bryan		
Rider, Matthew		
Rockwell, Margaret		
Sprouse, Mark		
Wunschel, Scott		

ACCUPERMIT	CHENC
Schmidt, James	
Williams, Angelo	**CENAB**
	Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel transferred 30 empty drums, drum scale, sump liner and other equipment to the 4825 Glenbrook site and began setting up equipment. They pulled up and staged. construction pads to be used in the sump. They trimmed trees and brush from between the office trailers at the federal property site.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	


65
10-10-17
0630 SAFETY BRIEF.
0700 RADIO CHECKS.
0780 THE TEAMS ARE WORKING AT FEDETOM
PROPERTY. PREPING FOR JUMP
ASSEMBLY
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 11 October 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 69° High 75°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	Askew, Tom
	Prate, Warren	Bobal, Brandon
Matter, Phil	Yorkshire, Bart	
Nelms, Bobby		
Oien, Joshua		Smith, Ethan
Pilato, Bryan		Landers, Brian
Rider, Matthew		Foor, Adam
Rockwell, Margaret		Bartosh, Ian
Sprouse, Mark		Miller, Don
Wunschel, Scott		Druyor, Chris

ACCUPERMIT	CHENC
Schmidt, James	
Williams, Angelo	**CENAB**
	Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel completed constructing the sump for concrete demolition. They also inventoried packed and shipped Interspiro gear for inspection and certification. ECBC personnel returned to the site and set up equipment.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg
66 10-11-17
0630 SAFETY BRIEF.
1650 RADIO CHECKS.
0710 THE TEAMS ARE WORKING AT FEDERAL PROPERTY.
1100 ECBC ON SITE. THE TEAMS WORKING TO COMPLETE SUMP.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 12 October 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 63° High 70°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	Askew, Tom
	Prate, Warren	Bobal, Brandon
Matter, Phil	Yorkshire, Bart	Tucker, Willie
Nelms, Bobby		
Oien, Joshua		Smith, Ethan
Pilato, Bryan		Landers, Brian
Rider, Matthew		Foor, Adam
		Bartosh, Ian
Sprouse, Mark		Miller, Don
Wunschel, Scott		Druyor, Chris

ACCUPERMIT	CHENC
Schmidt, James	
Williams, Angelo	**CENAB**
	Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel conducted refresher training (walk thru), then begin demolition of the concrete footers. Teams performed end of week clean up and maintenance.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg 67 10-12-17

0630 SAFETY BRIEF
0700 RADIO CHECKS, TRAFFIC SIGNS IN PLACE.
0730 PDS IS UP.
0752 MINICAMS & DRAMS UP
1025 TRAINING SCENARIOS W/TEAMS.
1100 TRAINING SCENARIOS COMPLETE. CONFERENCE CALL.
1115 STARTING MID DAY CHALLENGE.
1131 MIDDAY COMPLETE
1230 TEAM 1 DOWNRANGE, RIDER, OLEN MANGOSH BREAKING CONCRETE SECTION #4.
1330 TEAM 1 HAS CLEARED PDS.
1332 TEAM 3 DOWN RANGE SPROUSE PICATO PRATE. BREAKING CONCRETE SECTION #4.
1438 TEAM 3 CLEARED PDS
1448 MINICAMS DOING END OF DAY CHECKS
1500 TWO WEEK LOOK AHEAD.
1525 TWO WEEK LOOK AHEAD COMPLETED.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 16 October 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 63° High 69°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	Askew, Tom
Courtney, Kenneth	Prate, Warren	Hall, Steve
Matter, Phil	Yorkshire, Bart	Tucker, Willie
Nelms, Bobby		
Oien, Joshua		Smith, Ethan
Pilato, Bryan		Landers, Brian
Rider, Matthew		Foor, Adam
Rockwell, Margaret		Bartosh, Ian
Sprouse, Mark		Miller, Don
Wunschel, Reina		Druyor, Chris
Wunschel, Scott		

ACCUPERMIT	CHENC
Schmidt, James	
Williams, Angelo	**CENAB**
	Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued demolition of the concrete footers. No drums were filled.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



68 10-16-17
0630 SAFETY BRIEF
0655 RADIO CHECKS, PDS UP, TRAFFIC SIGNS IN PLACE
0743 MINICAMS AND DRONES UP
0805 TEAM 1 DOWN RANGE RIDER, DION MANGOSH. BREAKING CONCRETE
0915 TEAM 1 CLEARED PDS.
0930 TEAM 2 DOWN RANGE, WUNSCHEL, COURTNEY PRATE. BREAKING CONCRETE.
1030 TEAM 2 CLEARED PDS.
1035 TEAM 3 DOWN RANGE, SPROUSE, PICARO MANGOSH. BREAKING CONCRETE.
1138 TEAM 3 CLEARED PDS
1142 STARTING MIDDAY CHALLENGE
1305 MIDDAY CHALLENGE COMPLETE
1310 TEAM 1 DOWN RANGE BREAKING CONCRETE. RIDER, DION ~~MANGOSH~~ PRATE
1410 TEAM 1 CLEARED PDS.
1415 TEAM 2 DOWN RANGE WUNSCHEL, COURTNEY MANGOSH.
1534 TEAM 2 CLEARED PDS.
STARTING END OF DAY CHECKS
1701 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 17 October 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 51° High 64°

Personnel on Site

PARSONS	ZES	ECBC	
	Mangosh, Ed	Askew, Tom	
Courtney, Kenneth	Prate, Warren	Hall, Steve	
Matter, Phil	Yorkshire, Bart	Tucker, Willie	
Nelms, Bobby			
Oien, Joshua		Smith, Ethan	
Pilato, Bryan		Landers, Brian	
Rider, Matthew		Foor, Adam	
Rockwell, Margaret		Bartosh, Ian	
Sprouse, Mark		Miller, Don	
Wunschel, Reina		Bagley, Robert	
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued demolition of the concrete footers. 35 drums were filled and transported to the federal property site for storage.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Pg 69

10-17-17

0630 SAFETY BRIEF.
0710 RADIO CHECKS
0702 PDS UP TRAFFIC SIGNS IN PLACE.
0730 MINI CAM'S & DRONES UP.
0914 TEAM 3 DOWN RANGE. SPROUSE, PICATO
WARREN.
0934 TEAM 3 CLEARED PDS.
0944 TEAM 1 DOWN RANGE. RIDER, OIEN
1050 TEAM 1 CLEARED PDS. RUBBLE DRUMS
1347 THRU 1362 FILLED AND TRANSPOTED
TO FED PROPERTY.
1055 TEAM 2 DOWN RANGE, WINSCHER, COMPTON
MCINTOSH.
1140 TEAM 2 CLEARED PDS.
1145 STARTING MIDDAY CHALLENGE.
1237 MIDDAY CHALLENGE COMPLETE.
1253 TEAM 3 DOWN RANGE. SPROUSE PICATO
1413 TEAM 3 CLEARED PDS. RUBBLE
DRUMS 1363 THRU 1382 LOADED FOR
FEDERAL PROPERTY.
1426 TEAM 1 DOWN RANGE RIDER, OIEN
1509 RUBBLE DRUMS 1373 THRU 1388 LOADED
FOR FEDERAL PROPERTY.
1535 TEAM 1 CLEARED PDS.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 18 October 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 53° High 67°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	Askew, Tom
Courtney, Kenneth	Prate, Warren	Hall, Steve
Matter, Phil	Yorkshire, Bart	Tucker, Willie
Nelms, Bobby		
Oien, Joshua		Smith, Ethan
Pilato, Bryan		Landers, Brian
Rider, Matthew		Foor, Adam
Rockwell, Margaret		Bartosh, Ian
Sprouse, Mark		Miller, Don
Wunschel, Reina		Bagley, Robert
Wunschel, Scott		

ACCUPERMIT	CHENC
Schmidt, James	
Williams, Angelo	**CENAB**
	Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued demolition of the concrete footers. No drums were filled. Two loads of cleared soil were transported to the sub-title D landfill.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Pg

71 10-18-17

0630 SAFETY BRIEF.

0700 RADIO CHECKS.

0735 MINICAMS UP.

0800 DAARMS RUNNING.

0840 TEAM 2 DOWN RANGE, WONSCHEL, COURTNEY, MANGOSH.

0940 ~~TEAM~~ 2 CLEARED PDS

0946 TEAM 3 DOWN RANGE, SPROUSE, PICATO PRATT.

1038 TEAM 3 CLEARED PDS

1047 TEAM 1 DOWN RANGE RIDER, OIEN MANGOSH

1137 TEAM 1 CLEARED PDS

1140 STARTING MID DAY CHALLENGE.

1158 MID DAY CHALLENGE COMPLETE.

1245 TEAM 2 DOWN RANGE, WONSCHEL, COURTNEY PRATT.

1350 TEAM 2 CLEARED PDS.

1355 TEAM 3 DOWN RANGE ~~FLOYD~~ SPROUSE, ~~LIEN~~ MANGOSH

1538 TEAM 3 CLEARED PDS

1541 STARTING END OF DAY CHECKS

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 19 October 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 54° High 65°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	Askew, Tom
Courtney, Kenneth	Prate, Warren	Hall, Steve
Matter, Phil	Yorkshire, Bart	Tucker, Willie
Nelms, Bobby		
Oien, Joshua		Smith, Ethan
Pilato, Bryan		Landers, Brian
Rider, Matthew		Foor, Adam
Rockwell, Margaret		Bartosh, Ian
Sprouse, Mark		Miller, Don
Wunschel, Reina		Druyer, Chris

ACCUPERMIT	CHENC
Schmidt, James	
Williams, Angelo	

CENAB
Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued demolition of the concrete footers. No drums were filled. Personnel performed end of week clean up and maintenance.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors
DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Pg

72 10-19-17

1430 SAFETY BRIEF

0700 RADIO CHECKS TRAFFIC SIGNS IN PLACE.

0735 MINICAMS UP

0800 DRAMS RUNNING

0815 TEAM 1 DOWN RANGE RIBER OJEN PRATE. BREAKING CONCRETE.

0925 TEAM 1 CLEARED PDS.

0942 TEAM 2 DOWN RANGE WONSCHER, CONNING, MANGOSH. CUTTING REBAR & BREAKING CONCRETE.

1118 TEAM 2 CLEARED PDS.

1123 STARTING MID DAY CHALLENGE

1216 MID DAY COMPLETE.

1221 TEAM 3 DOWN RANGE SPROUSE PRATE

134 TEAM 3 CLEARED PDS.

1350 STARTING END OF DAY CHECKS

1530 TWO WEEK LOOK AHEAD.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 23 October 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 61° High 74°

Personnel on Site

PARSONS	ZES	ECBC
	Mangosh, Ed	Copeland, Eric
Courtney, Kenneth	Prate, Warren	Heard, Irving
Matter, Phil	Yorkshire, Bart	Tucker, Robin
Nelms, Bobby		
Oien, Joshua		Smith, Ethan
Pilato, Bryan		Landers, Brian
Rider, Matthew		Foor, Adam
Rockwell, Margaret		Bartosh, Ian
Sprouse, Mark		Miller, Don
Wunschel, Reina		Druyer, Chris
Wunschel, Scott		

ACCUPERMIT	CHENC
Schmidt, James	
Williams, Angelo	**CENAB**
	Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued demolition of the concrete footers. No drums were filled.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg

73 10-23-17
1630 SAFETY BRIEF
0780 RADIO CHECKS, TRAFFIC SIGNS IN PLACE
0711 PDS UP.
0800 MINICAMS AND DRAMS UP.
1812 TEAM 3 DOWN RANGE, SPRUSE, DICATO MANGOSH. BREAKING CONCRETE.
0915 TEAM 3 CLEARED PDS.
0921 TEAM 1 DOWN RANGE, RIDER, OIGT, PRATE
1022 TEAM 1 CLEARED PDS.
1031 TEAM 2 DOWN RANGE, WONSCHEL, COMPANY. MANGOSH
1147 TEAM 2 CLEARED PDS
1148 STARTING MIDDAY CHALLENGE
1203 MIDDAY CHALLENGE COMPLETE
1225 TEAM 3 DOWN RANGE, SPRUSE, FICATO, PRATE
1330 TEAM 3 CLEARED PDS
1345 TEAM 1 DOWN RANGE, RIDER, OIGT, MANGOSH.
1446 TEAM 1 CLEARED PDS
1450 TEAM 2 DOWN RANGE, WONSCHEL, COMPANY, PRATE
1545 TEAM 2 CLEARED PDS STARTING END OF DAY CHECKS.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 24 October 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 55° High 72°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Copeland, Eric
Mantell, Dawn	Prate, Warren	Heard, Irving
Matter, Phil	Yorkshire, Bart	Tucker, Robin
Nelms, Bobby		
Oien, Joshua		Smith, Ethan
Pilato, Bryan		Landers, Brian
Rider, Matthew		Foor, Adam
Rockwell, Margaret		Bartosh, Ian
Sprouse, Mark		Miller, Don
Wunschel, Reina		Druyer, Chris
Wunschel, Scott		

ACCUPERMIT	CHENC
Schmidt, James	
Williams, Angelo	CENAB
	Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued demolition of the concrete footers. 45 drums were filled and transported to the federal property site for storage.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg

74

10-24-17

0630 SAFETY BRIEF

0700 RADIO CHECKS TRAFFIC SIGNS IN PLACE

0730 MINICAMS UP

0800 DOAMS UP

0815 TEAM 3 DOWN RANGE, SPROUSE, PICATO, MANTELL

0920 TEAM 3 CLEARED PDS

0935 TEAM 1 DOWN RANGE. RIDER, OIEN

1022 RUBBLE DRUMS 1389 THRU 1408 FILLED AND LOADED FOR FEDERAL PROPERTY

1039 TEAM 1 CLEARED PDS

1053 TEAM 2 DOWN RANGE WOOSLEY, COURTNEY

1137 TEAM 2 [redacted] CLEARED PDS

STARTING MIDDAY CHALLENGE

1154 MID DAY CHALLENGE COMPLETE.

1240 TEAM 3 DOWN RANGE, SPROUSE, MANTELL

1346 TEAM 3 CLEARED PDS

RUBBLE DRUMS 1409 THRU 1433 FILLED AND LOADED FOR FEDERAL PROPERTY.

1357 TEAM 1 DOWN RANGE RIDER, OIEN

1457 TEAM 1 CLEARED PDS

1500 TEAM 2 DOWN RANGE WOOSLEY, COURTNEY MANLOSH.

1540 TEAM 2 CLEARED PDS

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 25 October 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 54° High 75°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Copeland, Eric	
Mantell, Dawn	Prate, Warren	Heard, Irving	
Matter, Phil	Yorkshire, Bart	Tucker, Robin	
Nelms, Bobby			
Oien, Joshua		Smith, Ethan	
Pilato, Bryan		Landers, Brian	
Rider, Matthew		Foor, Adam	
Rockwell, Margaret		Bartosh, Ian	
Sprouse, Mark		Miller, Don	
Wunschel, Reina		Druyer, Chris	
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued demolition of the concrete footers. 25 drums were loaded and transported to the federal property site. Personnel also cut and drummed the rebar from inside the concrete, 2 drums were loaded.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



E

76 10-25-17
0630 SAFETY BRIEF
0706 RADIO CHECKS, TRAFFIC SIGNS IN PLACE.
0800 DAAMS PUMPS RUNNING.
0810 MINICAMS UP.
0845 TEAM 3 DOWN RANGE SPROUSE MANTELL PILATO DRUMMING RUBBLE.
0921 RUBBLE DRUMS 1434 THRU 1458 AND PPE DRUM 403 LOADED FOR FED. PROPERTY.
1031 TEAM 3 CLEARED PDS
1042 ~~TEAM~~ 1 DOWN RANGE RIDER BIDEN
1152 TEAM 1 CLEARED PDS MID DAY CHANGE
1256 MID DAY COMPLETE.
1310 TEAM 2 DOWN RANGE WUNSCHEL, COURTNEY MAGOSH.
1430 TEAM 2 CLEARED PDS
1440 TEAM 3 DOWN RANGE SPROUSE MANTELL PILATO.
1543 TEAM 3 CLEARED PDS. STARTING END OF DAY CHECKS.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 26 October 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild, Low 46° High 58°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Copeland, Eric	
Mantell, Dawn	Prate, Warren	Heard, Irving	
Matter, Phil	Yorkshire, Bart	Tucker, Robin	
Nelms, Bobby			
Oien, Joshua		Smith, Ethan	
Pilato, Bryan		Landers, Brian	
Rider, Matthew		Foor, Adam	
Rockwell, Margaret		Bartosh, Ian	
Sprouse, Mark		Miller, Don	
Wunschel, Reina		Druyer, Chris	
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued demolition of the concrete footers. No drums were filled. Personnel performed end of week clean up and maintenance.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Pg

77 10-26-17

0630 SAFETY BRIEF.

0700 RADIO CHECKS.

0740 MINICAMS UP

1800 DAAMS PUMPS RUNNING.

0810 TEAM 1 DOWN RANGE, RIDER, OIEN, MACKOSH.

0925 TEAM 1 CLEARED PDS.

0934 TEAM 2 DOWN RANGE WONSCHEL, MANTEL, PRATE.

1050 TEAM 2 CLEARED PDS

1105 TEAM 3 DOWN RANGE, SPROOSE, PICATO, MACKOSH.

1135 TEAM 3 CLEARED PDS.

1142 STARTING MIDDAY CHALLENGE.

1200 MIDDAY CHALLENGE COMPLETE.

1237 TEAM 1 DOWN RANGE RIDER, OIEN, PRATE.

1402 TEAM 1 CLEARED PDS.

1405 TEAM 2 DOWN RANGE, WONSCHEL, COURTNEY, MACKOSH.

1515 TEAM 2 CLEARED PDS. TWO WATER LOOK AHEAD.

1710 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 30 October 2017
Site Location: 4825 Glenbrook Road

Weather:
Cool, with high winds Low 42° High 53°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Copeland, Eric
Mantell, Dawn		Heard, Irving
Matter, Phil	Yorkshire, Bart	Avila, Michelle
Nelms, Bobby		
Oien, Joshua		Smith, Ethan
Pilato, Bryan		Landers, Brian
Rider, Matthew		Foor, Adam
Rockwell, Margaret		Bagley, Robert
Sprouse, Mark		Miller, Don
Wunschel, Reina		Druyer, Chris
Wunschel, Scott		
	ACCUPERMIT	**CHENC**
	Schmidt, James	
	Williams, Angelo	**CENAB**
		Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel began by pumping rain water from the sump, 8 water drums were filled. Teams continued demolition of the concrete footers. No rubble drums were filled.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Pg

78 10-30-17

0630 SAFETY BRIEF

0645 RADIO CHECKS.

0737 PDS IS UP.

0800 MINICAMS & DAAMS UP.

0824 TEAM 3 DOWN RANGE SPROUSE, MANTELL.

0916 AQ DRUMS 614 THRU 621 AND ESW DRUMS 1459 & 1460 FILLED AND LOADED FOR FEDERAL PROPERTY.

0925 ED MANGOSH DOWN RANGE.

1006 TEAM 3 CLEARED PDS.

1027 TEAM 1 DOWN RANGE, ~~WUNSCHE~~ RIDER, OLEN MANGOSH

1157 TEAM 1 CLEARED PDS

1159 STARTING MID DAY CHALLENGE

1210 MID DAY CHALLENGE COMPLETE

1300 TEAM 2 DOWN RANGE, WUNSCHER, COURONEY MANGOSH.

1430 TEAM 2 CLEARED PDS

1448 TEAM 3 DOWN RANGE, SPROUSE, MANTELL, MANGOSH

1540 TEAM 3 CLEARED PDS.

1545 STARTING END OF DAY CHECKS.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 31 October 2017
Site Location: 4825 Glenbrook Road

Weather:
Cool, Low 41° High 57°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Copeland, Eric
Mantell, Dawn	Prate, Warren	Heard, Irving
Marian, Jedidiah	Yorkshire, Bart	Avila, Michelle
Matter, Phil		
Nelms, Bobby		Smith, Ethan
Oien, Joshua		Landers, Brian
Pilato, Bryan		Foor, Adam
Rider, Matthew		Bartosh, Ian
Rockwell, Margaret		Miller, Don
Sprouse, Mark		Druyer, Chris
Wunschel, Reina		
Wunschel, Scott		
	ACCUPERMIT	**CHENC**
	Schmidt, James	
	Williams, Angelo	**CENAB**
		Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel cut and drummed the rebar from inside the concrete, one drum was filled. Teams then filled drums with concrete rubble, 48 drums were filled and transported to the federal property site for storage.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg

79 10-31-17

0630 SAFETY BRIEF.

0700 RADIO CHECKS. TRAFFIC SIGNS IN PLACE.

0730 PDS UP.

0755 MUNICIANS UP.

0815 DAMS PUMPS RUNNING.

0820 TEAM 1 DOWN RANGE, RIDER, DICK, COURTNEY CUTTING REBAR

1020 TEAM 1 CLEARED PDS.

1025 TEAM 2 DOWN RANGE WONSCHER, MARBAN

1145 TEAM 2 CLEARED PDS.

1150 STARTING M10 DRY CHALLENGE

1302 M10 DRY COMPLETE

1315 TEAM 3 DOWN RANGE SPARKS, PILATO MANFELL, MANGOSH.

1440 TEAM 3 CLEARED PDS.

1450 TEAM 1 DOWN RANGE RIDER, DICK, COURTNEY.

NOTE: RUBBLE DRUMS 446 THRU 1485, SCR DRUMS 526 & 521 PDE DRUM 444 LOADED FOR FED PROP.

1540 TEAM 1 CLEARED PDS.

1546 STARTING END OF DAY CHECKS.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 01 November 2017
Site Location: 4825 Glenbrook Road

Weather:
Cool, Low 55° High 64°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Copeland, Eric	
Mantell, Dawn	Prate, Warren	Heard, Irving	
Marian, Jedidiah	Yorkshire, Bart	Avila, Michelle	
Nelms, Bobby		Smith, Ethan	
Oien, Joshua		Landers, Brian	
Pilato, Bryan		Foor, Adam	
Rider, Matthew		Bartosh, Ian	
Rockwell, Margaret		Miller, Don	
Sprouse, Mark		Druyer, Chris	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel made repairs to the gravel driveway areas at the 4825 site. Teams then continued demolition of the concrete footers. No rubble drums were filled.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



8th 11-1-17
0630 SAFETY BRIEF.
0700 RADIO CHECKS, TRAFFIC SIGNS IN PLACE.
0740 MINICAMS UP.
0758 DADM 3 PUMPS RUNNING.
0880 RUBBLE DRUMS 1486 THRU 1508 LOADED AND TRANSPORTED TO FEDERAL PROPERTY.
0923 TEAM 3 DOWN RANGE SPROUSE PICATO MANGOSA MARIAN. BREAKING CONCRETE.
1016 PICATO CLEARED PDS.
1051 TEAM 3 CLEARED PDS.
1055 TEAM 1 DOWN RANGE RIDER, GIDY PRATT.
1142 TEAM 1 CLEARED PDS. STARTING MID DAY CHALLENGE.
1209 MID DAY CHALLENGE COMPLETE.
1300 TEAM 3 DOWN RANGE SPROUSE MANTEL MANGOSA. BREAKING CONCRETE
1420 TEAM 3 CLEARED PDS.
1436 TEAM 1 DOWN RANGE, RIDER, GIDY. FRATT BREAKING CONCRETE
1544 TEAM 1 CLEARED PDS.
1546 STARTING END OF DAY CHECKS.
1710 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 02 November 2017
Site Location: 4825 Glenbrook Road

Weather:
Cool, Low 55° High 72°

Personnel on Site

PARSONS	ZES	ECBC	
	Mangosh, Ed	Copeland, Eric	
Mantell, Dawn	Prate, Warren	Heard, Irving	
Marian, Jedidiah	Yorkshire, Bart	Avila, Michelle	
Nelms, Bobby		Smith, Ethan	
Oien, Joshua		Landers, Brian	
Pilato, Bryan		Foor, Adam	
Rider, Matthew		Bartosh, Ian	
Rockwell, Margaret		Miller, Don	
Sprouse, Mark		Druyer, Chris	
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued demolition of the concrete footers. No rubble drums were filled. Personnel performed end of week clean up and maintenance.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



R	
82	11-2-17
0630	SAFETY BRIEF
0700	RADIO CHECKS TRAFFIC SIGNS UP.
0745	MINICAMS UP
0800	DRAMS PUMPS RUNNING.
0835	TEAM 3 DOWN RANGE SPROUSE, MANTELL, MANGOSH
1005	TEAM 3 CLEARED PDS.
1015	TEAM 1 DOWN RANGE. RIDER, OLEN, PRATE.
1100	CONFERENCE CALL.
1115	CONFERENCE CALL COMPLETE.
1138	TEAM 1 CLEARED PDS. STARTING MIDDAY CHALLENGE.
1202	MIDDAY COMPLETE.
1230	TEAM 3 DOWN RANGE. SPROUSE, MANTELL, MANGOSH.
1345	TEAM 3 CLEARED PDS.
1400	TEAM 1 DOWN RANGE RIDER, OLEN PRATE
1500	TEAM 1 CLEARED PDS
1509	STARTING END OF DAY CHECKS. TWO WEEK LOOK AHEAD.
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 06 November 2017
Site Location: 4825 Glenbrook Road

Weather:
Cool, possible rain Low 54° High 68°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Alvano, Lou	
Mantell, Dawn	Prate, Warren	Heard, Irving	
Marian, Jedidiah	Yorkshire, Bart	Wagner, Darien	
Nelms, Bobby		Collins, Torrie	
Oien, Joshua		Fortier, John	
Pilato, Bryan		McClellan, Dale	
Rider, Matthew		McGill, Andre	
Rockwell, Margaret		Shavers, Dedrick	
Sprouse, Mark		Bagley, Robert	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel began by pumping rain water from the sump, 3 water drums were filled. Teams continued demolition of the concrete footers. No rubble drums were filled. Parsons electrical contractor made repairs to electrical outlets at the federal property site.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg
83 11-6-17
0630 SAFETY BRIEF
0700 RADIO CHECKS.
0740 MINICAMS OP.
0750 DAAMS PUMPS RUNNING.
0815 WATER DRUMS 622-624 FILLED.
0825 TEAM 2 DOWN RANGE, WONSCHEL, MARIAN, MANGOSH
BREAKING CONCRETE.
1000 TEAM 2 CLEARED PDS.
1010 TEAM 3 DOWN RANGE, SPRUSE, PILATO, PRATE
1137 TEAM 3 CLEARED PDS. STARTING MID
DAY CHALLENGE.
1203 MIDDAY CHALLENGE COMPLETE
1225 TEAM 1 DOWN RANGE RIDER, OIEN MANGOSH.
1405 TEAM 1 CLEARED PDS.
1406 TEAM 2 DOWN RANGE, WONSCHEL, MARIAN, PRATE
1539 TEAM 2 CLEARED PDS. STARTING
END OF DAY CHECKS
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 07 November 2017
Site Location: 4825 Glenbrook Road

Weather:
Cool, Rainy Low 41° High 49°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Alvano, Lou	
Mantell, Dawn	Prate, Warren	Heard, Irving	
Marian, Jedidiah	Yorkshire, Bart	Wagner, Darien	
Nelms, Bobby		Collins, Torrie	
		Fortier, John	
Pilato, Bryan		McClellan, Dale	
Rider, Matthew		McGill, Andre	
		Shavers, Dedrick	
Sprouse, Mark		Bagley, Robert	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James		
	Williams, Angelo	**CENAB**	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued demolition of the concrete footers. No rubble drums were filled.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg

84 11-7-17

0630 SAFETY BRIEF

0700 RADIO CHECKS TRAFFIC SIGNS IN PLACE

0740 MINICAMS UP

0755 DAAMS PUMPS RUNNING.

0827 WATER DRUMS 622 THRU 625 AND PPE DRUM 405 LOADED FOR TRANSPORT TO FEDERAL PROPERTY.

0832 TEAM 3 DOWN RANGE, SPROUSE, MANTELL, MANGOSH.

1000 TEAM 3 CLEARED PDS

1010 TEAM 1 DOWN RANGE RIDER, COURTNEY, PRATT.

1137 TEAM 1 CLEARED PDS STARTING MID DAY CHALLENGE

1155 MIDDAY CHALLENGE COMPLETE

1305 TEAM 3 DOWN RANGE, SPROUSE, MANTELL, MANGOSH.

1333 MINICAMS REPORTS WATER IN THE SAMPLE LINES W/ ~~7#~~ FOR "L", THE TEAMS MOVED TO THE PDS.

1342 MINICAMS REPORTS ALL CLEAR 2nd cycle

1400 CENAB OESS INFORMED / SEAN BUCKLEY INFORMED. STARTING MAINTENANCE ON MINICAMS.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 08 November 2017
Site Location: 4825 Glenbrook Road

Weather:
Cool, Rainy Low 40° High 47°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Alvano, Lou	
Mantell, Dawn	Prate, Warren	Heard, Irving	
Marian, Jedidiah	Yorkshire, Bart	Wagner, Darien	
Matter, Phil			
Nelms, Bobby		Collins, Torrie	
Oien, Joshua		Fortier, John	
Pilato, Bryan		McClellan, Dale	
Rider, Matthew		McGill, Andre	
		Shavers, Dedrick	
		Bagley, Robert	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James		
	Vargas, Brandon	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel began by pumping rain water from the sump, 5 water drums were filled. Teams continued demolition of the concrete footers and filled drums with rubble. 25 Drums of rubble were filled and transported to the federal property site.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg	
85	11-8-17
0630	SAFETY BRIEF
0700	RADIO CHECKS
0708	TRAFFIC SIGNS IN PLACE.
0714	PDS UP.
0740	MINICAMS UP
0755	DAHMS PUMPS RUNNING.
0830	WATER DRUMS 626 THRU 630 LOADED FOR FEDERAL PROPERTY.
0852	TEAM 2 DOWN RANGE WUNSCHEL, MARIAN, MANGOSH. BREAKING CONCRETE.
1022	TEAM 2 CLEARED PDS
1044	TEAM 1 DOWN RANGE RIDER, OLEN, PRATE
1140	TEAM 1 CLEARED PDS.
1141	RUBBLE DRUMS 1509 THRU 1533 FILLED AND LOADED FOR FEDERAL PROPERTY.
1142	STARTING MID DAY CHALLENGE.
1203	MID DAY CHALLENGE COMPLETE.
1230	TEAM 2 DOWN RANGE WUNSCHEL, MARIAN, MANGOSH.
1405	TEAM 2 CLEARED PDS
1410	TEAM 1 DOWN RANGE RIDER, OLEN, PRATE.
1540	TEAM 1 CLEARED PDS
1700	SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 09 November 2017
Site Location: 4825 Glenbrook Road

Weather:
Cool, Rainy Low 41° High 53°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Alvano, Lou	
Mantell, Dawn	Prate, Warren	Heard, Irving	
Marian, Jedidiah	Yorkshire, Bart	Wagner, Darien	
Matter, Phil			
Nelms, Bobby		Collins, Torrie	
Oien, Joshua		Fortier, John	
Pilato, Bryan		McClellan, Dale	
Rider, Matthew		McGill, Andre	
Rockwell, Margaret		Shavers, Dedrick	
		Bagley, Robert	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James		
	Pulsirisaroth, Andrew	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued demolition of the concrete footers, cutting up rebar and drumming rubble waste. Personnel performed end of week clean up and maintenance.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Ag

To 11-9-17

0650 SAFETY BRIEF

0700 RADIO CHECKS TRAFFIC SIGNS UP

0740 MINICAMS UP

0753 DAAMS PUMPS RUNNING

0844 EYE WASH CHECKED AND ~~THE HEATER~~ INSTALLED.

0857 TEAM 2 DOWN RANGE, WONSCHEL, MARIAN, MACKSH

1035 TEAM 2 CLEARED PDS. RUBBLE DRUMS

1534 THRU 1559 LOADED AND TRANSPORTED TO FEDERAL PROPERTY.

1047 TEAM 1 DOWN RANGE, RIDER, GIEN, MACKSH

1141 TEAM 1 CLEARED PDS. STARTING MID DAY CHALLENGE.

1242 MID DAY CHALLENGE COMPLETE.

1258 TEAM 2 DOWN RANGE, WONSCHEL, MARIAN, MANTEL.

1442 TEAM 2 CLEARED PDS.

1~~4~~5~~8~~ STARTING END OF DAY CHECKS.

1530 SAFETY MEETING/TRAINING W/SITE. PARSONS, ZIMMER, AND ECBC.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 13 November 2017
Site Location: 4825 Glenbrook Road

Weather:
Cool, possible rain Low 40° High 52°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Burell, Dianne	
Mantell, Dawn	Prate, Warren	Heard, Irving	
Marian, Jedidiah	Yorkshire, Bart	Wagner, Darien	
Matter, Phil			
Nelms, Bobby		Collins, Torrie	
Oien, Joshua		Fortier, John	
Pilato, Bryan		McClellan, Dale	
Rider, Matthew		McGill, Andre	
		Shavers, Dedrick	
Sprouse, Mark		Bagley, Robert	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel began by pumping rain water from the sump. Teams completed cutting rebar that came from the concrete footers. After the rebar cutting the teams began decontaminating equipment, the jackhammer, a set of stairs and one construction mat was deconned.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

PG	
LT	11-13-17
1630	SAFETY BRIEF.
0700	RADIO CHECKS, TRAFFIC SIGNS IN PLACE.
0740	MINICAMS UP.
0753	DAAMS PUMPS RUNNING.
0802	TEAM 3 DOWN RANGE SPONSE, MANTELL.
0932	TEAM 3 CLEARED POS.
0950	TEAM 1 DOWN RANGE, RIDER, OLEN.
1030	TEAM 1 CLEARED POS.
1128	STARTING MIDDAY CHALLENGE.
1200	MIDDAY CHALLENGE COMPLETE.
1220	TEAM 2 DOWN RANGE, WUNSCHEL, MARIAN COURTNEY, MANGISH. STARTING DECON OPS.
1245	MINICAMS CALL CK ALARM @ 4:2
1248	TEAM 2 MASKED AND EXITED EX. WAITING AT POS.
1248	2nd CYCLE CLEAR
1252	3rd CYCLE CLOSER
1255	MINICAMS WILL RECHALLENGE.
1305	RECHALLENGE COMPLETE.
1307	TEAM 2 DOWN RANGE WUNSCHEL, MARIAN COURTNEY, MANGOSH. DECON OPS.
1414	TEAM 2 CLEARED POS. SPONSE PILOT
1434	TEAM 3 DOWN RANGE. RIDER, ~~OLEN~~, MANGOSH. MANTELL.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 14 November 2017
Site Location: 4825 Glenbrook Road

Weather:
Cool, Low 36° High 54°

Personnel on Site

PARSONS	ZES	ECBC
Courtney, Kenneth	Mangosh, Ed	Burell, Dianne
Mantell, Dawn	Prate, Warren	Baker, Dawn
	Yorkshire, Bart	Wagner, Darien
Matter, Phil		
Nelms, Bobby		Collins, Torrie
Oien, Joshua		Landers, Brian
Pilato, Bryan		McClellan, Dale
Rider, Matthew		Myers, Royce
		Shavers, Dedrick
Sprouse, Mark		Smith, Ethan
Wunschel, Reina		
Wunschel, Scott		
	ACCUPERMIT	**CHENC**
	Schmidt, James	
	Williams, Angelo	**CENAB**
		Martin, JR

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued decontamination and break down of the sump. A second construction mat was cleaned then the team began cutting up plywood and padding material.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

(59) 11-14-2017 Tuesday 36/52 P. Cloudy

0630 Daily safety + operations briefings.
Jed Marion out sick
0700 Traffic + PDS is operational
0720 Radio checks complete.
0732 Mini CAMS up.
0820 Drums AQ 631, 632 ESW 1582 PPE 406 to Fed Prop.
0833 TM1 in EZ
0910 Call Zimmer for pressure washer. TM1 transitions from const. not to hand tools while waiting for p. washer.
1042 TM1 out / TM2 going in cutting up wood.
1145 TM2 out midday challenge
1201 MIDDAY CHALLENGE COMPLETE.
1231 TEAM 3 DOWN RANGE, SPROUSE, MANTELL, PALITO
1401 TEAM 3 CLEARED PDS.
1415 TEAM 1 DOWN RANGE, RIDER, OIEN,
1543 TEAM 1 CLEARED PDS.
1549 STARTING END OF DAY CHECKS.
1610 DAN NOBLE AND BRENDA BARBER ON SITE
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 15 November 2017
Site Location: 4825 Glenbrook Road

Weather:
Cool and breezy Low 43° High 51°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Burell, Dianne	
Mantell, Dawn	Prate, Warren	Baker, Dawn	
Marian, Jedidiah	Yorkshire, Bart	Wagner, Darien	
Matter, Phil			
Nelms, Bobby		Collins, Torrie	
Oien, Joshua		Landers, Brian	
Pilato, Bryan		McClellan, Dale	
Rider, Matthew		Myers, Royce	
		Shavers, Dedrick	
Sprouse, Mark		Smith, Ethan	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued cutting up plywood and padding material. Material was drummed and weighed then sent to the federal property site.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Pg

90 11-15-17

0630 SAFETY BRIEF.

0700 RADIO CHECKS TRAFFIC SIGNS IN PLACE.

0701 PDS THAT RONA WUNSCHEL HAS FALLEN ~~ON~~ THE SECOND SET OF STOPS

0711 SCOTT WUNSCHEL TAKING RONA WUNSCHEL TO THE SIBLEY HOSPITAL.

0731 SONN BUCKLEY MICHAEL COON AND ED GRUNWALD. NOTIFIED. CREW AWARE.

1015 RONA WUNSCHEL BACK FROM HOSPITAL & XRAYS WERE TAKEN AND HER SHOULDER RESET. SHE WILL BE HOME FOR THE DAY

1020 WALKED SITE.

1030 THE SITE IS RETURNING TO WORK.

1102 SCR DRUMS 524 THRU 526. PPE DRUM 407 AND WATER DRUMS 633 THRU 639 LOADED FOR TRANSPORT TO FEDERAL PROPERTY.

1109 TEAM 1 DOWN RANGE RIDER, OPEN, CLEARING.

1140 TEAM 1 CLEARED PDS

1142 STARTING MID DAY CHALLENGE.

1145 MID DAY CHALLENGE COMPLETE.

1237 TEAM 3 DOWN RANGE, SPROUSE, MANTEL, PICARD.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 16 November 2017
Site Location: 4825 Glenbrook Road

Weather:
Cool Low 40° High 57°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Burell, Dianne	
Mantell, Dawn	Prate, Warren	Baker, Dawn	
Marian, Jedidiah	Yorkshire, Bart	Wagner, Darien	
Matter, Phil			
Nelms, Bobby		Collins, Torrie	
Oien, Joshua		Landers, Brian	
Pilato, Bryan		McClellan, Dale	
Rider, Matthew		Myers, Royce	
		Shavers, Dedrick	
Sprouse, Mark		Smith, Ethan	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel completed washing equipment, cutting and drumming the wood and padding. The teams began decontaminating the sumps pond liner. Personnel performed end of week clean up and maintenance.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Sensitive

Pg	
92	11-16-17
0630	SAFETY BRIEF.
1653	RADIO CHECKS. TRAFFIC SIGNS UP.
0719	PDS UP
0820	SCIF DRUMS 527-533, ESN DRUM 1583
	LOADED FOR FEDERAL PROPERTY.
0900	DAPMS PUMPS RUNNING.
0740	MINICAMS UP
1008	TEAM 1 DOWN RANGE RIDER, OIEN, COURTNEY.
	NOTE: POSITION "A" MINICAMS UP @ 10:00
1051	TEAM 1 CLEARED PDS. STARTING
	MID DAY CHALLENGE.
1150	MIDDAY CHALLENGE COMPLETE.
1134	TEAM 3 DOWN RANGE SPREUSE, MATELL, MARION
1305	TEAM 3 CLEARED PDS.
1313	TEAM 3 DINN RANGE SPREUSE, OEN, COURTNEY.
1429	MINICAMS REPORT ALARM FOR CK 1.91.
	THE TEAM HAS MARKED UP MOVED TO THE PDS.
1434	2ND MINICAMS CYCLE WAS CLEAR.
1438	3rd CYCLE CLEAR.
1450	TEAM 3 CLEARED PDS.
1500	STARTING END OF WEEK CHECKS.
	TWO WEEK LOOK AHEAD.
1700	SECURED



SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 20 November 2017
Site Location: 4825 Glenbrook Road

Weather:
Cool Low 43° High 56°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Hall, Stephen	
Mantell, Dawn	Prate, Warren	Baker, Dawn	
Marian, Jedidiah		Wagner, Darien	
Matter, Phil			
Nelms, Bobby		Collins, Torrie	
Oien, Joshua		Landers, Brian	
Pilato, Bryan		McClellan, Dale	
Rider, Matthew		Myers, Royce	
Rockwell, Margaret		Shavers, Dedrick	
Sprouse, Mark		Smith, Ethan	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel completed decontaminating the sumps pond liner. Teams also broke down the sump walls and transported them to the federal property site.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Pg

93 11-20-17

0630 SAFETY BRIEF

0653 PDS UP, RADIO CHECKS.

0728 MINICAMS UP.

0755 DARMS PUMPS RUNNING.

0813 TEAM 1 DOWN RANGE RIDER OLEN

0931 SCR DRUM 534 THRU 546, WATER DRUMS 640 THRU 646 PPE DRUM 408, ESW DRUMS 1584 THRU 1585 LOAD FOR FEDERAL PROPERTY.

1134 TEAM 1 CLEARED PDS. STARTING MIDDAY CHALLENGE.

1146 MIDDAY CHALLENGE COMPLETE.

1235 TEAM 3 DOWN RANGE SPROUSE MANTEL

1343 TEAM 3 CLEARED PDS. END OF DAY CHECK

1415 SCR DRUM 547, WATER DRUMS 647 THRU 653, ESW DRUMS 1586 & 1587 LOAD FOR FEDERAL PROPERTY.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 21 November 2017
Site Location: 4825 Glenbrook Road

Weather:
Cool Low 45° High 59°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Hall, Stephen	
Mantell, Dawn	Prate, Warren	Baker, Dawn	
Marian, Jedidiah		Wagner, Darien	
Matter, Phil			
Nelms, Bobby			
Oien, Joshua		Landers, Brian	
Pilato, Bryan		McClellan, Dale	
Rider, Matthew		Myers, Royce	
Rockwell, Margaret		Shavers, Dedrick	
Sprouse, Mark		Smith, Ethan	
Wunschel, Reina			
Wunschel, Scott			
	ACCUPERMIT	**CHENC**	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel finished transporting sump parts, tools, and miscellaneous equipment to the federal property site for storage. Teams secured gear for the long holiday weekend and performed end of week maintenance.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	


Pg
94 11-24-17
0630 SAFETY BRIEF
0700 RADIO CHECKS
0800 STARTING SITE PREPS FOR THANKSGIVING.
1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 27 November 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild with cold front moving in Low 37° High 57°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Hall, Stephen	
Mantell, Dawn	Prate, Warren	Baker, Dawn	
		Wagner, Darien	
Matter, Phil			
Nelms, Bobby			
Oien, Joshua		Landers, Brian	
		McClellan, Dale	
Rider, Matthew		Myers, Royce	
Rockwell, Margaret		Shavers, Dedrick	
Sprouse, Mark		Smith, Ethan	
Wunschel, Reina			
Wunschel, Scott			
Peterlin, Joe	**ACCUPERMIT**	**CHENC**	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

ECBC personnel began setting up the PDS and other equipment in the driveway of the 4835 property. Parsons personnel mover the MINICAMS shed, installed stairs and made improvements to the walkway to the back yard of 4835.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



Pg
95 11-27-17
0630 SAFETY BRIEF
0700 TRAFFIC SIGN IN PLACE, RADIO CHECKS.
0800 THE SITE IS SETTING UP FOR THE SAMPLING AT 4835.
1700 SECURED.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 28 November 2017
Site Location: 4825 Glenbrook Road

Weather:
Mild Low 41° High 61°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Hall, Stephen	
Mantell, Dawn	Prate, Warren	Baker, Dawn	
	Yorkshire, Bart	Wagner, Darien	
Matter, Phil			
Nelms, Bobby			
Oien, Joshua		Landers, Brian	
		McClellan, Dale	
Rider, Matthew		Myers, Royce	
Rockwell, Margaret		Shavers, Dedrick	
Sprouse, Mark		Smith, Ethan	
Wunschel, Reina			
Wunschel, Scott			
Peterlin, Joe	**ACCUPERMIT**	**CHENC**	
		Boles, Judson	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued setting up the site for the concrete coring and sampling operation at the 4835 property. Personnel received site specific training at the federal property site. Parsons personnel began mask fitting its teams.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Pg

96 11-28-17

0630 SAFETY BRIEF.

0700 RADIO CHECKS

1930 SITE SPECIFIC TRAINING WITH PARSONS ZIMMER ECBC & TRAFFIC CONTROL.

1300 CENAB JR. MARTIN OP SEC BRIEF WITH PARSONS, ZIMMER, ECBC & TRAFFIC CONTROL.

1330 ALL TRAINING COMPLETE.

1400 FITTESTING SITE FOR INTERSPIRO'S" FULL FACE MPSK.

1400 MARTIN, PETERLIN DIOT RIDER AND SPOUSE COMPLETED & PASSED INTERSPIRO FIT TEST.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 29 November 2017
Site Location: 4825 Glenbrook Road

Weather:
cool Low 37° High 63°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Hall, Stephen	
Mantell, Dawn	Prate, Warren	Duff, Todd	
	Yorkshire, Bart	DeLaPaz, Hector	
Matter, Phil			
Nelms, Bobby		McGill, Andre	
Oien, Joshua	**LIFE STAR**	Landers, Brian	
		Foor, Adam	
Rider, Matthew	Alfaro, Walter	Bartosh, Ian	
Rockwell, Margaret	Vines, Doreen	Wainwright, Lee	
Sprouse, Mark		Smith, Ethan	
Wunschel, Reina		Miller, Dorn	
Wunschel, Scott		Henderson, Amos	
Peterlin, Joe	**ACCUPERMIT**	**CHENC**	
		Boles, Judson	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel continued setting up the site for the concrete coring and sampling operation at the 4835 property. Parsons personnel continued mask fitting teams and conducted training on the Geo Probe and the concrete coring machine.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Sensitive


PG

96 11-29-17

0630 SAFETY BRIEF. MEDICAL ON SITE.
"LIFE SHAD"

0700 RADIO CHECKS. TRAFFIC SIGNS IN PLACE.

0900 THE TEAMS ARE TRAINING W/GEOPROBE.
CONTINUE TO PREPARE FOR SAMPLING AT 4835 GB

1230 FIT TEST COURTNEY ON INTERSPIRO.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 30 November 2017
Site Location: 4825 Glenbrook Road

Weather:
cool Low 43° High 57°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Hall, Stephen	
Mantell, Dawn	Prate, Warren	Duff, Todd	
	Yorkshire, Bart	DeLaPaz, Hector	
Matter, Phil			
Nelms, Bobby		McGill, Andre	
Oien, Joshua	**LIFE STAR**	Landers, Brian	
		Foor, Adam	
Rider, Matthew	Alfaro, Walter	Bartosh, Ian	
Rockwell, Margaret	Vines, Doreen	Wainwright, Lee	
Sprouse, Mark		Smith, Ethan	
Wunschel, Reina		Miller, Dorn	
Wunschel, Scott		Henderson, Amos	
Peterlin, Joe	**ACCUPERMIT**	**CHENC**	
		Boles, Judson	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel completed set up of the site for the concrete coring and sampling operation at the 4835 property. Personnel conducted training on level B PPE and equipment. Parsons began prepping concrete coring locations.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

PG

97 11-30-17

0630 SAFETY BRIEF

0700 RADIO CHECKS, TRAFFIC SIGNS IN PLACE.

0730 THE TEAMS ARE RECEIVING "MUSTARD EXPOSURE TRAINING" PROVIDE BY LIFESTAR.

1020 THE PERSONS PERSONNEL COMPLETED MUSTARD TRAINING.

1330 STARTING PDS TRAINING/DRESS OUT WITH TEAM 3 AND MR. PETERSEN

1480 TRAINING COMPLETED FOR THE DAY. "LEVEL"B" DRESS OUT/SWITCHING FROM TENOR BOTTLES TO LINE AIR AND BACK. RETRIEVED EMERGENCY BOTTLE DETINATION.

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 04 December 2017
Site Location: 4825 Glenbrook Road

Weather:
Cold Low 32° High 56°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Nichols, Douglas	
Mantell, Dawn	Prate, Warren	Duff, Todd	
	Yorkshire, Bart	DeLaPaz, Hector	
Matter, Phil			
Nelms, Bobby		McGill, Andre	
Oien, Joshua	**LIFE STAR**	Landers, Brian	
Pilato, Bryan		Foor, Adam	
Rider, Matthew	Alfaro, Walter	Bartosh, Ian	
Rockwell, Margaret	Murdock, Mark	Caldwell, Jeff	
Sprouse, Mark		Smith, Ethan	
Wunschel, Reina		Miller, Dorn	
Wunschel, Scott			
Peterlin, Joe	**ACCUPERMIT**	**CHENC**	
		Boles, Judson	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Site personnel completed set up of equipment at the 4835 house, some of the set up could not be completed on Thursday due to AU property in the way. After set up site personnel practiced man down drills. In the afternoon the intrusive team began coring the concrete at location SB-12, they drilled approximately 4.5 inches.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	



R

98 12-04-17

0630 SAFETY BRIEF.

0700 RADIO CHECKS TRAFFIC SIGNS IN PLACE.

0800 THE SITE IS PREPING FOR SAMPLING OPERATIONS.

1115 PILATO FIT TEST FOR INTERSPIRO.

1350 PDS COMPLETED MAN DOWN DRILL"

1326 MINICAMS ARE UP.

1400 THE CONTRACT FOR MEDICAL SUPPORT W/G W HOSPITAL HAS BEEN SIGNED.

1350 DAMMS PUMPS RUNNING.

1430 TEAM 1 AT PDS

1431 TEAM 1 RIDER OIEN & COURONEY. DOWN RANGE "LEVEL B" "TRAINING!!

1434 MAN DOWN DRILLS!! TRAINING!!

1508 TEAM 1 DOWN RANGE "LEVEL" B. RIDER OIEN, COURONEY.

1510 STARTING WORK AT BH # 12

1554 TEAM 1 CLEARED PDS.

1600 THE TEAM CLEARED MEDICAL

1615 STARTING END OF DAY CHECKS

1700 SECURED

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 05 December 2017
Site Location: 4825 Glenbrook Road

Weather:
Cool Low 41° High 59°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Nichols, Douglas	
Mantell, Dawn	Prate, Warren	Duff, Todd	
	Yorkshire, Bart	DeLaPaz, Hector	
Matter, Phil			
Nelms, Bobby		McGill, Andre	
Oien, Joshua	**LIFE STAR**	Landers, Brian	
Pilato, Bryan		Foor, Adam	
Rider, Matthew	Alfaro, Walter	Bartosh, Ian	
Rockwell, Margaret	Ramsey, Charles	Caldwell, Jeff	
Sprouse, Mark		Smith, Ethan	
Wunschel, Reina		Miller, Dorn	
Wunschel, Scott			
Peterlin, Joe	**ACCUPERMIT**	**CHENC**	
		Boles, Judson	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

ECBC personnel collected a DAAMS pumps sample of the sump in the crawl space at the 4835 site. The Parsons down range teams completed the concrete coring of SB-12 and SB-13 then used the Geoprobe to collect soil samples at SB-12.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**12/5/2017**
Weather:	**Cloudy 19-59F, wind 0-7 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Concrete coring and geoprobe sampling of borehole 12. Collected one sample**
Summary:	**Concrete coring and geoprobe sampling of borehole 12. Collected one sample and submitted for headspace.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**12/5/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**



Pg

99 12-5-17

0630 SAFETY BRIEF.

0700 RADIO CHECKS, TRAFFIC SIGN IN PLACE

0705 PDS UP.

0710 TEAM 3 DOWN RANGE W/ DAAMS PUMP TO SAMPLE SUMP.

0715 DAAMS PUMP FOR SUMP AIR SAMPLE RUNNING.

0756 MINICAMS UP.

0815 THE SUMP DAAMS PUMP RECOVERED.

0817 DAAMS PUMPS RUNNING.

0834 TEAM 1 DOWN RANGE MOD "D" FOR SETUP

0858 TEAM 1 CLEARED PDS.

0858 TEAM 3 DOWN RANGE "LEVEL B" SPROUSE MANTELL, PILATO.

0913 BH #12 AT VAPOR BARRIER PULLING CONCRETE CORE. ALL MONITORS READ ZERO.

0946 MINICAMS REPORT ALL CLEAR.

1007 TEAM 3 CLEARED PDS.

1033 TEAM 1 DOWN RANGE "LEVEL B" RIDER OLEN, COURTNEY.

1107 TEAM 1 CLEARED PDS. THE DRILL IS BROKEN AND HAS BEEN PROCESSED THRU PDS.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 06 December 2017
Site Location: 4825 Glenbrook Road

Weather:
Cool Low 36° High 50°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Nichols, Douglas	
Mantell, Dawn	Prate, Warren	Duff, Todd	
	Yorkshire, Bart	DeLaPaz, Hector	
Matter, Phil			
Nelms, Bobby		McGill, Andre	
Oien, Joshua	**LIFE STAR**	Landers, Brian	
Pilato, Bryan		Foor, Adam	
Rider, Matthew	Alfaro, Walter	Bartosh, Ian	
Rockwell, Margaret	Ramsey, Charles	Caldwell, Jeff	
Sprouse, Mark		Smith, Ethan	
Wunschel, Reina		Miller, Dorn	
Wunschel, Scott			
Peterlin, Joe	**ACCUPERMIT**	**CHENC**	
		Boles, Judson	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons down range team used the Geoprobe to collect soil samples at SB-13 then backfilled SB-12 and SB-13 with bentonite. A second team performed concrete coring at SB-14 and SB-15. The Geoprobe was used to collect soil samples from SB-14 and SB-15 then SB-15 was backfilled with bentonite, SB-14 will not be backfilled for possible future soil gas monitoring.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report	
Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**12/6/2017**
Weather:	**Partly Cloudy 34-48°F, wind 0-13 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Crews continued concrete coring of boreholes 13, 14, and 15 in the kitchen section of the 4835 property. Collected 3 samples (see COC for IDs) from boreholes (13, 14, 15) and submitted for headspace.**
Summary:	**Crews continued concrete coring of boreholes 13, 14, and 15 in the kitchen section of the 4835 property. Collected 3 samples (see COC for IDs) from boreholes (13, 14, 15) and submitted for headspace.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**12/6/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

PG

1 12-16-17
0630 SAFETY BRIEF
0715 RADIO CHECKS.
0746 MINICAMS UP
0800 DRAMS PUMPS RUNNING.
0812 PDS IS UP.
0837 TEAM 1 DOWN RANGE "LEVEL B"
RIDER, OLEN, Peterlin.
0845 BH #13 w/GEO PROBE
0900 TEAM 1 REPORTS GEO PROBE @ 2ft
WITH REFUSAL!
0910 COLLECTING COMPOSITE BH 13, 0-2'.
0914 JOE Peterlin CLEARED PDS, BRUCE COURTNEY
DOWN RANGE "LEVEL B"
0931 BH #13 HAS BEEN FILLED w/BENTONITE.
0935 BH #12 HAS BEEN FILLED w/BENTONITE.
0948 TEAM 1 HAS CLEARED PDS.
1000 TEAM 3 DOWN RANGE "LEVEL B" SPROUSE, MANTEL.
1014 BH 14 STARTING BORING. Note: BH 14 WAS
MOVE 5 INCHES TOWARDS THE PATIO. THE BORING
MACHINE COULD NOT MAKE A SUCTION.
1030 BH #14 @ GRAVEL.
1051 ALL MONITORS READ ZERO.
1052 STARTING CORING AT BH #15
1117 BH #15 AT GRAVEL.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 07 December 2017
Site Location: 4825 Glenbrook Road

Weather:
Cool Low 38° High 53°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Nichols, Douglas	
Mantell, Dawn	Prate, Warren	Duff, Todd	
Marian, Jedidiah	Yorkshire, Bart	DeLaPaz, Hector	
Matter, Phil			
Nelms, Bobby		McGill, Andre	
Oien, Joshua	**LIFE STAR**	Landers, Brian	
Pilato, Bryan		Foor, Adam	
Rider, Matthew	Alfaro, Walter	Bartosh, Ian	
Rockwell, Margaret	Brick, Thomas	Caldwell, Jeff	
Sprouse, Mark		Smith, Ethan	
Wunschel, Reina		Miller, Dorn	
Wunschel, Scott		Fortier, John	
Peterlin, Joe	**ACCUPERMIT**	**CHENC**	
		Boles, Judson	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons personnel collected a water sample from the sump in the crawl space at the 4835 site. The intrusive team completed the concrete coring of SB-03 and SB-04 then the Geoprobe was used to collect soil samples from SB-03. Site personnel completed end of week clean up and maintenance.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**12/7/2017**
Weather:	**Partly Cloudy 31-49°F, wind 0-7 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Parsons team collected one sample (43835GR-SUMP-120717-01) from the sump and submitted to ECBC for analysis. Submitted 4835GR-BH12-120517-(1-3) to ECBC for low level analysis. Parsons team bored through concrete at Boreholes 3 and 4. Team collected 3 samples using the Geoprobe for borehole 3 and submitted for headspace.**
Summary:	**Parsons team collected one sample (43835GR-SUMP-120717-01) from the sump and submitted to ECBC for analysis. Submitted 4835GR-BH12-120517-(1-3) to ECBC for low level analysis. Parsons team bored through concrete at Boreholes 3 and 4. Team collected 3 samples using the Geoprobe for borehole 3 (see headspace COC for IDs) and submitted for headspace.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**12/7/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

R1	
3	12-7-17
0650	SAFETY BRIEF.
0700	RADIO CHECKS. TRAFFIC SIGNS IN PLACE.
0752	STARTING WATER SAMPLE COLLECTION "4935G SUMP". PILATO, PETERLIN
0748	MINICAMS UP
0800	PDS UP. MARIAN COMPLETED FIT TEST INTERVIEW
0815	THE WATER SAMPLE HAS BEEN COLLECTED AND THE SUMP PUMPED DRY.
0823	MARIAN TRAINING W/ PDS. TRANSFER FROM LINE AIR TO BOTTLES / DECON PROCESS.
0826	PILATO, PETERLIN CLEARED PDS. TEAM 3 DOWN RANGE FOR SETUP SPRONSE MANTELL.
0904	SETUP COMPLETE. TEAM 3 CLEARED PDS.
0940	TEAM 3 DOWN RANGE, "LEVER" SPRONSE MANTELL, PILATO.
0942	THE TEAM STARTED BORING IN BH "3
0950	REMOVED THE CONCRETE CORE & VAPOR BARRIER.
1007	MINICAMS ALL CLEAR.
1020	BORING ON BH "4
1040	CONCRETE CORE REMOVED, VAPOR BARRIER & GRAVEL REMOVED.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 11 December 2017
Site Location: 4825 Glenbrook Road

Weather:
Cold Low 34° High 42°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Wagner, Darian	
Mantell, Dawn	Prate, Warren	Duff, Todd	
Marian, Jedidiah	Yorkshire, Bart	Tallent, Michael	
Matter, Phil			
Nelms, Bobby			
Oien, Joshua	**LIFE STAR**	Landers, Brian	
Pilato, Bryan		Foor, Adam	
Rider, Matthew	Murdock, Mark	Bartosh, Ian	
Rockwell, Margaret	Vines, Doreen	Wainwright, Leroy	
Sprouse, Mark		Smith, Ethan	
Wunschel, Reina		Miller, Dorn	
Wunschel, Scott		Fortier, John	
Peterlin, Joe	**ACCUPERMIT**	**CHENC**	
		Boles, Judson	
	Schmidt, James		
	Williams, Angelo	**CENAB**	
		Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

There was a delay getting started as the PDS could not get up to operational temp, the problem has been resolved. Parsons down range team used the Geoprobe to collect soil samples at SB-04 then backfilled SB-03 with bentonite. SB-04 will not be backfilled for possible future soil gas monitoring. The down range team completed the concrete coring of SB-05 and SB-06.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**12/11/2017**
Weather:	**Sunny 36-46°F, wind 0-6 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Parsons team collected 3 samples from Borehole 4 and submitted for headspace (See Headspace COC for IDs). Sent one sample to APPL for analysis (4835GR-BH12-120517-(1-3)). Cored concrete in boreholes 5 and 6.**
Summary:	**Parsons team collected 3 samples from Borehole 4 and submitted for headspace (See Headspace COC for IDs). Sent one sample to APPL for analysis (4835GR-BH12-120517-(1-3)). Cored concrete in boreholes 5 and 6.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**12/11/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Pg	
5	12-11-17
0630	SAFETY BRIEF
0700	TRAFFIC SIGNS IN PLACE, RADIO CHECKS.
0747	MINICAMS UP
0800	DAAMS PUMPS RUNNING.
1036	TEAM 1 DOWN RANGE LEVEL B RIDGE DION PETERSEN.
1141	STARTING TO ADVANCE GEO PROBE IN BH# 4.
1139	BH# 4 REFUSAL @ 6.5'
1142	PETERSEN CLEARED PDS.
1152	ALL COMPOSITE SAMPLES FOR BH# 4 COLLECTED.
1154	TEAM 1 CLEARED PDS.
1200	STARTING M10 DAY CHALLENGE
1217	M10 DAY CHALLENGE COMPLETE.
1300	TEAM 3 DOWN RANGE, SPONASE, MANTEL, MARIAN. "LEVEL B".
1308	CORING BH# 5
1346	CONCRETE 11in. THICK MINICAMS ALL CLEAR.
1350	BH# 5 SEALED w/ BENTONITE. STARTING CORING IN BH# 6.
1423	CONCRETE 10in. THICK
1439	BH# 6 SEALED
1447	TEAM 3 CLEARED PDS.

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 12 December 2017
Site Location: 4825 Glenbrook Road

Weather:
Cold Low 34° High 42°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Wagner, Darian	
	Prate, Warren	Duff, Todd	
Marian, Jedidiah	Yorkshire, Bart	Tallent, Michael	
Matter, Phil			
Nelms, Bobby		Fortier, John	
Oien, Joshua	**LIFE STAR**	Landers, Brian	
Pilato, Bryan		Foor, Adam	
Rider, Matthew	Haupt, Calvin	Dryor, Chris	
Rockwell, Margaret	Vines, Doreen	Wainwright, Leroy	
Sprouse, Mark		Smith, Ethan	
Wunschel, Reina		Miller, Don	
Wunschel, Scott			
Peterlin, Joe	**ACCUPERMIT**	**CHENC**	
		Boles, Judson	
	Schmidt, James	**CENAB**	
	Williams, Angelo	Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons down range team used the Geoprobe to collect soil samples at SB-05 and SB-06 then backfilled SB-05 and SB-06 with bentonite. A second team performed concrete coring at SB-07 and SB-08.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors	Contractors
	DAVEY ( )
	ACCUPERMIT (2)
	ACI (0)
	CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report

Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**12/12/2017**
Weather:	**Sunny 36-46°F, wind 0-6 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Sent 6 samples to ECBC for low level analysis. Parsons team collected 3 samples at Borehole 5 and 2 samples at Borehole 6 and submitted samples for headspace. Parsons teams cored concrete at boreholes 7 and 8.**
Summary:	**Sent 6 samples to ECBC for low level analysis (see Low Level COC for IDs). Parsons team collected 3 samples at Borehole 5 and 2 samples at Borehole 6 and submitted samples for headspace (See headspace COC for IDs). Parsons teams cored concrete at boreholes 7 and 8.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**12/12/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Pg	
7	12-12-17
0630	SAFETY BRIEF.
0700	RADIO CHECKS
0758	DARMS PUMPS RUNNING.
0755	MINICAMS UP
0800	PDS UP.
0853	TEAM 1 DOWN RANGE, RIDER OVEN PETERLIN.
0857	ADVANCING GEOPROBE IN BH #5
1015	BH #5 1-3', 3-5', 5-6.5' COMPLETED/REFUSAL
1023	BH #5 BACKFILLER w/ BENTONITE AND COVERED.
1024	ADVANCING GEOPROBE IN BH #6
1052	COMPLETED 0-2', 2-4' REFUSAL
1100	PETERLIN CLEARED PDS
1123	TEAM 1 CLEARED PDS.
1136	STARTING MID DAY CHALLENGE.
1147	MID DAY COMPLETE
1250	TEAM 3 DOWN RANGE, SPRUSE, MARIAN PILATO. LEVEL B
1256	CORING BH #7
1335	CORING COMPLETE, MINICAMS CLEAR. CONCRETE APPROX 5 IN. THICK.
1344	BH #7 COVERED w/PLASTIC, MOVING TO BH #8
1403	AT VAPOR BARRIER ON BH #8

SPRING VALLEY, WASHINGTON DC

Contract No: W912DY-09-D-0062
Delivery Order: TO 0006
Date: 13 December 2017
Site Location: 4825 Glenbrook Road

Weather:
Very Cold Low 23° High 35°

Personnel on Site

PARSONS	ZES	ECBC	
Courtney, Kenneth	Mangosh, Ed	Wagner, Darian	
Mantell, Dawn	Prate, Warren	Duff, Todd	
Marian, Jedidiah	Yorkshire, Bart	Tallent, Michael	
Matter, Phil			
Nelms, Bobby		Fortier, John	
Oien, Joshua	**LIFE STAR**	Landers, Brian	
Pilato, Bryan		Foor, Adam	
Rider, Matthew	Murdock, Mark	Dryor, Chris	
Rockwell, Margaret	Vines, Doreen	Wainwright, Leroy	
Sprouse, Mark		Smith, Ethan	
Wunschel, Reina		Miller, Don	
Wunschel, Scott			
Peterlin, Joe	**ACCUPERMIT**	**CHENC**	
		Boles, Judson	
	Schmidt, James	**CENAB**	
	Williams, Angelo	Martin, JR	

ACTIVITIES CONDUCTED (include site mobilization/demobilization, brush/tree clearing, geophysical survey, intrusive excavation, contaminated soil excavation, sampling, and restoration activities)

Safety Briefing: 6:30

Parsons down range team used the Geoprobe to collect soil samples at SB-07 and SB-08. Possible AUES glass found in SB-07 at approximately 4.5 ft from the top of concrete. A second team performed concrete coring at SB-09 and SB-10.

End of Day: 1700

SAMPLES COLLECTED: See DQCR for sample information

Closed cavity items found None

New Equipment on Site: N/A

Visitors

Contractors

DAVEY ( )
ACCUPERMIT (2)
ACI (0)
CPJ (0)

Problems encountered/resolutions:

Instructions given by government personnel:

Activities anticipated for tomorrow:

Attachments (include as appropriate)		
	Y/N	
Geophysical Summary	Y/N	
Excavation Summary	Y/N	
Air Monitoring Summary	Y/N	*To be included if investigation is using CSS protocols*
Dig Sheet	Y/N	*To be included at least once every week during intrusive investigation*
Sample Chains-of-Custody (COCS)	Y/N	
Contingency Plan Initiation Summary	Y/N	
Health and Safety Report	Y/N	*To be included weekly during field activities*
Property Management Summary	Y/N	*Include complete property inventory once every month*
Photographs	Y/N	

Daily Contractor Quality Control Report	
Contract Number:	**W912DY-09-D-0062**
Delivery Order Number:	**0006**
Project Name:	**4825 Glenbrook Rd. Remedial Action, Spring Valley FUDS.**
Project Number:	**748272.03000**
Site Location:	**Spring Valley, Washington, DC.**
Date:	**12/13/2017**
Weather:	**Sunny 30-35°F, wind 0-19 mph**
Field Instrument:	**Arsine - (1) Down Range, HCL - (1) Down Range, HCN - (1) Down Range, (1) PID - Down Range, MiniCAMS, DAAMs**
Measurements:	**All Non Detect.**
Calibrations:	**Arsine and HCL – Fresh air zero calibration, HCN – Fresh Air and 10ppm HCN/Nitrogen Balance, PID - 100ppm isobutylene and fresh air.**
Activities Conducted:	**Parsons team collected samples at boreholes 7 and 8 using the Geoprobe and submitted for headspace. Team collected glass from Borehole 7 and submitted for headspace. Sent 6 samples to APPL. Teams cored concrete in boreholes 9 and 10.**
Summary:	**Parsons team collected samples at boreholes 7 (3 samples) and 8 (2 samples) using the Geoprobe and submitted for headspace (see Soil COC for IDs). Team collected glass from Borehole 7 and submitted for headspace (See Glass COC for IDs). Sent 6 samples to APPL (See COC for IDs). Teams cored concrete in boreholes 9 and 10.**
Items Found:	**None**
Contingency Plan Initiated:	**No**
Air Monitoring:	**MiniCAMMS , DAAMS**
IDW Generated:	**PPE and Decon Water**
Waste Disposal:	**None**
Departures from approved SSWP:	**None**
Problems encountered/resolutions:	**None**
Instructions given by government personnel:	**None**
Attachments:	Sample Logs Daily QC Logs UXO Safety Log (Weekly) **COC**
Signed by:	
Name (print):	**Margaret Rockwell**
Date:	**12/13/2017**
Phone Number:	**571-721-9804**
Copy sent to:	**Scott Wunschel**

Pg

9 12-13-17

0630 SAFETY BRIEF.

0700 RADIO CHECKS.

0745 DRAMS PUMPS RUNNING

0754 PDS UP

0826 MINICAMS UP @ 07:54

0900 TEAM 1 DOWN RANGE LEVEL B"
RIDER, OVER PETERSON.

0905 ADVANCING GEOPROBE IN BH#7

0914 GEOPROBE 0-2' COLLECTING SAMPLE.

0929 GEOPROBE ADVANCED 2-4' w/ REFUSAL.

0939 THE REPORT AVE'S GLASS w/ SAMPLE

0959 TWO CLEAR CYCLES w/ MINICAMS,
ALL HAND HELD MONITORS CLEAR.
THE GLASS HAS BEEN SEPERATED FOR
HEAD SPACING.

1029 BH#7 4-6' SAMPLE COMPLETED, REFUSAL
STARTING BH#8 ADVANCING GEOPROBE.

1033 BH#8 @ 0-2' COLLECTING SAMPLE.

1051 BH#8 @ 2-3.5' REFUSAL, SAMPLE BEING
COLLECTED.

1128 AVE'S GLASS WAS DOUBLE BAGGED, BH 7/8
COVERED w/ PLASTIC. EQUIPMENT WAS
DECONED, THE TEAM HAS CLEARED
PDS.